

CULTURAL RESOURCE SURVEY PROPERTY IDENTIFICATION FORM

CRS#	S-11519
SPO Map	18-19-12
-	Lewes and
Hundred	Rehoboth
Quad	Lewes
Other	3-34-5-72

	- Breight				Hundred	Reh	oboth
					Quad	_Lew	
					Other	3-34	l-5-72
1.	HISTORIC NAME/FUNCTION:	Nassau Orch	<u>ards Marl</u>	et	<u> </u>		
2.	ADDRESS/LOCATION: 871 Na	assau Road/N	IE side of	<u>U.S. Route 1 (C</u>	oastal High	way)	
3.	TOWN/NEAREST TOWN: Lewe	es				v	icinity? 🛚 🖾
4 .	MAIN TYPE OF RESOURCE:	building landscape		structure [site		object 🗌
5.	MAIN FUNCTION OF PROPERTY	r: Single F	amily Dw	elling and Orcha	ard Busines:	5	
6.	PROJECT TITLE/ REASON FOR Western Parkway Project (Sect		plicable):				
	#: Form: 2 CRS 2 Main Building Form 4 CRS 3 Secondary Building	ig Form	Dwelling	perty types: I, Produce Marke Sheds, Stable,		Barn .	
	0 CRS 4 Archaeological Sit 1 CRS 5 Structure (Building		Water T	ower -			
	0 CRS 6 Structure (Land Fe		*******				
	0 CRS 7 Object Form		•			•	' '
	0 CRS 8 Landscape Elemen	nts Form					
	1 CRS 9 Map Form		N/A				
	0 CRS 14 Potential District	Form				· · · · · · · · ·	
8.	SURVEYOR INFORMATION:						
	Surveyor name:	Gerald M. I	Kuncio				
	Principal Investigator name:	Gerald M, I	Kuncio	1.4			
	Principal investigator signature:		ewlest	Buren	<u> </u>		
	Organization:	Skelly and	Loy, Inc.	-		Date:	12/2005

10. STATE HISTORIC CON plan(s)):	TEXT FRAMEWORK (check all appropriate boxes; refer to state management
a) Time period(s)	☐ Pre-European Contact ☐ Paleo-Indian ☐ Archaic ☐ Woodland I ☐ Woodland II
	1600-1750± Contact Period (Native American) 1630-1730± Exploration and Frontier Settlement 1730-1770± Intensified and Durable Occupation 1770-1830± Early Industrialization 1830-1880± Industrialization and Early Urbanization 1880-1940± Urbanization and Early Suburbanization 1940-1960± Suburbanization and Early Ex-urbanization
b) Geographical zone	 □ Pledmont □ Upper Peninsula □ Lower Peninsula/Cypress Swamp □ Coastat □ Urban (City of Wilmington)
c) Historic period ther	ne(s)
	Agriculture Forestry Transportation and Communication Settlement Patterns and Demographic Changes Architecture, Engineering and Decorative Arts Mining/Quarrying Government Fishing/Oystering Manufacturing Retailing/Wholesaling Finance Occupational Organizations Professional Services Transportation and Communication Settlement Patterns and Demographic Changes Architecture, Engineering and Decorative Arts Government Religion Education Community Organizations Occupational Organizations Major Families, Individuals and Events

9. OTHER NOTES OR OBSERVATIONS:

CRS# <u>S-11519</u>

CULTURAL RESOURCE SURVEY MAIN BUILDING FORM

1.	ADDRESS/LOCATION: 871 Nassau Road/NE side of U.S. Route 1 (Coastal Highway)	
2.	FUNCTION(S): historic Single Family Dwelling current Single Family Dwelling	g
3.	YEAR BUILT: 1960 CIRCA?: ARCHITECT/BUILDER: N/A	
4.	STYLE OR FLOOR PLAN: Modern	
5,	INTEGRITY: original site 🖾 moved 📋	
	if moved, from where other location's CRS #	<u>year</u>
	list major alterations and additions with years (if known) a. Built in 3 stages between 1952 and 1964 b.	year
6.	CURRENT CONDITION: excellent good fair poor	
7.	DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; lear blanks.)	ve no
	a. Overall shape: Rectangular Stories: 2 Additions: N/A	
	b Structural system (if known): Wood frame	
	c. Foundation: materials: Concrete block basement: full partial in not visible in no basement in the control of	
	d. Exterior walls (original if visible& any subsequent coverings): Asbestos shingle	
	e. Roof: shape: Side gable materials: Asphalt shingles cornice: Simple wood dormers: 0 chimney: location(s): Corbelled brick interior at the west side ridge line	
8.	DESCRIPTION OF ELEVATIONS: a. Facade: Direction: S 1) Bays 12 2) Windows 16 fenestration Symmetrical type 8/8, 4/4, 8/12, picture window trim Simple wood surrounds	

shutters 0

Facade (cont'd)

3) Door(s) 2

location Recessed on the right side of the main block; left side of the garage type Wood and glass trim Side lights

- 4) Porch(es) Recessed under a shed roof
- b. Side: Direction: E
 - 1) Bays 2-3
 - 2) Windows 1

fenestration irregular type 8/12 wood trim Simple wood surrounds shutters 0

3) Door(s) 4

location 3 - E end of garage; 1 - pedestrian door behind the garage type Garage: vinyl overhead; Pedestrian: Wood with 12-light center panel trim N/A

- 4) Porch(es) 1 Small entry porch sheltering the garage door
- c. Side: Direction: W
 - 1) Bays 2
 - 2) Windows 2

fenestration Regular type 8/8 wood sash trim Simple wood surrounds shutters 0

3) Door(s) 0

location N/A type N/A trim N/A

- 4) Porch(es) 0
- d. Rear; Direction: N
 - 1) Bays 12
 - 2) Windows Not visible

fenestration Not visible

type Not visible trim Not visible shutters Not visible

3) Door(s) Not visible

location Not visible type Not visible trim Not visible

- Porch(es) Not visible
- 9. INTERIOR: Not accessible
- LANDSCAPING: Nestled on a landscaped lawn among mature trees.
- 11. OTHER COMMENTS: Market is closest to the road, then outbuildings, then the house.

CULTURAL RESOURCE SURVEY MAIN BUILDING FORM

CRS#	S-11519

	ADDRESS/LOCATION: 871 Nassau Road/NE side of U.S. Route 1 (Coastal Highway)	
		- 44-de-A
2.	FUNCTION(S): historic Roadside Produce Market current Roadside Produc	e Market
) _	YEAR BUILT: 1952 CIRCA?: ARCHITECT/BUILDER: N/A	
١.	STYLE OR FLOOR PLAN: Open/Utilitarian Commercial	
5 .	INTEGRITY: original site 🗵 moved 📋	
	if moved, from where other location's CRS N/A	# year
	list major alterations and additions with years (if known) a. N/A	year
	b.	
ŝ.	CURRENT CONDITION: excellent 🔲 good 🖾 fair 🗀 poor [
7.	DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; blanks.)	leave no
	a. Overall shape: Rectangular Stories: 1 Additions: N/A	
	b Structural system (if known): Wood frame	
	c. Foundation: materials: Poured concrete basement; full ☐ partial ☐ not visible ☐ no basement ☒	
	 d. Exterior walls (original if visible& any subsequent coverings): Asbestos shingle 	
	e. Roof: shape: Flat materials: Rolled asphalt cornice: Signboard reading "Nassau Orchards Market Established 1919" dormers: 0 chimney: location(s): 0	
8.	DESCRIPTION OF ELEVATIONS: a. Facade: Direction: S 1) Bays 11 2) Windows 20 fenestration irregular type Molded plastic in overhead garage doors	

shutters 0

Facade (cont'd)

3) Door(s) 10

location Across entire front and on pedestrian door on the recessed portion type Overhead vinyl garage and a plain wood pedestrian door trim Wood runners

- 4) Porch(es) 0
- b. Side: Direction: W
 - 1) Bays 3
 - 2) Windows 4

fenestration Irregular type 3 - 3-light; 1 - 1/1 trim Simple wood surrounds shutters 0

3) Door(s) 0

location N/A type N/A trim N/A

4) Porch(es) 0

Side: Direction: E

- - 1) Bays 5
 - 2) Windows 9

fenestration Regular type 3-light grouped in 3s; one set covered with chicken wire trim Simple wood surrounds

shutters 0

3) Door(s) 0

location N/A type N/A trim N/A

- 4) Porch(es) 0
- d. Rear: Direction: N
 - 1) Bays 11
 - 2) Windows 14

fenestration irregular

type 12 - 4; light with fixed panes; 2 - 2-light fixed pane trim Simple wood surrounds

shutters 0

3) Door(s) 1

location Centered type Barn/shed trim Wood surround

- 4) Porch(es) 0
- INTERIOR: Not accessible
- 10. LANDSCAPING: Asphalt parking lot between Nassau Road and the building.
- OTHER COMMENTS: Construction date was provided by the owner.



CULTURAL RESOURCE SURVEY SECONDARY BUILDING FORM

CRS#	S-11519	

1.	ADDRESS/LOCATION: 871 Nassau Road/NE side of U.S. Route 1 (Coastal Highway)	
2.	FUNCTION(S): historic Garage current Garage	
3.	YEAR BUILT: 1930 CIRCA?: MA ARCHITECT/BUILDER: N/A	
4.	STYLE/FLOOR PLAN: No style/Open	
5.	INTEGRITY: original site ⊠ moved □ if moved, from where N/A original location's CRS #	year
	Ilst major alterations and additions with years (if known) a. N/A b.	year
6.	CURRENT CONDITION: excellent good fair	poor [
7,	DESCRIPTION:	
	a. Structural system Pressed block	
	b. Number of stories 1	
	c. Wall coverings Pressed block/shiplap siding in the gable ends	
	d. Foundation Not visible	
	e. Roof Front gable structural system Purlins and rafters (tails are exposed) coverings Asphalt shingles openings 0	
8.	DESCRIPTION OF ELEVATIONS:	
	a. Facade: direction: W 1) bays: 1 2) windows: 0	
	3) door(s): 2 - Double-leaf barn doors	
	4) other: Shiplap siding in the gable end	

CRS# S	-11519
--------	--------

Ь.	1)	e: direction: N bays: 1 windows: 2 - 9-light fixed sash
	3)	door(s): 0
	4)	other: Obscured by trees
C.	1)	e; direction: S bays: 1 windows: 2 – 9-light fixed sash
	3)	door(s): 0
	4)	other: N/A
d.	,	ar: direction: E

- 2) windows: 2 9-light fixed sash; 1-single pane casement in gable
- 3) door(s): 0
- 4) other: Shiplap siding in the gable end
- INTERIOR (if accessible):
 - a) Floor plan Not accessible
 - b) Partition/walls Not accessible
 - c) Finishes Not accessible
 - d) Furnishings/machinery Not accessible



CULTURAL RESOURCE SURVEY SECONDARY BUILDING FORM

CRS#	S-11519

1.	ADDRESS/LOCATION: 871 Nassau Road/NE side of U.S. Route 1 (Coastal Highway)	.
2.	FUNCTION(S): historic Shed/Storage current Shed/Storage	
3.	YEAR BUILT: 1930 CIRCA?: ARCHITECT/BUILDER: N/A	
4.	STYLE/FLOOR PLAN: No style/Open	
5.	INTEGRITY: original site moved	
	if moved, from where original location's CRS #	<u>year</u>
	list major alterations and additions with years (if known) a. N/A b.	year
6.	CURRENT CONDITION: excellent ☐ good ☒ fair ☐	poor 🗀
7.	DESCRIPTION:	
	a. Structural system Wood frame	
	b. Number of stories 1½	
	c. Wall coverings Vertical board and batten	
	d. Foundation Not visible	
	e. Roof structural system Side gable coverings Asphalt shingles openings 0	
8.	DESCRIPTION OF ELEVATIONS:	

a. Facade: direction: S

1) bays: 1

2) windows: 0

3) door(s): 2 - Vertical boards in the main block and the addition

4) other: Sign reads "Pesticide Storage"

1519	S-11	CRS#
------	------	------

_			-
h	Cida.	direction:	_
D.	JIUU.	unecuon.	_

- 1) bays: 1
- 2) windows: 0
- 3) door(s): 0
- 4) other: 1-story, 1-bay shed roof addition at this end

c. Side: direction: W

- 1) bavs: 1
- 2) windows: 0
- 3) door(s): 0
- 4) other: Directly against this side is a cylindrical metal water tower
- d. Rear: direction: N
 - 1) bays: 1
 - 2) windows: 1 2-light wood fixed casement
 - 3) door(s): 0
 - 4) other: N/A

9. INTERIOR (if accessible):

- a) Floor plan Not accessible
- b) Partition/walls Not accessible
- c) Finishes Not accessible
- d) Furnishings/machinery Not accessible



CULTURAL RESOURCE SURVEY SECONDARY BUILDING FORM

CRS#	S-11519	

1.	ADDRESS/LOCATION: 871 Nassau Road/NE side of U.S. Route 1 (Coastal Highway)	
٠.		
2.	FUNCTION(S): historic Stable current Stable	
3.	YEAR BUILT: 1975 CIRCA?: ☑ ARCHITECT/BUILDER: N/A	
4.	STYLE/FLOOR PLAN: No style/Stalls	
5.	INTEGRITY: original site 🗵 moved 🗌	
	If moved, from where N/A original location's CRS#	year
	list major alterations and additions with years (if known) a. N/A b.	year
6.	CURRENT CONDITION: excellent ☐ good ⊠ fair ☐	poor 🗌
7.	DESCRIPTION:	
	a. Structural system Wood frame	
	b. Number of stories 1	
	c. Wall coverings Barn siding	
	d. Foundation None	
	e. Roof Shallow side gable with an overhang over the stall doors structural system. Not visible coverings. Metal openings. 0	
8.	DESCRIPTION OF ELEVATIONS:	
	a. Facade: direction: E 1) bays: 6 2) windows: 4	
	3) door(s): 4 - Dutch doors	

4) other: N/A

CRS#	S-11519
------	---------

- b. Side: direction: S
 - 1) bays: 1
 - 2) windows: 0
 - 3) door(s): 1 Dutch door
 - 4) other: N/A
- c. Side: direction: N
 - 1) bays: 1
 - 2) windows: 0
 - 3) door(s): 0
 - 4) other: N/A
- d. Rear: direction: W
 - 1) bays: 4
 - 2) windows: 0
 - 3) door(s): 0
 - 4) other: N/A
- 9. INTERIOR (if accessible):
 - a) Floor plan Stalls
 - b) Partition/walls Not visible
 - c) Finishes None
 - d) Furnishings/machinery Not visible



CULTURAL RESOURCE SURVEY SECONDARY BUILDING FORM

4) other: Wood poles between separate bays

CRS#	S-11519	

 ADDRESS/LOCATION: 871 Nassau Road/NE side of U.S. Route 1 (Coastal Highway) 		
2.	FUNCTION(S): historic Equipment Barn current Equipment Barn	
3.	YEAR BUILT: 1955 CIRCA?: ARCHITECT/BUILDER: N/A	<u> </u>
4.	STYLE/FLOOR PLAN: No style/Open	
5.	INTEGRITY: original site 🖾 moved 🗌 If moved, from where N/A original location's CRS #	year
	list major alterations and additions with years (if known) a. N/A b.	уеаг
6.	CURRENT CONDITION: excellent ☐ good ☑ fair ☐	poor 🗌
7.	DESCRIPTION:	
	a. Structural system Wood frame	
	b. Number of stories 1	
	c. Wall coverings Wood siding	
	d. Foundation Not visible	
	e. Roof Side gable structural system Purlins and rafters coverings Metal openings 0	
8.	DESCRIPTION OF ELEVATIONS:	
	a. Facade: direction: S 1) bays: 6 2) windows: 0	
	3) door(s): 4 Dutch doors	

CRS#	S-11519	
------	---------	--

- b. Side; direction: S
 - 1) bays: 1
 - 2) windows: 0
 - 3) door(s): 1 Dutch door
 - 4) other: Faint "Nassau Orchards Inc."
- c. Side; direction: W
 - 1) bays: 1
 - 2) windows: 0
 - 3) door(s): 0
 - 4) other: N/A
- d. Rear: direction: N
 - 1) bays: 6
 - 2) windows: 0
 - 3) door(s): 0
 - 4) other: N/A
- 9. INTERIOR (if accessible):
 - a) Floor plan Open
 - b) Partition/walls No interior walls
 - c) Finishes None
 - d) Furnishings/machinery Various pieces of farming equipment

ST SET

DELAWARE STATE HISTORIC PRESERVATION OFFICE 15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY _STRUCTURE (BUILDING-LIKE) FORM

CRS#	S-11519	

1.	ADDRESS/LOCATION: 871 Nassau Road/NE side of U.S. Route 1 (Coastal Highway)	
2.	FUNCTION: Water Tower IN L	ISE7 🛚
3.	YEAR BUILT: 1930 CIRCA?: MA ARCHITECT/BUILDER: N/A	_
4.	STYLE/PLAN: Cylindrical tower on wood bents	
5.	INTEGRITY: original site 🗵 moved 🗔	
	If moved, from where original location's CRS #	<u>year</u>
	list major alterations and additions with dates (if known)	<u>year</u>
	a. N/A b.	
6.	CURRENT CONDITION: excellent good fair poor	
7.	DESCRIPTION (describe the structure as completely as possible):	
	a) Overall shape Cylindrical helght Approx. 15 ft length Approx. 6 ft width Approx. 10 ft	
	b) Structural system: Wood bents formed into a tower	
	c) Foundation: Concrete slab	
	d) Exterior covering: Metal tank; wood bents	

7. DESCRIPTION (cont'd):

CRS# S-11519

e) Openings 0

f) Other features A pipe extends out to the south, apparently to fill tankers with water or pesticides.

CULTURAL RESOURCE SURVEY MAP FORM


CRS#	S-11519	

1.	ADDRESS/LOCATION:	871 Na	ssau Road	d/Northeast side of U.S. Route 1 (Coastal Highway)
	_			 -
2.	NOT FOR PUBLICATION		reason:	
3.	LOCATION MAP:			

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDIC	AT	E N	ЮF	₹Tŧ	4 (ON	P	<u>.</u> A	N																												
• :•:	•	-	• .	• .	•	•(*	•	•		•	• .	4	•	•	•	•	•	•	•	•	•	₽v.	•	٠.	•	4	•	•.	*	•	•	•	*	•		1
<u> 140</u>	• 0	*.	₹ :	4 (•	•	•	•	•	, ,,	•	• '	•	•	•	•	·•	•	•		•	•	F	.	•	7	•	^	*	۰	•	*	*	•	•	•	1
* *	•	•	•	= '	+	•	•	•		•		•		•	•		#	•	.		•	•	3	3		•	•	: *	7		•	•	•	•	•	• •	1
		● : 4	•	•	.*	•	. .			•	•.	•	•	•	•. :	•	•		•		* ,		Ě	₹	•		•	· ·			•	.•.	_	1 .	•	. •]
	•	•	•		•	•	•	•	,		۹.	*	**	•		•	•	•.	•	•	•	•		, co		;• 		į.) ;= .	•	•		•	•	· -]
* *	•	٠,	•	•	•	٠		•		•	•	•	•	•	•.	•.		•	•	•	• 2 .1	<u>.</u>	3	5	•	_	•	Ž	4		•	•	•	-	•	_]
4	*	•	•	•	•	•	₩.	•	' '	•	•	■.	. .	•	•	•	ď		•	•	•		ľ	ĺ	•		•	2	1		•		•	•	•	•]
	.•.	#	.	•	•	•	•	•	' '	•		•	•	•	•	_	Ţ		•	•			Γ	-	:	•		Δ	٠							-]
•	•	•	•	•	•	٠	•	•		_	•	•	•	•	•	•		,	•		•		ŀ			- 2		٠	i.	_	_			_]
· ·	•	•	•	•	•	•	•	•		-	<u>.</u>	•	<u>.</u>	•	Ϊ.	_			~	. "			L	•					T		72	-				Ī.,].
18	₹		•	•		•	•			•	-			-		${\mathbb L}$]	•		Ĺ	1	- \-					1	<u>:</u>	_			 ب د د	•	·]
) = *	•	₹. •	•	. •	•	. •			-		•										•	•			÷		4					r	_ 			}
%%' * ∞ =		•	•	•	•	•	-			•			<i>"</i>	-	4					÷.		*	÷				ار العجار	-	À				ŀ	•			1
· · · · · · · · · · · · · · · · · · ·	• 1		•		-	•								- •	4		'S ●	,-		•				•		٠.		֡֟֟֟ <u>֚֚֚֚֚֚֚֚֚֚֚֚֚֚֚</u>			÷.		ŀ	•	4	4	1
iren en e	.≅ 14.	•				-T -≟				_				•												Ú,	$\bar{\mathbf{z}}$	4		•			-		·	<u>.</u>	1
)***		-	-			•				■.		•	•	•			•	·				ě.					j.	٦,	•	•	•			-	/		IA
		•	:	:	ì	•	_						I	2								•					ع_	,4	١.,				ľ		•		ROAD
		-						,				3.	1	Į.	H					•							·\$.	-			ė		ľ				1 %
	•				٠	-		. ,		ኢ	λ	.2	1	Ł	۲			÷	٠.	5					₹.		3	4			٠					•	1
									٠,	7	۲.	Ε	1	Ł	H			•	•			3	:4			•	3	-]	•		•	4	Ļ		•	•	! - ፈ
									. 3		ľ		Ļ	ļ,	+	١.		•	•		ŀ	F	7	•	*1	3	3	1	7	•	•	ľ	٠.	•	•	•	NASSAU
	÷	•		•	-				-3	Ļ	4		l	Ł	ተ'		•		•]		•	Н	Ь	3.	آم	4	4			_			1	•	•	•	+ 5 2
						. •			٧,	Ş	1	•	ı	1	h	2	•	•	•	•	, u -	7	₹	Ξ.	1	ı	I		4	٠.	=;*		₽.		٠	٠	1
		•	÷	ď		•	•	٠.	. 4	•	ı	•	l			3 -	•.	•	•	•	•	C	J	7	4			4	*	•	•	•	-	#	•	•	ΙŽ
	•				•	. •		1		Ċ.	1	•	1	3	1	3	.="		•	•	*	إز	,	¥	Ĵ≢÷	1	•	X	ſ	,#	•	٠	٠	•	•	•	1
	•		•	•		•	,	٠.	• 4	ð	1		╂	4	4	•		•	•	•			Š	•	•	P	•	3	꿑.	٠	•	•	•.	•	•		1
	•	.•	÷	÷	÷	•	*		• •	3		•		I	1	2	•	•	٠.			3	<u>.</u>	•		•			ζ.	•	٠		•	•	٠	•	1
:¥	-	; 4	•	*	•	•	•	•	- 4	ē	●.	•		1	ŀ	•	.•	•	1.7	, = "	٠.•	3	A. Å.		₽,	•	•	-	₹.	7	•	. •	•	•	•	•	1
. <u></u> •		. 🖦	•	•	•	٠		•	•		٠	•	7		+	٠	•	•	٠	*	٠	.*	•	٠	•	*	•	4	2.	•	•	•	•	•	•		1
	•	.•	*	•	.•	4	• •	•	٠	(4)		٠	2			•	*	7 4	•	•	•	٠	₫.	•	•	•	•	*	•	•	•	•	•	*	*	•	1
· * +	٠	4	3	•	•	*	3	• -	•	* *	•	. s	•	•••	•	-	•	*	*	•	•	•	7.	•	•	•	•		ļ	•	•		*		•	•	4
/4 ·-	•	•	•	♣.	•		•	•	•.	; * .	4	7 4 5	•	•	•;	Æ	٠	√ ■	•	٠	•		•) p -	₹.	•	•	*	•		•				*	= ,	1
* *	•	♦.	•	•	.♦.	i, 🛉	9		*	•	•	1	•	•	*	*	٠	•	٠	440	₩'	≜ \	•	/ = 1.		**	•	, , (*)	•		•	•	4 #	•			1
* *		•	(-))	*	*	V 🖻	2	•.	٠	*	٠		•	•	•	•		•	٠	, = 7	7	*	*	٩	*	₩,	٠	*	•	, :			•			· **/	1
(3)	:- .	٠	•	×	*	٠	17	•	•	•="	•	. # .	•	1 4 .7	٠		•	4	*	•	٠	(A)	•	17	Ħ	2	•	*	•	•			•	\ .	•	•	1_
·* •	•	•	•	•	./•	•	d	•	+	*	•	*	•	. 🕶	*	*		₽ ₽].	٠	**	•	•	•		•	•	-	•		•	h, √	•	. •				
, (1.1 - 1.8)	1#1	÷	•	•	32	. ,		¥,	*	•	•	•		•	*	4	•	7 6 7	•	\ #	4	₹	₹.	***	•	•		•	tr - #	• 4	,		. *	i		بمسد	1
ean∮ ∓	140	•	•	*	e, iii	•		₩"."	•		*	*	٠	* "	#	·#k-	₩.	- *	*	A\$	•	٠	*		•	4				e di	•	• •		•	•	72	1
i est		•	.=		-		. 1	•	4	y .	•	÷	÷	•	٠	•	7	•	•	€.	'n	*		•	•		•	•	v a	•	• 4	•	'	• •	. #	•	1

DELAWARE STATE HISTORIC PRESERVATION OFFICE

PHOTOGRAPHIC INVENTORY

CRS # S-11519 Date 12/2005 Photo Roll # C-4612 Surveyor Gerald M. Kuncio

Description: C-4612:1 House, S (front) elevation; C-4612:2 House, E and N (rear) elevations; C-4612:3 House, S front) elevation; C-4612:4 Fruit Stand, S (front) and E elevations; C-4612:5 Fruit Stand, W and S (front) elevations; C-4612:6 Fruit Stand, E and N (rear) elevations; C-4612:7 Garage, N and W (front) elevations; c-4612:8 Pesticide

torage and water tank, facing NE

Negative location (if other than SHPO)

Skelly and Loy, Inc.



oc # 20-06-01-05-12









DELAWARE STATE HISTORIC PRESERVATION OFFICE

PHOTOGRAPHIC INVENTORY

CRS # S-11519 Date 4/2006 Photo Roll # C-4616 Surveyor Gerald M. Kuncio

Description: C-4616:1 - Equipment barn, facing NW; C-4616:2 - Stable, facing SW.

Negative location (if other than SHPO) Skelly and Loy, Inc.

Attach contact print(s):





doc # 20-06-01-05-12

A STEP INCHES

DELAWARE STATE HISTORIC PRESERVATION OFFICE 15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY SURVEY UPDATE FORM

CRS#	S-8393	

	r (metagos							
1.	HISTORIC NAME/FUNCTION: Be	lltown Historic	District					
2.	ADDRESS/LOCATION: U.S. Rou Points/Le	te 9 (Seashore	e Highway -	and S.	R. 23 (Bea	ver Dam R	oad) at the i	Five
3.	CURRENT CONDITION: exceller	nt 🗌 goo	d 🗌	fair) poor		lemolished	
4.	INTEGRITY: The historic district he existing buildings, and the in-fill co	as lost integrity nstruction of n	y due to the new buildin	e loss of gs.	resources,	additions a	ind alteration	ns to
5.	SETTING INTEGRITY: Belitown's he the encroachment of large, new he	istoric setting a busing develop	as a rurai A pments and	African A d comm	merican co ercial const	mmunity is truction in t	being lost du he area.	ue to
6 . I	#: Form: O CR\$ 2 Main Building Form CR\$ 3 Secondary Building F CR\$ 4 Archaeological Site F CR\$ 5 Structure (Building-L CR\$ 6 Structure (Land Feate CR\$ 7 Object Form CR\$ 8 Landscape Elements CR\$ 9 Map Form CR\$ 14 Potential District Fo	Corm Orm ike) Form Ure) Form N/	st property	types:				
7.	SURVEYOR INFORMATION:							
	Surveyor name:	Gerald M. Kı	uncio					
	Principal Investigator name:	Gerald M. Kı	uncio					
	Principal Investigator signature:	Hea	ald IN	Zun	ر کری			
	Organization:	Skelly and L	oy, Inc.			Date:	12/2005	

8. OTHER NOTES OR OBSERVATIONS:

9.

CRS# S-8393

Belltown was determined eligible for NRHP listing in 1988 under NRHP Criterion A as an early African American community in southern Delaware. It is proposed that the Belltown Historic District be evaluated as no longer eligible for listing. In 1988, the community "retained a great deal of social continuity since many of the families [were] descendants of early residents." The community also "retained a relatively high degree of architectural integrity" (Tidlow et al. 1988). The anchors of the community were the school and the church. both located at the east end of the village.

The architectural integrity has been lost in the 18-year period since the historic district was surveyed. As illustrated on the accompanying CRS-13 form, Belltown is much different today. Original contributing resources have been lost. Others that remain, such as 32359 U.S. Route 9, have been greatly expanded. remodeled, or have had original exterior materials and windows altered. There has also been a great deal of infill construction, including a multiplicity of trailer homes. In short, Belltown today little resembles the community that was determined eligible for listing in the NRHP in 1988.

The extensive alterations have compromised Belltown's ability to convey its history as a rural African American community in southern Sussex County. It is recommended that the Belltown Historic District be determined not eligible for NRHP listing.

9. STATE HISTORIC CONT plan(s)):	EXI FRAMEWORK (Check	all appropriate boxes; refer to state management
a) Time period(s)	☐ Pre-European C☐ Paleo-Indian☐ Archaic☐ Woodland I☐ Woodland II	Contact
	1880-1940± Urbanization	and Frontier Settlement and Durable Occupation
b) Geographical zone	🗵 Coastai	
c) Historic period them	ə(s)	
	Agriculture Forestry Trapping/Hunting Mining/Quarrying Fishing/Oystering Manufacturing Retailing/Wholesaling Finance Professional Services	 □ Transportation and Communication ☑ Settlement Patterns and Demographic Changes ☑ Architecture, Engineering and Decorative Arts □ Government □ Religion □ Education □ Community Organizations □ Occupational Organizations □ Major Families, Individuals and Events

doc # 20-06-01-05-13

DELAWARE STATE HISTORIC PRESERVATION OFFICE 15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY POTENTIAL DISTRICT FORM

CRS#

S-8393

CRS-14

1.	NAME OF DISTRICT: Belitown I	Historic District	· · · · · · · · · · · · · · · · · · ·								
2.	BOUNDARY: Roughly bounded by U.S. Route 9 (Seashore Highway) and S.R. 23 (Beaver Dam Road) at the Five Points/Lewes										
3.	FUNCTION: residential: [2 recreational: [2 other: [2]		religious: 🗵 archaeological: 🗌 vernmental: 🔲 educational: 🗍								
4.	REASON FOR SURVEY: Western	n Parkway Project (Section 106)									
5.	DOCUMENTATION:										
	a) Report title: Western Park	way Project, Phase I Historic Arch	tectural Resource Survey								
	b) Map showing boundary:	attached 🗵									
	c) Cross-reference list of individual CRS#s (use ranges only for sequential numbers): The Belltown Historic District was determined eligible for listing in the National Register of Historic Places in 1988. It includes these individual survey numbers:										
	S-870 through S-890 S-8006 through S-8015										
	These numbers may include dup	licates.									
6.	SURVEYOR INFORMATION:										
	Surveyor name:	Gerald M. Kunclo									
	Principal investigator name:	Gerald M. Kuncio									
	Principal investigator signature:	- Seuld MZ	w								
	Organization:	Skelly and Loy, Inc.	Date: 12/2005								

USE BLACK INK ONLY

DELAWARE STATE HISTORIC PRESERVATION OFFICE

PHOTOGRAPHIC INVENTORY

RS# S-8393 Date 12/2005 Photo Roll# C-4613 Surveyor Gerald M. Kuncio

Description: C-4613:10 Dwelling on the N side of U.S. Route 9 with a large noncontributing resource in the ackground, facing NE; C-4613:11 Noncontributing resource on the N side of U.S. Route 9, facing NW; C-4613:12 New construction at U.S. Route 9 and Evette Lane, facing N; C-4613:13 Much altered house at the NW edge of the community, facing NW; C-4613:14 Same house, facing NE; C-4613:15 Removal of contributing resources on the outh side of U.S. Route 9 and replacement by trailers, facing SE; C-4613:16 New construction on the N side of S.R. 23, facing N; C-4613:17 Replacement construction on the N side of S.R. 23, facing NW.

legative location (if other than SHPO)

Skelly and Loy, Inc.











oc # 20-06-01-05-12

4/2006 Photo Roll# C-4616 Gerald M. Kuncio S-8393 Surveyor ČRS# Date Pescription: C-4616:12 New, large building set back on the N side of U.S. Route 9, facing N; C-4616:13 Contributing uilding on the S side of U.S. Route 9 replaced by trailers, facing SW; C-4616:14 Noncontributing and two contributing buildings on the S side of U.S. Route 9, facing SW; C-4616:15 Replacement building on the N side of ■.S. Route 9, facing NW; C-4616:16 Expansion of the Seaway Transportation Company at the comer of U.S. Route 9 nd Stingley Lane, facing NW; C-4616:17 Three contributing resources on the NW side of U.S. Route 9, facing NE; Two contributing resources at the SW corner of Beaver Dam Road, facing NE; Contributing resource and vacant lot where contributing resource was removed on the N side of Beaver Dam Road, facing NW; C-4616:20 Formerly ontributing resource with a new addition on the N side of Beaver Dam Road, facing NW; C-4616:21 New construction and a contributing resource in the background on the N side of Beaver Dam Road, facing NE; C-4616:22 Contributing and noncontributing resources on the N side of Beaver Dam Road, facing NW.

Regative location (if other than SHPO) Skelly and Loy, Inc.













oc # 20-06-01-05-12

CRS# S-8393

Date 7/2006

Photo Roll#

C-4654 Surve

Surveyor Gerald M. Kuncio

Description: 16 The Nassau Colored School, facing NW; 17 House on lot 3-34-5-113, facing N; 18 House on Waples St. not included in the original Belltown Historic District boundary, facing NE; 19 House on Waples St. not included in the original Belltown Historic District boundary, facing NW; 20 House on Waples St. not included in the original Belltown Historic District boundary, facing NE; 21 House from late 20th century on lot 3-34-5-122, facing NW; 22 House on lot 3-34-5-124, facing N; 23 House not included in the original Belltown Historic District boundary, facing NE; 24 Late 20th century building located in Belltown outside the historic district boundary.

Negative location (if other than SHPO)

Skelly and Loy, Inc.

Attach contact print(s):



doc # 20-06-01-05-12

CRS # S-8393 Date 7/2006 Photo Roll # C-4655 Surveyor Gerald M. Kuncio

Description: 1 Building on lot 3-34-5-131, facing N, with a large garage/industrial building constructed to its rear; 2 House on lot 3-34-5-133, facing NW; 3 House on lot 3-34-5-135.1, facing NW; 4 House on lot 3-34-5-134, with a large new addition at the rear, facing N; 5 Substantially altered house on lot 3-34-5-139, facing N; 6 House on lot 3-34-5-193, facing SE; 7 House on lot 3-34-5-2-2, now with a large addition appended to the rear, facing SE.

Negative location (if other than SHPO)

Skelly and Loy, Inc.

Attach contact print(s):















doc # 20-06-01-05-12

CRS # S-8393 Date 7/2006 Photo Roll # C-4655 Surveyor Gerald M. Kuncio

Description: 8 Building on lot 3-34-5-214, facing SE; 9 John Wesley Methodist Episcopal Church, facing SE; 10 House on the Beaver Dam Road portion of lot 3-34-5-216, facing N; 11 Second house on the Beaver Dam Road portion of lot 3-34-5-216, facing N; 12 House on lot 3-34-5-212, facing N, note the replacement siding, replacement fenestration, and a new roof; 13 House on lot 3-34-5-211, which replaced a contributing house, facing NW; 14 House on lot 3-34-5-210, facing NW.

Negative location (if other than SHPO) Skelly and Loy, Inc.

Attach contact print(s):



doc # 20-06-01-05-12

Photo Roll # C-4655 Surveyor Gerald M. Kuncio CRS # S-8393 7/2006 Date

Description: 15 House on lot 3-34-5-200, facing NW; 16 House on lot 3-34-5-198 with a one-story addition on the east side, facing NW; 17 House on lot 3-34-5-196 with new siding and roof, facing NE; 18 Trailer on lot 3-34-5-191, facing W; 19 House on lot 3-34-5-190, facing NE; note the one-story garage addition; 20 House on lot 3-34-5-190, facing NE; note the one-story garage addition; 21 House on lot 3-34-5-189, facing NW, note the deterioration and that he cross-gable jerkinhead roof has been replaced.

Negative location (if other than SHPO)

Skelly and Loy, Inc.

Attach contact print(s):











doc # 20-06-01-05-12

5-8393

National Register of Historic Places Registration Form

This form is for use in nominating or requesting determinations of eligibility for individual properties or districts. See instructions in Guidelines for Completing National Register Forms (National Register Bulletin 16). Complete each item by marking "x" in the appropriate box or by entering the requested information. If an item does not apply to the property being documented, enter "N/A" for "not applicable." For functions, styles, materials, and areas of significance, enter only the categories and subcategories listed in the instructions. For additional space use continuation sheets (Form 10-900a). Type all entries.

1. Name of Property			
	toric District	, ,,	··· · · · · · · · · · · · · · · · · ·
other names/site number			
2. Location	· · · · · ·		
	ection of Routes 1,	9,275, and 285 L	not for publication
		5,2,5, and 205 [vicinity
city, town Lewes and Reho state Delaware code		ex code 005	
date Belanale code	DE county Suss	<u>ex code 005</u>	zip code 19958
3. Classification			- ···
Ownership of Property	Category of Property		rces within Property
<u>X</u> private	building(s)	Contributing	Noncontributing
public-local	_X district	60	22_ buildings
public-State	site		sites
public-Federal	structure		structures
	object		objects
	•	60	22 Total
Name of related multiple property listing	na:	Number of contrib	outing resources previously
The state of the s	·B·	listed in the Natio	T 2 T
	 _	1310C III III0 1144IC	mai riegistei
4. State/Federal Agency Certification	ation		
National Register of Historic Places	mination of eligibility meets the d and meets the procedural and p	professional requirements se	registering properties in the et forth in 36 CFR Part 60.
National Register of Historic Places In my opinion, the property mee	mination of eligibility meets the d and meets the procedural and p	ocumentation standards for professional requirements se	registering properties in the et forth in 36 CFR Part 60. continuation sheet.
National Register of Historic Places	mination of eligibility meets the d and meets the procedural and p	ocumentation standards for professional requirements se	registering properties in the et forth in 36 CFR Part 60.
National Register of Historic Places In my opinion, the property mee	mination of eligibility meets the d and meets the procedural and p	ocumentation standards for professional requirements se	registering properties in the et forth in 36 CFR Part 60. continuation sheet.
National Register of Historic Places In my opinion, the property mee Signature of certifying official	mination of eligibility meets the distance and meets the procedural and pets does not meet the National	ocumentation standards for professional requirements seal Register criteria. See c	registering properties in the et forth in 36 CFR Part 60. ontinuation sheet.
National Register of Historic Places In my opinion, the property mee Signature of certifying official State or Federal agency and bureau	mination of eligibility meets the distand meets the procedural and pats does not meet the National	ocumentation standards for professional requirements seal Register criteria. See c	registering properties in the et forth in 36 CFR Part 60. ontinuation sheet.
National Register of Historic Places In my opinion, the property mee Signature of certifying official State or Federal agency and bureau In my opinion, the property mee	mination of eligibility meets the distand meets the procedural and pats does not meet the National	ocumentation standards for professional requirements seal Register criteria. See c	registering properties in the et forth in 36 CFR Part 60. continuation sheet. Date continuation sheet.
National Register of Historic Places In my opinion, the property mee Signature of certifying official State or Federal agency and bureau In my opinion, the property mee Signature of commenting or other official	mination of eligibility meets the distand meets the procedural and pats does not meet the National ets does not meet the National ets does not meet the National	ocumentation standards for professional requirements seal Register criteria. See c	registering properties in the et forth in 36 CFR Part 60. continuation sheet. Date continuation sheet.
National Register of Historic Places In my opinion, the property mee Signature of certifying official State or Federal agency and bureau In my opinion, the property mee Signature of commenting or other official State or Federal agency and bureau 5. National Park Service Certific	mination of eligibility meets the distand meets the procedural and pats does not meet the National ets does not meet the National ets does not meet the National	ocumentation standards for professional requirements seal Register criteria. See c	registering properties in the et forth in 36 CFR Part 60. continuation sheet. Date continuation sheet.
National Register of Historic Places In my opinion, the property mee Signature of certifying official State or Federal agency and bureau In my opinion, the property mee Signature of commenting or other official State or Federal agency and bureau 5. National Park Service Certific I, hereby, certify that this property is:	mination of eligibility meets the distand meets the procedural and pats does not meet the National ets does not meet the National ets does not meet the National	ocumentation standards for professional requirements seal Register criteria. See c	registering properties in the et forth in 36 CFR Part 60. continuation sheet. Date continuation sheet.
National Register of Historic Places In my opinion, the property mee Signature of certifying official State or Federal agency and bureau In my opinion, the property mee Signature of commenting or other official State or Federal agency and bureau 5. National Park Service Certific	mination of eligibility meets the distand meets the procedural and pats does not meet the National ets does not meet the National ets does not meet the National	ocumentation standards for professional requirements seal Register criteria. See c	registering properties in the et forth in 36 CFR Part 60. continuation sheet. Date continuation sheet.
National Register of Historic Places In my opinion, the property mee Signature of certifying official State or Federal agency and bureau In my opinion, the property mee Signature of commenting or other offici State or Federal agency and bureau 5. National Park Service Certific I, hereby, certify that this property is:	mination of eligibility meets the distand meets the procedural and pats does not meet the National ets does not meet the National ets does not meet the National	ocumentation standards for professional requirements seal Register criteria. See c	registering properties in the et forth in 36 CFR Part 60. continuation sheet. Date continuation sheet.
National Register of Historic Places In my opinion, the property mee Signature of certifying official State or Federal agency and bureau In my opinion, the property mee Signature of commenting or other offici State or Federal agency and bureau 5. National Park Service Certific I, hereby, certify that this property is: entered in the National Register.	mination of eligibility meets the distand meets the procedural and pats does not meet the National ets does not meet the National ets does not meet the National	ocumentation standards for professional requirements seal Register criteria. See c	registering properties in the et forth in 36 CFR Part 60. continuation sheet. Date continuation sheet.
National Register of Historic Places In my opinion, the property mee Signature of certifying official State or Federal agency and bureau In my opinion, the property mee Signature of commenting or other offici. State or Federal agency and bureau 5. National Park Service Certific I, hereby, certify that this property is: entered in the National Register. See continuation sheet. determined eligible for the National	mination of eligibility meets the distand meets the procedural and pats does not meet the National ets does not meet the National ets does not meet the National	ocumentation standards for professional requirements seal Register criteria. See c	registering properties in the et forth in 36 CFR Part 60. continuation sheet. Date continuation sheet.
National Register of Historic Places In my opinion, the property mee Signature of certifying official State or Federal agency and bureau In my opinion, the property mee Signature of commenting or other offici State or Federal agency and bureau 5. National Park Service Certific I, hereby, certify that this property is: entered in the National Register. See continuation sheet. determined eligible for the National Register. See continuation sheet.	mination of eligibility meets the distand meets the procedural and pats does not meet the National ets does not meet the National ets does not meet the National	ocumentation standards for professional requirements seal Register criteria. See c	registering properties in the et forth in 36 CFR Part 60. continuation sheet. Date continuation sheet.
National Register of Historic Places In my opinion, the property mee Signature of certifying official State or Federal agency and bureau In my opinion, the property mee Signature of commenting or other official State or Federal agency and bureau 5. National Park Service Certific I, hereby, certify that this property is: entered in the National Register. See continuation sheet. determined eligible for the National Register. determined not eligible for the	mination of eligibility meets the distand meets the procedural and pats does not meet the National ets does not meet the National ets does not meet the National	ocumentation standards for professional requirements seal Register criteria. See c	registering properties in the et forth in 36 CFR Part 60. continuation sheet. Date continuation sheet.
National Register of Historic Places In my opinion, the property mee Signature of certifying official State or Federal agency and bureau In my opinion, the property mee Signature of commenting or other offici State or Federal agency and bureau 5. National Park Service Certific I, hereby, certify that this property is: entered in the National Register. See continuation sheet. determined eligible for the National Register. See continuation sheet.	mination of eligibility meets the distand meets the procedural and pats does not meet the National ets does not meet the National ets does not meet the National	ocumentation standards for professional requirements seal Register criteria. See c	registering properties in the et forth in 36 CFR Part 60. continuation sheet. Date continuation sheet.
National Register of Historic Places In my opinion, the property mee Signature of certifying official State or Federal agency and bureau In my opinion, the property mee Signature of commenting or other official State or Federal agency and bureau 5. National Park Service Certific I, hereby, certify that this property is: entered in the National Register. See continuation sheet. determined eligible for the National Register. determined not eligible for the National Register.	mination of eligibility meets the distand meets the procedural and pats does not meet the National ets does not meet the National al	ocumentation standards for professional requirements seal Register criteria. See c	registering properties in the et forth in 36 CFR Part 60. continuation sheet. Date continuation sheet.
National Register of Historic Places In my opinion, the property mee Signature of certifying official State or Federal agency and bureau In my opinion, the property mee Signature of commenting or other offici State or Federal agency and bureau 5. National Park Service Certific I, hereby, certify that this property is: entered in the National Register. See continuation sheet. determined eligible for the National Register. determined not eligible for the National Register. removed from the National Register.	mination of eligibility meets the distand meets the procedural and pats does not meet the National ets does not meet the Nat	ocumentation standards for professional requirements seal Register criteria. See c	registering properties in the et forth in 36 CFR Part 60. continuation sheet. Date continuation sheet.
National Register of Historic Places In my opinion, the property mee Signature of certifying official State or Federal agency and bureau In my opinion, the property mee Signature of commenting or other official State or Federal agency and bureau 5. National Park Service Certific I, hereby, certify that this property is: entered in the National Register. See continuation sheet. determined eligible for the National Register. determined not eligible for the National Register.	mination of eligibility meets the distand meets the procedural and pats does not meet the National ets does not meet the Nat	ocumentation standards for professional requirements seal Register criteria. See c	registering properties in the et forth in 36 CFR Part 60. continuation sheet. Date continuation sheet.

6. Function or Use	<u> </u>
Historic Functions (enter categories from instructions) DOMESTIC: single dwelling	Current Functions (enter categories from instructions) DOMESTIC: single dwelling
7. Description	
Architectural Classification enter categories from instructions)	Materials (enter categories from instructions)
OTHER: vernacular	foundation concrete walls wood composition aluminum
	roof wood, asphalt

Describe present and historic physical appearance.

Belltown is a relatively densely built rural community defined by open fields on the west and South. Commercial strip development has encroached on the north and east. Contributing resources include the following buildings.

Belltown School c. 1930 Route 9 (tax map #3-34-5-94)

Description: The Belltown School is a large one story wood framed rectangular block with a gabled roof. It is located on the north side of Route 9, west of its intersection with Delaware Route 1. The exterior walls are sheathed in cedar shingles above a rusticated CMU foundation, and the roof is covered with composite shingles. The southern slope of the roof extends further than the northern slope. The facade or southern elevation of the main block of the school consists of three bays, composed of an axial entrance and two flanking window Each window opening is filled with a rank of four 9/9 A gable roofed porch at the top of four concrete steps shelters the front entrance. The porch roof is supported on a simple architrave resting on paired battered wooden posts and pilasters applied to shingled cheek walls. The molded cornice returns on the gable end of the porch roof frame an arched Triple railings line the sides of the porch. double-leafed entrance door has nine lights in each leaf and is set in plain surrounds. The eastern and western elevations lack fenestration; a louvered wooden vent is centered in each gable. Molded cornice returns and a boxed cornice furnish the only other gable detail. Composite shingles cover the roof, where a large brick chimney rises from the center of the ridge. At the southeast corner of the building, a small one story hip roofed wing extends the facade one bay to the east. A paired window consisting of two 6/6 sash occupies the facade of the addition.

National Register of Historic Places Continuation Sheet

Section number 7 Page 2 Belltown Historic District

Edward Samuel Salters House c. 1920 115 Route 9 (tax map #3-34-5-112)

Description: The Edward Samuel Salters House is a rectangular one and a half story wood framed dwelling set on a concrete block foundation. Exterior walls are clad in metal siding, the gable roof in composite shingles. The southern elevation is a gable end that faces Route 9, forming a three bay facade. Flanking the axial sash entrance door are 6/1 sash windows. A 1/1 sash window is centered in the gable above. A one story wood framed porch on concrete block piers extends from the facade, sheltered by a hipped roof covered in composite shingles and supported on plain wood posts. Three 6/1 windows are symmetrically located on the eastern elevation, and two paired 6/1 windows on the western elevation. The exterior brick chimney rises from the northern end of the western elevation.

Edward F. Salters House early 20th c. NE corner Route 9 and Naples Street (tax map #3-34-5-113)

The Edward F. Salters House is a one and a half Description: story wood framed dwelling set on a concrete block foundation. An ell plan is formed by the gable roofed main block and a one story gable roofed rear addition which extends from the westernmost end of the northern elevation. Although the rafter ends are exposed beneath the overhanging roof of the addition, the eaves are boxed on the main block and on the front porch which extends from the three bay southern elevation or facade. The shed roofed, wood framed, screened front porch shelters the axial sash entrance door and the flanking 2/2 sash windows. On each of the east and west or gable end elevations a 2/2 sash window is centered in the peak of the gable, and a 2/2 sash window is centered on the first story below. Composite shingles clad the exterior walls of the entire house and cover the roof. The brick exterior chimney rises on the western elevation at the juncture of the main block and the rear addition.

National Register of Historic Places Continuation Sheet

Section number	Page .	3	Belltown	Historic	District
----------------	--------	---	----------	----------	----------

Clarence H. Roberts House c. 1920s 133 Route 9 (tax map #3-34-5-122)

The Clarence H. Roberts House is a one and a half Description: story rectangular gable roofed, wood framed dwelling set on a concrete block foundation. The exterior walls are covered with composite siding; the roof with composite shingles. southern gable end elevation faces Route 9 and forms a three bay facade, with an axial sash entrance door set between 1/1 sash windows. In the peak of the gable above the entrance door a 1/1 sash window lights the attic space. Above the concrete block foundation the exterior walls are clad with composite siding. An enclosed wood framed shed roofed porch extends across the southern elevation, lighted by a rank of 1/1 sash windows. the western elevation are located one single 1/1 sash window and one paired window with 1/1 sash. The eastern elevation contains three 6/6 sash windows. All window and door openings have molded trim. On the western slope of the roof a brick chimney rises, near the northern end of the ridge. Located to the northeast of the dwelling, at the end of a driveway which parallels the eastern elevation of the house stands a one story wood framed outbuilding. It has a shed roof, covered with corrugated metal, and on the south elevation, a porch roof supported by wood posts.

Daniel Jones House late 19th c. 137 Route 9, NE corner alley (tax map #3-34-5-124)

The Daniel Jones House is a two story gable Description: roofed, wood framed, ell-plan dwelling, two bays wide and two bays deep. The southern elevation or facade faces Route 9, with a one story shed roofed enclosed porch of three bays obscuring the first story of the main block. A two story, gable roofed rear ell extends from the easternmost bay of the northern elevation, with a one story addition on the western elevation of Above the CMU foundation the exterior walls are sheathed in composite shingles and metal siding; the roof has composite shingles on the main block with corrugated metal covering the roof of the rear ell. Window openings are filled with 1/1 sash in plain surrounds, except on the eastern elevation where 2/2 sash occupy the one bay of the main block first story, and on the west where a 3/1 sash window occupies the second story. A corbeled brick chimney is centered on the ridge of the main block; an exterior brick chimney is centered on the northern elevation of the ell. Located to the northeast of the dwelling is a rectangular one story wood framed shed, covered with horizontal board siding and tar paper. Its roof is covered with boards.

National Register of Historic Places Continuation Sheet

Section number7	Page _	4	Belltown	Historic	District
-----------------	--------	---	----------	----------	----------

James Paynter House c. 1920s 139 Route 9, NW corner alley (tax map #3-34-5-131)

Description: The James Paynter House is a one story wood framed rectangular dwelling with additions to the northern and southern gable end elevations. Composite shingles cover the exterior walls of the main block and the gable roofs of the main block and the southern addition, and metal cladding covers the walls of the southern addition and the flat roofed northern addition. All parts of the dwelling rest on a concrete block foundation. Fenestration consists of 6/1 sash in plain surrounds on the main block, 1/1 sash on the northern addition, and three light louvered windows on the southern addition. Facing Route 9, the southern elevation presents a five bay facade on the southern addition. It consists of an axial louvered sash entrance door set between four three light louvered windows. exterior chimney rises at the center of the eastern elevation to the south of the paired 6/1 sash windows that are centered on that elevation. Two outbuildings stand on this property, a shed The one story rectangular frame shed is sheathed and a privy. in composite shingles on the exterior walls and on the gable roof. It is located to the northeast of the dwelling on the western side of an alley which parallels the eastern elevation of the house. The gable roofed privy stands west of the shed. The privy walls are coverd with vertical board siding, its gable roof sheathed in tar paper.

William O. Duffie House c. 1920 143 Route 9 (tax map #3-34-5-133)

Description: The William O. Duffie House is a rectangular one and a half story gable roofed, wood framed dwelling. Above the concrete block foundation the exterior walls are covered with metal siding, both on the main block and on the one story gable roofed addition that extends one bay in depth from the northern elevation. The southern elevation is a gable end that faces Route 9 as the facade. A sash entrance door to the east of center and a 6/6 sash window to the west of center form the two bays of the first story. Centered in the gable above is a 6/6Three symmetrically placed 6/6 sash windows occupy the eastern and western elevations of the main block. northern addition, a sash entrance door is located on the western elevation and a 6/6 sash window on the eastern All window and door openings have plain surrounds. The overhanging gabled roof is covered in composite shingles and has metal enclosing the eaves and a brick chimney centered on the ridge. One outbuilding stands on this property, a one story wood framed rectangular shed with a gable roof. Vertical boards and composite shingles cover the walls of the shed, and composite shingles cover the roof. The shed is located to the northeast of the dwelling, with the gable end toward the street.

National Register of Historic Places Continuation Sheet

Section number _____ 7 Page __ 5 Belltown Historic District

Larry E. Jones House c. 1920 Route 9 (tax map #3-34-5-134)

The Larry E. Jones House is a rectangular one Description: story wood framed dwelling set with a gable end to the street. On the facade or southeastern elevation a hip roofed screened porch covers the three bays of the main block, an axial sash entrance door and flanking 1/1 sash windows. Above a concrete covered foundation the exterior walls are clad in metal siding, and the roof is sheathed with composite shingles. A full width addition to the northwestern elevation contains a sash entrance door on the southwestern elevation. Also on the southwestern elevation, the main block contains two 1/1 sash windows, and the screened front porch includes an entrance door. On the northeastern elevation are 3/1 sash windows and an exterior brick chimney at the northern end of the main block. Plain surrounds are used on all fenestration.

Larry E. Jones House c. 1920 147 Route 9 (tax map #3-34-5-135)

Description: The Larry E. Jones House is a one and a half story gable roofed, wood framed house with additions extending to the north from the rear elevation. The main block has a two bay facade on the southern elevation composed of a paired 6/6 sash window to the west of center and a sash entrance door to the The eastern elevation of the main block has a 6/6 sash window centered in the peak of the gable on the second story, and two 6/6 sash windows on the first story. On the western elevation of the main block, one 6/6 sash window occupies the gable peak, and one 6/6 sash window is located on the first story. Window and door openings on the main block are set in plain surrounds. Composite shingles cover the foundation, walls and roof of the main block. A one story shed roofed, wood framed addition extends the full width of the northern elevation of the main block, set on a concrete block foundation and covered with clapboarding. A one story flat roofed, wood framed addition extends across the eastern three-quarters of the northern elevation of the shed roofed addition, covered in composite shingles. One 1/1 sash window is located in the eastern elevation of each of the rear additions. A small gable roofed addition adjoins the western elevation of the shed roofed addition and extends to the north. No chimney is evident. outbuilding stands on this property, a one story rectangular wood framed shed. It is located close to the northwestern corner of the dwelling. Composite shingles cover the walls and the shed roof.

National Register of Historic Places Continuation Sheet

Section number ___ 7 Page 6 Belltown Historic District

Louis H. Tunnell House c. 1920 Route 9 (tax map #3-34-5-135.1)

Description: The Louis H. Tunnell House is a small one story, rectangular three bay, wood framed dwelling with two additions extending to the north. Resting on concrete block piers, the main block has exterior walls covered in metal cladding below an overhanging gabled roof with metal clad eaves, sheathed in The southern elevation faces Route 9 and composite shingles. forms a three bay facade composed of an axial sash entrance door between 1/1 sash windows. The eastern and western elevations or gable ends of the main block each contain a 1/1 sash window. Window and door surrounds are of molded wood. A shed roofed addition extends the width of the main block one bay to the north, and is lighted by a 1/1 sash window in the eastern elevation and a sash entrance door in the western elevation. Metal cladding covers the exterior walls of the shed roofed addition. A flat roofed addition extends the width of the shed roofed addition one more bay to the north, with walls covered in vertical board paneling and a 1/1 sash window on the eastern elevation. The exterior chimney is located on the western elevation south of the ridge of the main block and is covered with stucco. One outbuilding stands on this property, a rectangular one story, wood framed shed. It is located to the northwest of the dwelling, with plywood covering the exterior walls and composite shingles covering the shed roof. A double leaf entrance door of vertical flush boarding is centered on the southern elevation.

Martha Norwood House late 19th c. Route 9 (tax map #3-34-5-139)

Description: The Martha Norwood House is a wood framed dwelling composed of a two story gable roofed main block and a two story gable roofed rear ell, with a one story shed roofed addition filling in the space bordered by the arms of the ell. Corrigated metal stripping conceals the foundation below clapboard covered exterior walls. Composite shingles sheathe the roof slopes, where two concrete block chimneys rise from the ridge, one at the eastern end of the main block and one at the northern end of the rear ell. The southeastern elevation faces Route 9 and forms a three bay facade. On the first story of the facade a four light sash entrance door is centered between 2/2 sash windows, and the three bays of the second story consist of squared 2/2 sash windows. On the gable end elevations of the main block, facing northeast and southwest, there are no windows. On the northeastern elevation of the rear ell a 1/1 sash window occupies the second story. On the southwestern

National Register of Historic Places Continuation Sheet

Section number 7 Page 7 Belltown Historic District

elevation, a 1/X sash window and sash entrance door are located in the one story shed roofed addition. In the second story of the rear ell on the southwestern elevation is a 1/1 sash window. Doors and windows are set in plain surrounds, each with a small hood mold. A small wood framed, screened porch is located on the northeast elevation at the juncture of the main block and the rear ell. One outbuilding stands on this property, a one story rectangular wood framed shed. Located to the northwest of the dwelling, the shed has walls covered with vertical boards and a gable roof covered with corrugated metal. The door, on the eastern elevation, is constructed of vertical boards.

Beatrice Wiltbanks House c. 1930s Route 285 (tax map #3-34-5-189)

Description: The Beatrice Wiltbanks House is single story wood framed dwelling with a gabled roof and masonry foundation. Gable ends have been clipped on the side elevations. The street facade is arranged in three bays with a central door sheltered by a small porch. The porch roof also has a clipped gable end. Windows are regularly placed, each sheltered by a metal awning. Walls and roof are sheathed in composite siding.

Elsie Brittingham House c. 1930s Route 285 (tax map #3-34-5-190)

Description: The Elsie Brittingham House is a two story wood framed dwelling, two bays wide and three bays deep, with a gabled roof. Most windows are 6/1 sash. A single car garage and porch, sharing a shed roof, adjoin the street facade at its left side. An enclosed porch with a gabled roof adjoins the north elevation. A simple brick chimney rises outside the north wall of the dwelling.

Lucille I. Williams late 19th c. 136 Route 9 (tax map #3-34-5-193)

Description: The Lucille I. Williams House is a wood framed dwelling composed of a two story gable roofed main block and a two story gable roofed rear ell, to which an enclosed one story shed roofed front porch and an enclosed one story shed roofed rear porch have been added. Above the concrete block foundation the walls are clad in metal siding. Composite shingles cover all the roof slopes, and a brick chimney is centered on the ridge of the main block roof. The northwestern elevation of the main block faces Route 9 and forms a three bay facade. Above

National Register of Historic Places Continuation Sheet

Section number	7	Page	8	Belltown	Historic	District
----------------	---	------	---	----------	----------	----------

the enclosed front porch, three 2/2 sash windows are arranged symmetrically, trimmed with louvered metal shutters. facade of the enclosed porch an axial sash entrance door is flanked by three 2/2 sash windows on each side. Three 2/2 sash windows occupy both the northeastern and southwestern elevations of the enclosed porch. The northeastern elevation of the main block has one 1/1 sash window at the northern end of the first One 1/1 sash window can be seen on both the first and the second story of the rear ell. There are two 1/1 sash windows on the first story of the southwestern elevation of the main block, and one 3/6 sash window on the second story of the southwestern elevation of the rear ell. Two pairs of 2/2 sash windows and an entrance door occupy the southwestern elevation of the enclosed rear porch, which extends across the southwestern and the southeastern elevations of the rear ell. One outbuilding stands on this property, a rectangular one story, wood framed shed. The shed is located to the south of the house, at the end of a driveway which parallels the southwest elevation of the dwelling. The walls of the shed are covered with brick patterned sheathing paper, and the shed roof is covered with composite shingles.

Maull Heirs House late 19th c. Alley between Routes 9 and 285 (tax map #3-34-5-194)

The Maull Heirs House is a wood framed ell-plan dwelling composed of two gable roofed two story sections joined to form an ell, with a one story shed roofed addition filling in most of the space enclosed by the ell. No foundation is visible below the clapboard covering the exterior walls. On the southwestern elevation of the main block, which faces the alley and forms the facade, the entrance door is a modern paneled replacement with three lights. The door is located to the southeast of the center of the facade, with two 2/2 sash windows to the northwest and one 2/2 sash window to the southeast. Directly above the three first story windows are three square, two light sash windows on the second story. On the southeastern elevation, a gable end, one square two light sash window is centered in the gable above a 2/2 sash window on the first Extending the northwestern elevation of the main block to the northeast is the two story rear ell, containing 6/2 sash windows on the first story and 3/3 casement windows on the second story. The window and door openings are trimmed with plain surrounds, including the louvred windows in the one story shed roofed addition. Composite shingles cover all the slopes of the roof. Two corbeled brick chimneys rise from the ridges of the gabled roofs, one near the west end of the main block and one near the northwest end of the rear ell.

National Register of Historic Places Continuation Sheet

Section number	7	Page	9	Belltown	Historic	District
----------------	---	------	---	----------	----------	----------

Garland R. Briscoe House c. 1910 Route 285, Box 26 (tax map #3-34-5-196)

Description: The Garland R. Briscoe House is a two and a half story wood framed, hip roofed square dwelling set on a concrete block foundation. Covering the front or northwestern slope of the roof are wooden shingles; the other slopes are covered in composite shingles. A gable roofed dormer covered with clapboarding occupies the center of the northwestern slope of the roof, and a corbeled brick chimney rises from the southeastern slope near the peak. Vertical board paneling sheaths the walls both of the main block of the house and of the one story hip roofed enclosed front porch. Six 1/1 sash windows flank the front porch door. On the facade elevation of the house, the four light sash entrance door is flanked by two 5 vertical/1 sash windows, set below two 3/1 sash windows on the second story. This pattern is repeated on the southwestern elevation, where two 3/1 sash windows occupy the second story and one 5/1 sash occupies the first story. On the northeastern elevation, however, the second story windows are 1/1 and 2/2 sash while the first story window is 5/1 sash. All the windows have plain surrounds with a molding strip atop the lintels, forming a small hood mold. A second enclosed porch is located on the rear elevation and at the easternmost end of the northeastern elevation. One outbuilding stands on this property, a garage in deteriorated condition. Located to the northeast of the house and accessed by an alley which parallels the southwest elevation of the dwelling, the rectangular one story frame garage is set on concrete block piers and is covered with vertical board paneling. A gable roof is sheathed in corrugated metal.

Virginia Williams House mid 19th c. Route 285 (tax map #3-34-5-197)

Description: The Virginia Williams House is a two and a half story wood framed dwelling with a steeply pitched gabled roof and an adjoining rear wing of similar form and materials. The street facade is three bays wide with a door in the lower left side. Windows are 2/2 sash. The exterior is sheathed in claboard siding. A simple brick chimney rises inside the north wall of the main block and another inside the west wall of the wing. The building is abandoned and in poor condition.

National Register of Historic Places Continuation Sheet

Section number ____7__ Page __10 __ Belltown Historic District

William Holloman House c. 1920s Route 285 (tax map #3-34-5-198)

Description: The William Holloman House is a one and a half story wood framed dwelling, three bays wide and one bay deep, with a gabled roof. It also has a central dormer facing the street, a shed roofed enclosed porch, and several wings and additions to the rear. The exterior is sheathed in metal siding and the roof in composite shingles.

Irwin A. Coursey House c. 1920s Route 9 (tax map #3-34-5-202)

Description: The Irwin A. Coursey House is a rectangular one and a half story wood framed house with a gabled roof. Concrete block makes up the foundation, and the overhanging roof with exposed rafter ends is covered with composite shingles. northern gable end elevation faces Route 9 and forms the facade, with a shed roofed screened porch covering the three bays of the Above the front porch roof the peak of the gable is covered in clapboarding around a paired 1/1 sash window. The remaining exterior wall surface is clad in metal siding. axial screened door gives access to the front which features turned wooden posts and railings with turned wooden balusters. The axial sash entrance door to the main block is set between 1/1 sash windows. On the western elevation, two 1/1 sash windows are symmetrically placed, while four 1/1 sash windows are located on the eastern elevation. Window and door openings are set in molded surrounds. On the southern elevation, a gable roofed addition occupies the eastern half of the first story, adjoining a small screened porch on the west. A corbeled brick chimney rises from the ridge of the main block, to the north of the midpoint. One outbuilding stands on this property, a square wood frame privy. Located to the north of the dwelling, the privy walls are covered with vertical board siding and the shed roof in composite shingles.

Robert Cropper House c. 1920s Route 9 (tax map #3-34-5-204)

Description: The Robert Cropper House is a one and a half story wood framed dwelling with a gabled roof, the rectangular main block and one story rear addition forming an ell plan. Above a brick foundation the walls of the main block are covered in wood clapboarding, while unfinished plywood sheathes the walls of the addition. The overhanging gable roofs of the main block and the

National Register of Historic Places Continuation Sheet

Section number ____7 Page ___11 Belltown Historic District

addition have exposed rafter ends and are covered with composite shingles. A corbeled chimney rises from the midpoint of the ridge of the main block roof, and a second ridge chimney is centered on the roof on the rear addition. On the northern gable end elevation, which faces Route 9 and forms the facade, a shed roofed screened porch covers the three bays of the first Centered in the gable above the porch roof is a paired 1/1 sash window. An axial screen door set between turned wood posts is featured on the front porch, with an axial sash entrance door set between 1/1 sash windows in the main block The western elevation contains one three light facade within. louvered window and one 1/1 sash window in the main block. entrance door occupies the northernmost end of the western elevation of the rear addition, near the juncture with the main In the eastern elevation are located three 1/1 sash windows and one single light casement window. All the window and door openings are set in plain surrounds with molding atop the lintels to form hood molds. Two outbuildings stand on this property, a shed and a privy. The one story rectangular wood framed shed has walls and shed roof covered with corrugated metal, a sash entrance door on the eastern elevation, and 1/1 sash windows on the eastern and northern elevations. The square frame privy has plywood sheathing on the walls and composite shingles on the shed roof. Both outbuildings are located to the southwest of the dwelling.

Jeroy Carter House c. 1920s Route 9 (tax map #3-34-5-208)

Description: The Jeroy Carter House is a rectangular one story wood framed dwelling, sited with the northwestern gable and elevation facing Route 9. Corrugated metal covers the foundation below walls sheathed in both composite shingles and brick cladding. The gable roof, covered with composite roofing material, has a slight overhang. On the northwestern elevation or facade an axial sash entrance door is flanked by 1/1 sash windows below a boarded window in the peak of the gable. On the southwestern side elevation, the westernmost two-thirds of the wall is covered with composite shingle cladding and contains one 1/1 sash window. The southernmost one-third of the southwestern elevation is covered with composite brick sheathing, and contains one 1/1 sash window and an entrance door at the southernmost end. Three 1/1 sash windows are symmetrically placed in the northeastern elevation. All window and door openings are set in plain surrounds. An exterior concrete block chimney rises next to the southeastern elevation to the south of Two outbuildings stand on this property, a the roof ridge. shed covered with vertical board siding and a shed covered with clapboards. Both sheds are wood framed, rectangular and have The clapboard covered shed is located to the gable roofs.

National Register of Historic Places Continuation Sheet

Section number7_	_ Page	12	Belltown	Historic	District
------------------	--------	----	----------	----------	----------

southwest of the dwelling, and has garage doors on the northwestern elevation. The board siding covered shed is located to the southeast of the dwelling with a vertical board door at the northernmost corner of the western elevation.

Jeroy Carter House late 19th c. Route 9 (tax map #3-34-5-208.1)

Description: The Jeroy Carter House is a three bay, two and a half story wood framed block with a gabled roof. An enclosed porch with a hipped roof adjoins the street facade, while a two story wing adjoins the rear of the block. Windows are 1/1 sash, some with shutters intact. The exterior is sheathed in composite siding and roofing.

John H. Maker House mid 19th c. Route 285 (tax map #3-34-5-210)

Description: The John H. Maker House is a two story wood framed gable roofed dwelling, composed of a main block and a rear ell which together create an ell plan. Above the concrete block foundation the walls are covered with composite shingles. the overhanging roof, sheathed with composite shingles, two corbeled brick chimneys rise from the ridge: one to the southwest of center on the main block, and one at the northwest end of the rear ell. On the southeastern elevation, which faces Route 285 and forms the facade, four window openings are Two square 2/2 sash windows occupy the symmetrically placed. second story and two 1/1 sash windows occupy the first story. The four light sash entrance door is located northeast of the center of the facade. On the gable ends of the main block, sash windows are set in the peak of the gable: on the southwestern elevation, a 4/4 sash window, and on the northeastern, a 2/2sash window. The northeastern elevation of the ell has a 2/2 sash window on the first story with a 3/3 casement window on the second story. One outbuilding stands on this property, a one story square wood framed shed. Located to the north of the dwelling at the end of a driveway which parallels the northeast elevation of the house, the shed has a corrugated metal covered shed roof and walls that are sheathed in plywood.

National Register of Historic Places Continuation Sheet

Section number 7 Page 13 Belltown Historic District

Hattie Burton House late 19th c. Route 285 (tax map #3-34-5-211)

Description: The Hattie Burton House is a two story wood framed block, two bays wide and two bays deep, with a steeply pitched gabled roof. A two story wing adjoins the north wall. Windows are regularly placed 2/2 sash, flanked by shutters. The exterior is clad in clapboard siding and composite roofing.

George W. Tunnell House c. 1920s NW corner Route 285 and Church Road (tax map #3-34-5-212)

The George W. Tunnell House is a rectangular one story wood framed dwelling set on a concrete block foundation. An overhanging gable roof, sheathed in corrugated metal, shelters the exterior walls, which are covered with vertical board paneling. A one story shed roofed addition extends from the northern or rear elevation. The southern elevation is a gable end that faces the street and forms a two bay facade consisting of a paneled entrance door and a 6/6 sash window, both set in plain surrounds. On the western elevation are three 6/6 sash windows and an axial concrete block chimney, while one 6/6 window is centered on the eastern elevation. outbuildings stand on this property, a shed and a privy. rectangular wood framed shed is located to the northwest of the dwelling, the exterior walls covered with horizontal flush boarding and the shed roof with corrugated metal. entrance door occupies the northern end of the eastern elevation The walls of the rectangular wood framed privy are covered with plywood, the roof with corrugated metal. privy is located to the northeast of the dwelling.

The Paynter B. Ward House late 19th c. Route 9 (tax map #3-34-5-214)

Description: The Paynter B. Ward House is a rectangular two and a half story wood framed dwelling, three bays wide and two bays deep, with a one story shed roofed addition on the southeastern or rear elevation. Wooden clapboards cover the walls above a CMU foundation, and the overhanging gabled roof with exposed rafter ends is sheathed with composite shingles. On the northwestern elevation or facade the entrance door occupies the westernmost of the three bays, and contains one large light. Two 1/1 light sash windows are located in the two remaining bays of the first story, and three 1/1 light sash windows are arranged symmetrically on the second story. On the northeastern

National Register of Historic Places Continuation Sheet

Section	number	7	Page	14	Belltown	Historic	District
			. ~9~	<u> </u>			

elevation two similar windows are arranged on each of the first and second stories, and two small square openings ventilate the attic story. On the southwestern elevation one 1/1 light sash window appears on the second story. All window and door openings are trimmed with plain surrounds and a molding atop the lintel which forms a hood mold. At the easternmost end of the rear addition a one bay shed roofed porch shelters a rear entrance, the porch roof supported on wooden posts. A small addition extends to the west of the rear addition as well. The Paynter B. Ward House has two brick chimneys, a corbeled chimney on the ridge at the easternmost end of the main block, and a plain stack at the center of the rear addition.

John Wesley Methodist Episcopal Property mid 19th c., early 20th c. East side of Church Street (tax map #3-34-5-215)

Description: The John Wesley Methodist Episcopal Property contains a church and two houses. The church is a wood framed block raised on a masonry basement with a steeply pitched gabled roof. A smaller scaled wing adjoins the main block on the south, while a two staged entry tower with pyramidal roof adjoins the northeast corner of the block. Windows are modified lancets with art glass lights. They are regularly placed around the main block, wing, and second stage of the tower. Walls are covered with composite siding, the roof with composite shingles.

House 1 is situated near the corner of Church Street and Route 285. It is a one and a half story wood framed block with a gabled roof. A similar wing adjoins the main block on the north. A two bay facade dormer has been introduced on the street elevation, and the entire main block has been covered with wood shingles.

House 2 is situated east of House 1 and is a single story block with a shed roof. A central facade door is flanked by horizontal sash windows. The exterior is covered with similar wood shingles as House 1.

Unoccupied House c. 1920s Route 9 (tax map #3-34-5-576)

Description: The Unoccupied House is a rectangular one and a half story wood framed dwelling set on concrete block piers and covered with a gabled roof. The walls of both the main block and the one story shed roofed addition on the southeastern or rear elevation are covered with unpainted clapboards. The northwestern elevation, a gable end, faces Route 9 and forms a

National Register of Historic Places Continuation Sheet

Section number	7	Page .	15	Belltown	Historic	District
----------------	---	--------	----	----------	----------	----------

one bay facade on which a 1/1 sash window in plain surrounds is centered in the gable above an axial four light sash entrance door. Sheltering the entrance is a one story sloping porch roof supported on wooden posts and covered with corrugated metal. On the southwestern elevation of the main block are located two 4/6 light sash windows, and on the northeastern elevation is one 2/6 light sash window. No chimney is visible on the corrugated metal sheathed roof of the main block. One outbuilding stands on this property, a square wood framed outhouse with a gabled roof, the walls covered with plywood. It is located to the south of the dwelling.

Certifying official has considered the		rty in relation to other properties: statewide locally	<u>, </u>
Applicable National Register Criteria	⊠A □B □C	□ p	
Criteria Considerations (Exceptions)	□A □B □C	□D □E □F □G	
Areas of Significance (enter categoric social history	es from instructions)	Period of Significance c. 1840 - c. 1930	Significant Dates
		Cultural Affiliation N/A	
Significant Person		Architect/Builder unknown	

State significance of property, and justify criteria, criteria considerations, and areas and periods of significance noted above.

The Belltown Historic District appears to meet the Criteria for Evaluation of the National Register as an early black community in southern Delaware (Criterion A). The community has retained a great deal of social continuity since many of the families are descendents of early residents. In addition, the community has retained a relatively high level of architectural integrity, and most buildings have retained their original uses.

According to local tradition, Belltown is named for Jacob "Jigger" Bell and dates to the 1840s (Eckman 1955:494). Bell, a free black, sold parcels of land to other free blacks with the intention of creating a new community. He also donated a lot to the community, suitable for the erection of a church.

Little is known about the early history of Belltown or its Lewes and Rehoboth Hundred tax records, however, have yielded a little information about Jacob Bell. earliest Lewes and Rehoboth Hundred tax record listing Jacob Bell, a free black, was dated 1822. He apparently had no property at that time because he was assessed only a poll tax. In 1833 tax records Bell was again listed without any property. By 1836, however, he had acquired a house and a small piece of land valued at \$25. He appeared in the tax rolls in 1840, 1844, and 1848 with a house and a lot assessed each year at \$25. 1865 and 1876-1880 tax records he was listed as having a personal estate valued at \$150. Bell apparently died sometime in the late 1870s because the next tax roll, dated 1880-1884, included an assessment of \$100 for a house and lot owned by Jacob Bell's heirs.

Examination of Sussex County deed records revealed no land transactions with Jacob or Jigger Bell listed as a grantee or a grantor. The earliest document offering proof that Bell's land was actually located in present-day Belltown was the 1868 Atlas of the State of Delaware (Beers 1868).

See continuation sheet

National Register of Historic Places Continuation Sheet

Section number	8	Page_	2	Belltown	Historic	District
----------------	---	-------	---	----------	----------	----------

Title searches for four of the properties located in the vicinity of the Bell house shown on the 1868 map were undertaken. These specific properties were chosen because of their proximity to Bell's house and because they appeared to be the earliest remaining houses in Belltown as based on architectural evidence.

The John Wesley Methodist Episcopal Church is located on parcel 3-34-5-215. Included on this property are two houses that face onto Route 285. The house located at the corner of Route 285 and Church Street was determined to be one of the earliest structures still remaining in Belltown. Deed research revealed that the church purchased the property for a dollar in 1912 from Hiram R. Burton, trustee for the estate of Ruth H. Burton (Deed Book 186:65). Earlier transactions for the property are unknown.

Parcel 3-34-5-211 is located three lots west of Church Street. The house faces onto Route 285. This property is currently owned by Hattie Burton. She purchased the property from Gloria V. Brown in 1968 for one dollar (Deed Book 633:951). Brown had inherited the property from Charles Burton. In 1904 Charles Burton had acquired the property from William and Hannah Wiltbank (Deed Book 160:403). No earlier transactions for this property are known.

The third title search was conducted for parcel 3-34-5-210, which is located four lots west of Church Street. This house is currently owned by John H. Maker. Maker and his wife, Ruth, purchased the house and lot in 1985 from Elsie Johnson for \$7000 (Deed Book 1366:111). In 1983 Johnson acquired the property from Christine Maull Redding for \$5500 (Deed Book 1226:146). She had inherited the property from her son Theodore in 1979 (Will Book 91:558). Cyrus Maull, Jr. purchased the lot in 1913 from the heirs of Hannah Wiltbank (Deed Book 186:150). It remained in the Maull family for sixty years. The deed passing the property to Hannah Wiltbank was not recorded.

Parcel 3-34-5-197, located east of the alley running between Routes 9 and 285, has been owned by a member of the Johnson family since 1913 (Deed Books 1049:192; 1049:190; 931:36; Will Book 28:179). The current owner is Rose Johnson Davis of Camden, Delaware. In 1913 Rosanna Johnson purchased the property from the heirs of Orange Maull for one dollar (Deed Book 187:11). There were no transactions deeding any property to Maull. An O. Maull appeared on the 1868 Map of Lewes and Rehoboth Hundred, however, implying that the Maull's may have been Belltown residents at that early date (Beers 1868).

National Register of Historic Places Continuation Sheet

Section number .	8	Page .	3	Belltown	Historic	District
------------------	---	--------	---	----------	----------	----------

Beatrice Wiltbank, widow of Albert Wiltbank, provided some information on the earlier transactions involving the Wiltbank family (Wiltbank 1987). She related that her mother-in-law, Hannah Wiltbank, had been the local midwife for families in Belltown and the surrounding area. In many of these cases Hannah received either goods or land in lieu of money as a fee for her services. As a result, Hannah became one of the largest landowners in the Belltown community. Hannah, in turn, gave parcels of land to family members as gifts on occasions such as marriage.

The lack of land records prior to 1904 for Belltown properties is probably tied to the fact that these individuals were black. Title clerks at the Sussex County Courthouse in Georgetown indicated that they often had encountered this problem when they were conducting searches on properties owned by blacks. This pattern in Sussex County probably relates to the strength of the Democratic party in the county. The Democrats kept blacks from voting during the last quarter of the nineteenth century by keeping them off tax assessment rolls. It seems likely that if their land was officially registered in the Recorder of Deeds Office, they would have been taxed on it, thereby gaining the right to vote. Blacks were probably "discouraged" from registering their property.

Only one reference to the early Belltown church that stood on the land donated by Jacob Bell is known. Scharf, in 1881, reported that there were three "colored" churches in Lewes and Rehoboth Hundred, including one called Little Wesley (Scharf 1888:1221). He wrote that it had been built for African Methodists "many years ago, and becoming unfit for further use a new house was built in 1872." This new church, which dated to 1873 and not 1872, was named the John Wesley Methodist Episcopal Church (Zebley 1947:276). It was replaced by yet another church in 1908, this one constructed of cement blocks. This new church stood on a lot of land purchased from Hiram Burton in December 1912 (Deed Book 186:65). The church was enlarged in 1946 to its present size. The cornerstone bears the dates 1873, 1908, and 1946.

In the 1930s Works Progress Administration (WPA) fieldworkers conducted historical surveys in many states, including Delaware. Part of this research involved the collection of oral history and folklore. Their report for Delaware was published in 1955 and it contained some interesting, although unsubstantiated, information about the earlier history of Belltown (Eckman 1955:494).

National Register of Historic Places Continuation Sheet

Section number8	_ Page .	4	Belltown	Historic	District

The village became known for its "Devil-Worshippers" - a sect led by Arnsy Maull, whose voodoo art is still remembered and probably still followed to some extent, his clientele includes whites as well as Negroes for miles around. His "conjurs" had the required power, it was said, to cure a misery or kill an enemy. The Devil Worshippers had a prolonged initiation period: a neophyte had to spend seven Sundays in the woods in solitary communion with the Devil, who on the seventh Sunday took possession of his soul and gave him supernatural powers.

Arnsy Maull on his death bed repudiated this dark religion, ordering his followers, so the story goes, to get long whips and lash the air so as "to drive off the Devil and let the Lord in!" This they did all night, accompanying the cracks of the blacksnake whips with prayers, and exhortations. Arnsy's son Silas, an old man, disclaims any belief in Devil Worship but sells "charms" and "cures" made of herbs and other things.

Other information about Belltown was acquired through interviews with local residents. Ruth Maker (1987) stated that many families in the community were related to the early residents in Belltown and in many cases, more than one generation of the family still lived in the community. She indicated that in her family alone, there were four generations represented in the population.

Until recently most Belltown residents were quite poor (Maker 1987). During the first half of the twentieth century they managed to make a living by working as day laborers in nearby towns, such as Lewes, or on neighboring farms, such as the Knapp Family Farmstead (Marshall 1987). Often the families raised produce that they carried into town and sold to their employers. To supplement the produce from gardens, most residents raised pigs and chickens in their backyards (Maker 1987).

Perhaps the most prosperous period for Belltown residents was during Prohibition in the 1920s. Henry Marshall (1987) related that many Lewes residents purchased illegal liquor from Belltown families who were making moonshine somewhere in the nearby area. According to Marshall many of the homes in the area were either erected or greatly improved during this period of prosperity.

National Register of Historic Places Continuation Sheet

Section number8	Page _	5	Belltown	Historic	District
-----------------	--------	---	----------	----------	----------

Modern conveniences, such as telephones and indoor plumbing, are fairly recent additions to most Belltown homes (Maker 1987). In fact, some houses are still not equipped with indoor toilets, and residents must depend on outhouses located behind the houses.

Primary References	
Deed books, will books and Orphan Cou Sussex County Courthouse, Georgetown,	ort records are on file at the Delaware.
Lewes and Rehoboth Hundred tax record Census are on file at the Hall of Rec	ls and the United States Agricultural cords, Dover.
Beers, D. G.	
1868 Atlas of the State of Dela Philadelphia, PA.	ware. Pomeroy and Beers,
Previous documentation on file (NPS):	X See continuation sheet
preliminary determination of individual listing (36 CFR 67) has been requested previously listed in the National Register previously determined eligible by the National Register designated a National Historic Landmark recorded by Historic American Buildings Survey #	Primary location of additional data: State historic preservation office Other State agency Federal agency Local government University Other
recorded by Historic American Engineering Record #	Specify repository:
10. Geographical Data	
Acreage of property c. 19 acres	
UTM References A [18] [4β,4 5,6 0] [4,2 8,8 5,70] Zone Easting Northing C [1,8] [4β,4 32 0] [4,2 88 1,60] E 1 8 48 4 28 5 4 2 88 3 80	B 1 8 4 84 6 20 4 2 88 4 40 Zone Easting Northing D 1 8 4 84 3 60 42 88 2 40 F 1 8 4 84 1 30 42 88 3 60 See continuation sheet
Verbal Boundary Description	
The boundary of the Belltown Historic figure entitled "Belltown Area, Site	District is shown on the accompanying
-19410 Chilled Bellown Area, Site	Plan."
	See continuation sheet
Boundary Justification	Plan."
	See continuation sheet District includes all of the
Boundary Justification The boundary of the Belltown Historic properties contributing to the signif	See continuation sheet District includes all of the
Boundary Justification The boundary of the Belltown Historic properties contributing to the signif extent possible, corresponds to exist	See continuation sheet District includes all of the icance of the district and to the ing property lines. See continuation sheet
Boundary Justification The boundary of the Belltown Historic properties contributing to the signif extent possible, corresponds to exist 11. Form Prepared By name/title Evelyn M. Tidlow/Proj. Hist.;	See continuation sheet District includes all of the icance of the district and to the ing property lines. See continuation sheet Dorothy B. Templeton/Asst. Archit. His
Boundary Justification The boundary of the Belltown Historic properties contributing to the signif extent possible, corresponds to exist	See continuation sheet District includes all of the icance of the district and to the ing property lines. See continuation sheet Dorothy B. Templeton/Asst. Archit. His

9. Major Bibliographical References

National Register of Historic Places Continuation Sheet

Section number 9 Page 2 Belltown Historic District

Eckman, Jeannette

1955 Delaware: A Guide to the First State. Hastings House Publishers, New York.

Maker, Ruth

1987 Personal Communication Belltown, Delaware.

Marshall, Henry P.

1987 Personal Communication. Lewes, Delaware.

Scharf, J. Thomas


1988 History of Delaware, Volume II. L. J. Richard, Philadelphia, PA.

Wiltbank, Beatrice


1987 Personal Communication. Belltown, Delaware.

Zebley, Frank R.


1947 The Churches of Delaware. Published by the author, Wilmington.




BELLTOWN SCHOOL (BELLTOWN HISTORIC DISTRICT)
SUSSEX CO., DE
RICHARD WEBSTER
APRIL 1988
BAHP
FROM SOUTHEAST
3-34-5-94




BELLTOWN SCHOOL (BELLTOWN HISTORIC DISTRICT)
SUSSEX CO., DE
RICHARD WEBSTER
APRIL 1988
BAHP
FROM SOUTHEAST
3-34-5-94




DANIEL JONES HOUSE (BELLTOWN HISTORIC DISTRICT)
SUSSEX CO., DE
RICHARD WEBSTER
APRIL 1988
BAHP
FROM SOUTHEAST
3-34-5-124




MARTHA NORWOOD HOUSE (BELLTOWN HISTORIC DISTRICT)
SUSSEX CO., DE
RICHARD WEBSTER
APRIL 1988
BAHP
FROM NORTHEAST
3-34-5-139




LUCILLE I. WILLIAMS HOUSE (BELLTOWN HISTORIC DISTRICT)
SUSSEX CO., DE
RICHARD WEBSTER
APRIL 1988
BAHP
FROM NORTHWEST
3-34-5-193




MAULL HEIRS HOUSE (BELLTOWN HISTORIC DISTRICT)
SUSSEX CO., DE
RICHARD WEBSTER
APRIL 1988
BAHP
FROM SOUTHEAST
3-34-5-194




GARLAND R. BRISCOE HOUSE (BELLTOWN HISTORIC DISTRICT)
SUSSEX CO., DE
RICHARD WEBSTER
APRIL 1988
BAHP
FROM SOUTHEAST
3-34-5-196




VIRGINIA WILLIAMS HOUSE (BELLTOWN HISTORIC DISTRICT)
SUSSEX CO., DE
RICHARD WEBSTER
APRIL 1988
BAHP
FROM SOUTHEAST
3-34-5-197




JEROY CARTER HOUSE (BELLTOWN HISTORIC DISTRICT)
SUSSEX CO., DE
RICHARD WEBSTER
APRIL 1988
BAHP
FROM NORTHWEST
3-34-5-208.1




JOHN H. MAKER HOUSE (BELLTOWN HISTORIC DISTRICT)
SUSSEX CO., DE
RICHARD WEBSTER
APRIL 1988
BAHP
FROM SOUTH
3-34-5-210



HATTIE BURTON HOUSE (BELLTOWN HISTORIC DISTRICT)
SUSSEX CO., DE
RICHARD WEBSTER
APRIL 1988
BAHP
FROM EAST
3-34-5-211



JOHN WESLEY METHODIST CHURCH PROPERTY, HOUSE 1 (BELLTOWN HISTORIC DISTRICT)
SUSSEX CO., DE
RICHARD WEBSTER
APRIL 1988
BAHP
FROM SOUTHEAST
3-34-5-215



JOHN WESLEY METHODIST CHURCH AND GARAGE (BELLTOWN HISTORIC DISTRICT)
SUSSEX CO., DE
RICHARD WEBSTER
APRIL 1988
BAHP
FROM NORTH
3-34-5-215

CULTURAL RESOURCE SURVEY SURVEY UPDATE FORM

CRS#	S-900	

1.	HISTORIC NAME/FUNCTION: O	ikney Farmhouse/Frar	nces E.	Graves	Tenant	Farm Hor	nestead	
2.	ADDRESS/LOCATION: 17903 B	eaver Dam Road/One	mile no	rth of Ji	mtown i	Road	. _ .	
3.	CURRENT CONDITION: excelle	nt □ good ⊠	fair		poor	☐ d	emolished	
4 .	INTEGRITY: There have been no rehouse and existing outbuildings re		s to the	dwellin	g and ex	kisting out	ouildings; the	
5.	SETTING INTEGRITY: There has be integrity.	een no major alteratio	n to the	landsc	ape sett	ing; the se	etting retains	
6. I	FORMS ADDED (give number of form	s completed for each)	:					
	#: Form:	List prope	rty type	s:				
	0 CRS 2 Main Building Form							
	4 CRS 3 Secondary Building		<u>), Shed</u>	(2)				
	0 CRS 4 Archaeological Site I							
	0 CRS 5 Structure (Building-I					_		
	0 CRS 6 Structure (Land Feat	ure) Form						
	0 CRS 7 Object Form	•• <u>-</u>						
	0 CRS 8 Landscape Elements							
	1 CRS 9 Map Form 0 CRS 14 Potential District Fo	N/A					···	
7.	SURVEYOR INFORMATION:	AIII	• •					
	Surveyor name:	Bradley S. Reese			•			
	Principal Investigator name:	Gerald M. Kuncio						
	Principal Investigator signature:	Guld Man	~)				
	Organization:	Skelly and Loy, Inc.				Date:	12/2006	-

8. OTHER	NOTES OR	OBSERVATIONS:

CRS# 5-900

According to the present owner, the house was built in three or four different phases. The owner believes the original I-house section dates to before the Civil War, but the dwelling does not appear on the 1868 Beers Atlas of Delaware. It is on the 1918 USGS quadrangle map of the area. The two-story high, single-pile, three-bay wide front portion of the house that faces Beaver Dam Road dates from 1919, based on a date scratched into the foundation. Based on the skim-coated concrete block foundation, the partial-width, two-story rear ell appears to date from this time, too. The single-story porch with a shed roof that wraps around the north and east sides of the front of the house does not appear to be original. On the west side of the house is a one-story high, two-bay wide, and four-bay deep addition with a flat roof dating to 1954 (Trout, personal communication 2006). Within the last 20 years, the original cedar shingles of the roof have been replaced with asphalt shingles. Buildings that once existed adjacent to the current property on the west side of Beaver Dam Road have been demolished. This included a large barn complex with a concrete block shed and a silo. The date of demolition is estimated as 2000, and the reason for demolition is unknown.

The property was owned for much of the nineteenth century by the Rodney family, including Daniel Rodney, governor of Delaware from 1814 to 1817. It does not appear to ever have been the principal residence of any family member.

 STATE HISTORIC CON'I plan(s)): 	EXT FRAMEWORK (check	all appropriate boxes; refer to state management					
a) Time period(s)	☐ Pre-European C ☐ Paleo-Indian ☐ Archalc ☐ Woodland I ☐ Woodland II	ontact					
	 □ 1600-1750± Contact Period (Native American) □ 1630-1730± Exploration and Frontier Settlement □ 1730-1770± Intensified and Durable Occupation □ 1770-1830± Early Industrialization □ 1830-1880± Industrialization and Early Urbanization □ 1880-1940± Urbanization and Early Suburbanization □ 1940-1960± Suburbanization and Early Ex-urbanization 						
b) Geographical zone	🔯 Coastal	ninsula ninsula/Cypress Swamp ty of Wilmington)					
c) Historic period them	e(s)						
	Agriculture Forestry Trapping/Hunting Mining/Quarrying Flshing/Oystering Manufacturing Retailing/Wholesaling Finance Professional Services	Transportation and Communication Settlement Patterns and Demographic Changes Architecture, Engineering and Decorative Arts Government Religion Education Community Organizations Occupational Organizations Major Familles, Individuals and Events					



CULTURAL RESOURCE SURVEY SECONDARY BUILDING FORM

CRS#	S-900.01	

1.	ADDRESS/LOCATION: 17903 Beaver Dam Road/One mile north of Jimtown Road	
2 .	FUNCTION(S): historic Garage current Garage	
3.	YEAR BUILT: 1950 CIRCA?: ARCHITECT/BUILDER: N/A	
4.	STYLE/FLOOR PLAN: No style/Open	
5.	INTEGRITY: original site 🖾 moved 🗔	
	if moved, from where original location's CRS #	Year
	list major alterations and additions with years (if known) a. N/A b.	Aéat
6.	CURRENT CONDITION: excellent good fair	poor 🗆
7.	DESCRIPTION:	
	a. Structural system Frame	
	b. Number of stories 1	
	c. Wall coverings Vertical board	
	d. Foundation Concrete block	
	e. Roof structural system Gable coverings Asphalt openings 0	
8.	DESCRIPTION OF ELEVATIONS:	
	a. Facade: direction: S	

1) bays: 1

2) windows: 0

3) door(s): 1 - Hinged vertical board barn-style

4) other: Projecting light fixture under gable

CRS#	S-900.01
	U-300.U I

- b. Side: direction: W
 - 1) bays: 2
 - 2) windows: 1 Casement
 - 3) door(s): 0
 - 4) other: N/A
- c. Side: direction: E
 - 1) bays: 2
 - 2) windows: Not accessible
 - 3) door(s): Not accessible
 - 4) other: Not accessible
- d. Rear; direction: N
 - 1) bays: 1
 - 2) windows: 0
 - 3) door(s): 1 Hinged wood pedestrian
 - 4) other: Projecting light fixture under gable
- 9. INTERIOR (If accessible):
 - a) Floor plan Open
 - b) Partition/walls Not accessible
 - c) Finishes Not accessible
 - d) Furnishings/machinery Not accessible



CULTURAL RESOURCE SURVEY SECONDARY BUILDING FORM

4) other: Projecting light fixture under gable

CRS#	S-900.02	

1.	ADDRESS/LOCATION: 17903 Beaver Dam Road/One mile north of Jimtown Road	
2.	FUNCTION(S): historic Garage current Garage	
3.	YEAR BUILT: 1950 CIRCA?: MA ARCHITECT/BUILDER: N/A	
4.	STYLE/FLOOR PLAN: No style/Open	
5.	INTEGRITY: original site 🗵 moved 🗌	
	if moved, from where N/A original location's CRS #	<u>year</u>
	list major alterations and additions with years (if known) a. N/A b.	year
6.	CURRENT CONDITION: excellent good fair	poor 🗀
7.	DESCRIPTION:	
	a. Structural system Frame	
	b. Number of stories 1	
	c. Wall coverings Vertical board	
	d. Foundation Concrete block	
	e. Roof structural system Gable coverings Asphalt openings 0	
8.	DESCRIPTION OF ELEVATIONS:	
	a. Facade: direction: S 1) bays: 1 2) windows: 0	
	3) door(s): 1 - Overbead metal replacement	

CRS#	S-900.02
------	----------

- b. Side: direction: W
 - 1) bays: 2
 - 2) windows: Not accessible
 - 3) door(s): Not accessible
 - 4) other: Not accessible
- c. Side: direction: E
 - 1) bays: 2
 - 2) windows: Not accessible
 - 3) door(s): Not accessible
 - 4) other: Not accessible
- d. Rear: direction: N
 - 1) bays: 1
 - 2) windows: Not accessible
 - 3) door(s): Not accessible
 - 4) other: Not accessible
- 9. INTERIOR (If accessible):
 - a) Floor plan Open
 - b) Partition/walls Not accessible
 - c) Finishes Not accessible
 - d) Furnishings/machinery Not accessible



CULTURAL RESOURCE SURVEY SECONDARY BUILDING FORM

CRS#	S-900.03	
		"

1.	ADDRESS/LOCATION: 17903 Beaver Dam Road/One mile north of Jimtown Road	
2.	FUNCTION(S): historic Shed current Shed	
3.	YEAR BUILT: 1950 CIRCA?: ☑ ARCHITECT/BUILDER: N/A	
4.	STYLE/FLOOR PLAN: No style/Open	
5.	INTEGRITY: original site	year
	list major alterations and additions with years (if known) a. N/A b.	Aest
6.	CURRENT CONDITION: excellent ☐ good ☑ fair ☐	poor 🔲
7.	DESCRIPTION:	
	a. Structural system Wood frame	
	b. Number of stories 1	
	c. Wall coverings Vertical board	
	d. Foundation Concrete slab	
	e. Roof structural system Gable coverings Asphalt openings N/A	
8.	DESCRIPTION OF ELEVATIONS:	
	a. Facade: direction: N 1) bays: 1 2) windows: 0	
	3) door(s): 1 - Hinged double-door constructed of vertical board	
	4) other: Aluminum awning over doorway	

CRS# S-900.0	3	
--------------	---	--

- b. Side: direction: E
 - 1) bays: 1
 - 2) windows: 0
 - 3) door(s): 0
 - 4) other: N/A
- c. Side: direction: W
 - 1) bays: 1
 - 2) windows: 0
 - 3) door(s): 0
 - 4) other: Louvered vent below gable
- d. Rear: direction: S
 - 1) bays: 1
 - 2) windows: Not accessible
 - 3) door(s): Not accessible
 - 4) other: Not accessible
- 9. INTERIOR (If accessible):
 - a) Floor plan Open
 - b) Partition/walls Not accessible
 - c) Finishes Not accessible
 - d) Furnishings/machinery Not accessible



CULTURAL RESOURCE SURVEY SECONDARY BUILDING FORM

CRS#	S-900.04	

1.	ADDRESS/LOCATION: 17903 Beaver Dam Road/One mile north of Jimtown Road	
2.	FUNCTION(S): historic Shed current Shed	
3.	YEAR BUILT: 1950 CIRCA?: ARCHITECT/BUILDER: N/A	
4.	STYLE/FLOOR PLAN: No style/Open	
5.	INTEGRITY: original site	year
	list major alterations and additions with years (if known) a. N/A b.	year
6.	CURRENT CONDITION: excellent ☐ good ☒ fair ☐	poor 🗌
7.	DESCRIPTION:	
	a. Structural system Wood frame	
	b. Number of stories 1½	
	c. Wall coverings Vertical board and batten	
	d. Foundation Concrete slab	
	e. Roof structural system Gable coverings Asphalt openings N/A	
8.	DESCRIPTION OF ELEVATIONS:	
	a. Facade: direction: S 1) bays: 1 2) windows: 0	
	3) door(s): 2 - Lower level wood pedestrian door and upper level wood access door	
	4) other: N/A	

CRS#	S-900.04
------	----------

- b. Side: direction: W
 - 1) bays: 1
 - 2) windows: 0
 - 3) door(s): 0
 - 4) other: N/A
- c. Side; direction: E
 - 1) bays: 1
 - 2) windows: 0
 - 3) door(s): 0
 - 4) other: N/A
- d. Rear: direction: N
 - 1) bays: 1
 - 2) windows: Not accessible
 - 3) door(s): Not accessible
 - 4) other: Not accessible
- 9. INTERIOR (If accessible):
 - a) Floor plan Open
 - b) Partition/walls Not accessible
 - c) Finishes Not accessible
 - d) Furnishings/machinery Not accessible

A DESIGNATION OF THE PROPERTY OF THE PROPERTY

DELAWARE STATE HISTORIC PRESERVATION OFFICE 15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY MAP FORM

CRS#	S-900	
ヘビク #	3-800	


1.	ADDRESS/LOCATION:	17903	Beaver Da	am Road/One mile north of Jimtown Road
2.	NOT FOR PUBLICATION		reason:	
	LOCATION MAD.			

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN	
• • • • • • • • • • • • • • • • • • •	::::::::::::::::::::::::::::::::::::::
	· · · · · · • • • • · · · · · · · · · ·
	* * * * * * * * * *
 	
Garage .02	. Shed .03
	• • • • • • •
Garage 01	
MIN O WA	
	• • • • • • • • •
· · · · · · · · · · · · · · · · · ·	• • • • • • • •
	House
[· · · · · · · · · · · · · · · · · · ·	
W W W	
[• • • • • • • •
	* * * * * * * *

DELAWARE STATE HISTORIC PRESERVATION OFFICE

PHOTOGRAPHIC INVENTORY

RS # S-900 Date 12/2005 Photo Roll # C-4627 Surveyor Bradley S. Reese

escription:

■-4627:1 Garage A, N and W elevations, facing SE; C-4627:2 House, E (rear) and N elevations, facing SW; C-4627:3 Shed A, N and W elevations, facing SE; C-4627:4 Shed B, W and S elevations, facing S; C-4627:5 ■arages A and B, S (front) elevation, facing NE; C-4627:6 House, W (front) and S elevations, facing NE

Negative location (if other than SHPO) Skelly and Loy, Inc.

ttach contact print(s):











doc # 20-06-01-05-12

CRS-13

DELAWARE STATE HISTORIC PRESERVATION OFFICE

PHOTOGRAPHIC INVENTORY

RS # S-900 Date 4/2006 Photo Roll # C-4616 Surveyor Gerald M. Kuncio

escription:

-4616:6 - Façade and S side, facing NE; C-4616:7 - Façade and N side, facing SE. The portion at the rear

may be the original part of the building.

legative location (if other than SHPO) Skelly and Loy, Inc.

kttach contact print(s):





oc # 20-06-01-05-12

CRS-13

CULTURAL RESOURCE SURVEY LOCUS IDENTIFICATION FORM

DELAWARE BUREAU OF ARCHAEDLOGY AND HISTORIC PRESERVATION HALL OF RECORDS DOVER, DELAWARE 19901 (302) 678-5314



FORM CRS-2


FOR OFFICE USE ONLY

CRS # Quad SPO map # Hundred DOCUMENT

	OWNER'S NAME: Hances & Haures TEL. #
	ADDRESS: June D.C. 19958
	TYPE OF LOCUS: a) structure b) district c) archaeological sit
	d) other
	SURROUNDINGS OF LOCUS: (check more than one if necessary)
	a) fallow field b) cultivated field $$ c) woodland $$
	d) scattered buildings $\sqrt{}$ e) densely built up $\overline{}$ f) other $\overline{}$
,	THREATS TO LOCUS
	a) none know: b) zoning c) roads d) developers
	e) deterioration f) other
	REPRESENTATION ON OTHER SURVEYS:
	TITLE:
	TITLE:
	TITLE:
	YOUR NAME:

USE BLACK INK ONLY

700



CULTURAL RESOURCE SURVEY STRUCTURAL DATA FORM

DELAWARE BUREAU OF ARCHAEOLOGY AND HISTORIC PRESERVATION HALL OF RECORDS DOVER, DELAWARE 19901 (302) 678-5314



Form CRS-1 FOR OFFICE USE ONLY

CRS # Quad .. Fairmount. SPO map # 18-19-11 Hundred 20-06/78/09/14 DOCUMEN'T

forest "

SKETCH PLAN

1. ADDRESS OF STRUCTURE :

- 2. DESCRIBE THE STRUCTURE AS COMPLETELY AS POSSIBLE:
 - a) Overall shape "L" shape o main house stories two stender bays main raise. Stan facacle
 wings 2 stang gave winds on sicle - as here;
 by structural system

 b) Structural system

 Alathory

 - c) Foundation materials concrete block + stoken powered bousement basement
 - Exterior walls materials modern aluminum siding color(s) white
 - Covered un mosel stungles e) Roof shape: materials on the lear to + flat reds cornice simple closel comice - covered up aluminum siding dormers chimney Tocation(s) buck chimney on north interior quite and of north side union buck chimney on surem in the follows
 - f) Windows spacing symmetrical type double hung sashes - 2/2 lites modern additions has trim suites of 9/1 dentes, 4 lite square casements shutters simple flat him covered of aluminum.
 - spacing lite has vestilited of the property which wood of the traped type panes; each and of hear guild wing has which work from one trim partled bottom, as do send to has word down up if let book one trim partled bottom, as do send that ; flat noofel addition has white wood friend door g) Door
 - h) Porches n) Porches

 location(s) Sungle-tree learn to porch goes across all of focuses to materials around in routh gates and to side using in the decide the supports from decorative source and connect to molder to trim however by setting for 3 spilors port by sence type to however of learn to decide to south and south and search at south and of learn to decide in forther by denible and it interior details (if accessible) like those in forther to scarces.

USE BLACK INK ONLY

	-1			
3.	CONDITION:	go od	deteriorated	
	remark	S:		
4.	INTEGRITY:	a) original site	b) moved	
		c) if moved, when and	from where	F 4
		d) list major alteration	ons and dates (if known)	
5.	DATE OF INI	TIAL CONSTRUCTION:	!	
6.	ARCHITECT/8	OTLDER:		
7.	RELATED OUT	_		
	a) bar	n 🗸 b) carriage hous	e c) garage 📈 d) privy	
	e) she	ed 🏒 f) greenhouse _	g) shop h) gardens	
	i) ice	house j) springhou	sek) other	
8.	BRIEFLY OIS ASSOCIATION The factories of the control of the cont	La Count + batter of the County of the County + batter of the County + batter of the County of the C	monety been foundations broad with words and broad would be to be the foundation beautiful words and board of the structure. Note of Persons: And board words to be the decree of the STRUCTURE. NOTE of PERSONS: And to word wood shared government would be the foundation of the foun	ANY Rest board ANY Rest on a second of the second of th
		side almes.	in the original, main notice	
			•	
1	o: Surveyor	(Alle Haters	Date of Forms	ı <i>al</i> ın
ing see in		O Presidential	LACK THE ONLY	
(ૡહેર્ફ્ટર્સ્ટ 2000 - 20	<u> 1666 j. 37 september 1999</u> 37 milijar - Herrich J. 1890 j. 1			

PHOTOGRAPHIC INVENTORY

BUREAU OF ARCHAEOLOGY AND HISTORIC PRESERVATION Document 20-06/79/01/11

CRS Number			# C-809 (.01)
Location Attach co			
		(Laurente	

DELAWARE STATE HISTORIC PRESERVATION OFFICE 15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY SURVEY UPDATE FORM

CRS#	S-898	

				•		
ı.	HISTORIC NAME/FUNCTION: N	orwood-Jackso	on Farm/Ag	ricultural Co	omplex	
2.	ADDRESS/LOCATION: 19961 B Jimtown	•	Inpaved dri	veway east	of Beaver Dam	Road, north of
3.	CURRENT CONDITION: excelle	nt 🗌 god	od 🛚	fair 🔲	poor 🗌	demolished 🔲
4.	INTEGRITY: There have been no and outbuildings retain integrity.	major alteratio	ns to the ex	kisting dwell	ing and outbuil	dings; the house
5.	SETTING INTEGRITY: There has be integrity.	peen no major	alteration t	o the landso	cape setting; th	e setting retains
6. F	FORMS ADDED (give number of form	ns completed 1	for each):			
	#; Form:	Li	ist property	types:		
	0 CRS 2 Main Building Form					
	8 CRS 3 Secondary Building	Form C	oop, Bam ((2), Storage	Shed (3), Gree	enhouse, Workshop
	0 CRS 4 Archaeological Site					<u>-</u>
	0 CRS 5 Structure (Building-					
	0 CRS 6 Structure (Land Fea 0 CRS 7 Object Form	ture) Form				
	0 CRS 7 Object Form 0 CRS 8 Landscape Element:	Form				
	1 CRS 9 Map Form		/A	•	•	
	0 CRS 14 Potential District F					• •
7.	SURVEYOR INFORMATION:					
	Surveyor name:	Gerald M. K	uncio			
	Principal investigator name:	Gerald M. K	uncio			
	Principal Investigator signature:	Hei	DMZ	ance	2	
	Organization:	Skelly and L	oy, Inc.		Da	te: <u>12/2005</u>
doc	# 20-01-00-05-02	USE BLACK	INK ONLY			crs-10

OTHER NOTES OR OBSE	RVATIONS:	CRS#	S-89 8
The construction dates occupied the residence	for the buildings on the prosince 1963. Where possib	operty were provided by the property's le, dates were confirmed using aerial p	owner, who has hotography.
The house dates to ca.	1905. The dates for the ou	itbuildings are provided on the forms.	
. STATE HISTORIC CONT lan(s)):	EXT FRAMEWORK (check a	ill appropriate boxes; refer to state man	agement
a) Time perlod(s)	Pre-European Co Paleo-Indian Archaic Woodland I Woodland II	ntact	
	1600-1750± Contact Period 1630-1730± Exploration an 1730-1770± Intensified and 1770-1830± Early Industria 1830-1880± Industrializatio 1880-1940± Urbanization a 1940-1960± Suburbanizatio	d Frontier Settlement I Durable Occupation Ilization on and Early Urbanization	
b) Geographical zone	🖂 Coastal	insula insula/Cypress Swamp y of Wilmington)	
c) Historic period them	e(s)		
	Agriculture Forestry Trapping/Hunting Mining/Quarrying Fishing/Oystering Manufacturing Retailing/Wholesaling Finance Professional Services	 □ Transportation and Communication □ Settlement Patterns and Demograph □ Architecture, Engineering and Decomposition □ Religion □ Education □ Community Organizations □ Occupational Organizations □ Major Families, Individuals and Eventual 	phic Changes orative Arts

8. OTHER NOTES OR OBSERVATIONS:



CULTURAL RESOURCE SURVEY SECONDARY BUILDING FORM

CRS#	S-898.01	

1. ADDRESS/LOCATION: 19961 Bee Jay Lane/Unpaved driveway E of Beaver Dam Road, N of Jimto		
2.	FUNCTION(S): historic Chicken Coop current Vacant	-
3.	YEAR BUILT: 1975 CIRCA?: MARCHITECT/BUILDER: N/A	
4.	STYLE/FLOOR PLAN: No style/Open	_
5.	INTEGRITY: original site 🗵 moved 🗌	
	if moved, from where original location's CR\$ #	<u>year</u>
	list major alterations and additions with years (If known) a. N/A b.	year
6.	CURRENT CONDITION: excellent ☐ good ☑ fair ☐	poor 🗌
7.	DESCRIPTION:	
	a. Structural system Wood frame	
	b. Number of stories 1	
	c. Wall coverings Standing seam metal and asbestos sheeting	
	d. Foundation Concrete slab	
	e. Roof structural system Gable coverings Asphalt openings N/A	
8.	DESCRIPTION OF ELEVATIONS:	
	a. Facade: direction: W 1) bays: 1 2) windows: 0	
	3) door(s): 1 - Hinged door constructed of vertical boards	
	4) other: N/A	

CR\$	#	S-898.01
	**	3-030.U I

		CRS# S-898
þ.		: direction: E
		bays: 1 windows: 1 – 3-light, top-hinged covered with plastic sheeting and chicken wire
		door(s): 1 - Small square access door below window
	-	
	4)	other: N/A
Ç.	Side	; direction: N
	1) 2)	bays: 1 windows: 1 – 3-light, top-hinged covered with plastic sheeting and chicken wire
	3)	door(s): 0
	4)	other: N/A
d.		r: direction: S
	1) 2)	bays: 1 windows: 1 – 3-light, top-hinged covered with plastic sheeting and chicken wire
	3)	door(s): 0
	4)	other: N/A
****		//#
		(if accessible):
a) Flo	or pl	lan Open
h\ Do	ماداد.	n/walls None
D) F8	uuo	INMOND ITOMO
c) Fir	nishe	s Exposed wood frame

d) Furnishings/machinery None



CULTURAL RESOURCE SURVEY SECONDARY BUILDING FORM

CRS#	S-898.02	

1.	. ADDRESS/LOCATION: 19961 Bee Jay Lane/Unpaved driveway E of Beaver Dam Road, N of Jimto		
2 .	FUNCTION(S): historic Storage Shed current Storage Shed/Kennel		
3.	YEAR BUILT: 1956 CIRCA?: ☑ ARCHITECT/BUILDER: N/A		
4.	STYLE/FLOOR PLAN: _No style/Open		
5.	INTEGRITY: original site ⊠ moved □		
	if moved, from where N/A original location's CRS#	<u>vear</u>	
	list major alterations and additions with years (if known) a. N/A b.	year	
6.	CURRENT CONDITION: excellent ☐ good ☑ fair ☐	poor 🗌	
7.	DESCRIPTION:		
	a. Structural system Wood frame		
	b. Number of stories 1		
	c. Wall coverings Vertical wood board		
	d. Foundation Concrete block piers		
	e. Roof structural system Gable end coverings Metal openings N/A		
8.	DESCRIPTION OF ELEVATIONS:		
	a. Facade: direction: N 1) bays: 1 2) windows: 0		
	3) door(s): 1 - Hinged double door constructed of vertical board		
	4) other: N/A		

- b. Side: direction: E
 - 1) bays: 1
 - 2) windows: 0
 - 3) door(s): 0
 - 4) other: N/A
- c. Side: direction: W
 - 1) bays: 1
 - 2) windows: 1 1/1 metal frame fixed
 - 3) door(s): 0
 - 4) other: N/A
- d. Rear: direction: S
 - 1) bays: 1
 - 2) windows: 1 1/1 metal frame fixed
 - 3) door(s): 0
 - 4) other: N/A
- 9. INTERIOR (If accessible):
 - a) Floor plan Open
 - b) Partition/walls None
 - c) Finishes Exposed wood frame
 - d) Furnishings/machinery None



CULTURAL RESOURCE SURVEY SECONDARY BUILDING FORM

CRS#	S-898.03	
------	----------	--

2. 3.	FUNCTION(S): historic Barn current Barn YEAR BUILT: 1940 CIRCA?: ☑ ARCHITECT/BUILDER: N/A STYLE/FLOOR PLAN: Vernacular	
3.	STYLE/FLOOR PLAN: Vernacular	
		,
4.		
5.	INTEGRITY: original site 🖾 moved 🔲	
	if moved, from where original location's CRS #	Year
	list major alterations and additions with years (if known) a. N/A b.	year
6.	CURRENT CONDITION: excellent good fair	poor 🗔
7.	DESCRIPTION:	
	a. Structural system Wood frame	
	b. Number of stories 2	
	c. Wall coverings Vertical board, board and batten	
	d. Foundation Concrete slab	
	e. Roof structural system Gable coverings Standing seam metal openings N/A	
8.	DESCRIPTION OF ELEVATIONS:	
	a. Facade: direction: W 1) bays: 3 2) windows: 0	
	3) door(s): 1 - Hinged barn door	

4) other: N/A

CRS#	S-898.03	
------	----------	--

- b. Side: direction: N
 1) bays: 2
 2) windows: 0
 - 3) door(s): 1 Hinged wood pedestrian
 - 4) other: N/A
- c. Side: direction: S
 1) bays: 2
 2) windows: 0
 - 3) door(s): 2 Upper level hay access door and lower level pedestrian door; both are made of vertical wood board
 - 4) other: N/A
- d. Rear; direction: E
 - 1) bays: 3 2) windows: 0
 - 3) door(s): 2 Upper level hay access door and lower level pedestrian door; both are made of vertical wood board
 - 4) other: N/A
- 9. INTERIOR (if accessible):
 - a) Floor plan Not accessible
 - b) Partition/walls Not accessible
 - c) Finishes Not accessible
 - d) Furnishings/machinery Not accessible



CULTURAL RESOURCE SURVEY SECONDARY BUILDING FORM

CRS#	S-898.04	

1.	ADDRESS/LOCATION: 19961 Bee Jay Lane/Unpaved driveway E of Beaver Dam Road, N of J	imtown
2.	FUNCTION(S): historic Carriage Barn current Barn and Carport	
3.	YEAR BUILT: 1905 CIRCA?: X ARCHITECT/BUILDER: N/A	
4.	STYLE/FLOOR PLAN: Vernacular	
5.	INTEGRITY: original site	year
	list major alterations and additions with years (if known) a. N/A b.	year
6 .	CURRENT CONDITION: excellent ☐ good ☐ fair ☑	poor 🗌
7.	DESCRIPTION:	
	a. Structural system Wood frame	
	b. Number of stories 1½	
	c. Wall coverings Vertical board	
	d. Foundation Concrete piers	
	e. Roof structural system Gable with engaged shed roof on both sides coverings Corrugated metal openings N/A	
8.	DESCRIPTION OF ELEVATIONS:	
	a. Facade; direction: S 1) bays: 3 2) windows: 0	
	3) door(s): 2 - Upper and lower level access doors constructed of vertical boards	

4) other: 2 - Carriage bays on either side of main block

CRS# S-898.04

- b. Side: direction: W
 - 1) bays: 2
 - 2) windows: 0
 - 3) door(s): 0
 - 4) other: Replacement vertical wood board on sections of wall
- c. Side; direction: E
 - 1) bays: 2
 - 2) windows: 0
 - 3) door(s): 0
 - 4) other: N/A
- d. Rear: direction: N
 - 1) bays: 3
 - 2) windows: 1 covered
 - 3) door(s): 0
 - 4) other: N/A
- 9. INTERIOR (if accessible):
 - a) Floor plan Open
 - b) Partition/walls The main block is enclosed and the space is separated from the carriage bays.
 - c) Finishes Exposed wood frame
 - d) Furnishings/machinery The main block was not accessible; the west carriage bay contained various pieces of farming equipment.



CULTURAL RESOURCE SURVEY SECONDARY BUILDING FORM

CRS#	S-898.05	

1.	ADDRESS/LOCATION: 19961 Bee Jay Lane/Unpaved driveway E of Beaver Dam Road, N of J	imtown
2.	FUNCTION(S): historic Milkhouse current Concrete Block Shed	
3.	YEAR BUILT: 1956 CIRCA?: ARCHITECT/BUILDER: N/A	
4.	STYLE/FLOOR PLAN: Utilitarian	
5.	INTEGRITY: original site 🗵 moved 🗌	
	if moved, from where original location's CRS #	<u>year</u>
	list major alterations and additions with years (if known) a. N/A b.	year
6.	CURRENT CONDITION: excellent ☐ good ☐ fair ☑	poor 🗌
7.	DESCRIPTION:	
	a. Structural system Concrete block	
	b. Number of stories 1	
	c. Wall coverings Concrete block and asbestos shingles below gables	
	d. Foundation Concrete block	
	e. Roof structural system Gable coverings Asphalt openings Louvered vents below gables	
8.	DESCRIPTION OF ELEVATIONS:	
	 a. Facade: direction: S 1) bays: 1 2) windows: 1 – 4-light fixed metal pane right of center 3) door(s): 1 - Sliding wood 	

CRS#	S-898.05
	0-080.0 3

- b. Side: direction: W
 - 1) bays: 2
 - 2) windows: 2 4-light fixed metal pane
 - 3) door(s): 0
 - 4) other: N/A
- c. Side: direction: E
 - 1) bays: 2
 - 2) windows: 2 Paired 4-light fixed metal pane left of center
 - 3) door(s): 1 Sliding wood
 - 4) other: N/A
- d. Rear: direction: N
 - 1) bays: 1
 - 2) windows: 1 4-light fixed metal pane at center
 - 3) door(s): 0
 - 4) other: N/A
- 9. INTERIOR (if accessible):
 - a) Floor plan Open
 - b) Partition/walls Not accessible
 - c) Finishes Exposed concrete block
 - d) Furnishings/machinery Not accessible



CULTURAL RESOURCE SURVEY SECONDARY BUILDING FORM

CRS#	\$-898.06	

1.	ADDRESS/LOCATION: 19961 Bee Jay Lane/Unpaved driveway E of Beaver Dam Road, N of Ji	mtown
2.	FUNCTION(S): historic Workshop/Storage Shed current Workshop/Storage Sh	ed
3.	YEAR BUILT: 1956 CIRCA7: X ARCHITECT/BUILDER: N/A	
4.	STYLE/FLOOR PLAN: _Vemacular	
5.	INTEGRITY: original site 🗵 moved 🗌	
	If moved, from where original location's CR\$ #	
	list major alterations and additions with years (if known) a. N/A b.	year
6.	CURRENT CONDITION: excellent good fair	poor 🗌
7.	DESCRIPTION:	
	a. Structural system Wood frame	
	b. Number of stories 1	
	c. Wall coverings Vertical board	
	d. Foundation Concrete block	
	e. Roof structural system Gable coverings Corrugated metal sheeting openings N/A	
8.	DESCRIPTION OF ELEVATIONS:	
	a. Facade: direction: S 1) bays: 1 2) windows: 0	
	3) door(s): 1 - Double-leaf wood	

CRS# 9	-898.06
--------	---------

- b. Side: direction: W
 - 1) bays: 5
 - 2) windows: 3 1/1 metal replacement
 - 3) door(s): 1 Wood pedestrian door near west end
 - 4) other: N/A
- c. Side: direction: E
 - 1) bays: 5
 - 2) windows: 6 9-light wood sash
 - 3) door(s): 1 Sliding wood near west end
 - 4) other: N/A
- d. Rear: direction: N
 - 1) bays: 1
 - 2) windows: 0
 - 3) door(s): 1 Sliding wood
 - 4) other; N/A
- 9. INTERIOR (if accessible):
 - a) Floor plan Open
 - b) Partition/walls Not accessible
 - c) Finishes Not accessible
 - d) Furnishings/machinery Not accessible



CULTURAL RESOURCE SURVEY SECONDARY BUILDING FORM

CRS#	S-898.07

1.	ADDRESS/LOCATION: 19961 Bee Jay Lane/Unpaved driveway E of Beaver Dam Road, N of Ji	mtown_
2.	FUNCTION(S): historic Barn current Metal Barn	
3.	YEAR BUILT: 1975 CIRCA?: ARCHITECT/BUILDER: N/A	
4.	STYLE/FLOOR PLAN: Vernacular	
5.	INTEGRITY: original site	<u>year</u>
	Ilst major alterations and additions with years (if known) a. N/A b.	<u> үеаг</u>
6.	CURRENT CONDITION: excellent ☐ good ☑ fair ☐	poor 🔲
7 .	DESCRIPTION:	
	a. Structural system Wood frame	
	b. Number of stories 2	
	c. Wall coverings Standing seam metal and vertical board	
	d. Foundation Wood sills	
	e. Roof structural system Saltbox coverings Metal sheeting openings N/A	
8.	DESCRIPTION OF ELEVATIONS:	
	a. Facade: direction: S 1) bays: 4 2) windows: 0	
	3) door(s): 3 - Large metal hangar-style doors	

CRS#	S-898.07
------	----------

- b. Side: direction: W
 - 1) bays: 4
 - 2) windows: 0
 - 3) door(s): 1 Hinged wood pedestrian
 - 4) other: N/A
- c. Side: direction: E
 - 1) bays: 4
 - 2) windows: 0
 - 3) door(s): 0
 - 4) other: N/A
- d. Rear: direction: N
 - 1) bays: 4
 - 2) windows: 0
 - 3) door(s): 0
 - 4) other: N/A
- 9. INTERIOR (if accessible):
 - a) Floor plan Not accessible
 - b) Partition/walls Not accessible
 - c) Finishes Not accessible
 - d) Furnishings/machinery Not accessible



CULTURAL RESOURCE SURVEY SECONDARY BUILDING FORM

CRS#	S-898.08	

1.	ADDRESS/LOCATION: 19961 Bee Jay Lane/Unpaved driveway E of Beaver Dam Roa	d, N of Jimtown
2.	FUNCTION(S): historic Greenhouse current Greenhouse	
3.	YEAR BUILT: 1995 CIRCA?: ARCHITECT/BUILDER: N/A	·
4.	STYLE/FLOOR PLAN: No style/Open	
5.		s CRS# year
	if moved, from where original location's N/A	, CRS# year
	list major alterations and additions with years (if known) a. N/A b.	year
6.	CURRENT CONDITION: excellent good fair	boot 🗆
7.	DESCRIPTION:	
	a. Structural system Wood frame	
	b. Number of stories 1	
	c. Wall coverings Vertical board	
	d. Foundation Concrete slab	
	e. Roof structural system Gable coverings Translucent plastic sheeting openings N/A	
8.	. DESCRIPTION OF ELEVATIONS:	
	 a. Facade: direction: W 1) bays: 1 2) windows: 1 - Double-hung metal sash in door 	
	3) door(s): 1 - Hinged door constructed of vertical board	
	4) other: N/A	

CRS#	S-898.0 8	

- b. Side: direction: N
 - 1) bays: 1
 - 2) windows: 3 Double-hung metal sash
 - 3) door(s): 0
 - 4) other: N/A
- c. Side: direction: S
 - 1) bays: 1
 - 2) windows: 3 Double-hung metal sash
 - 3) door(s): 0
 - 4) other: N/A
- d. Rear: direction: E
 - 1) bays: 1
 - 2) windows: 3 Double-hung metal sash
 - 3) door(s): 0
 - 4) other: N/A
- 9. INTERIOR (if accessible):
 - a) Floor plan Open
 - b) Partition/walls None
 - c) Finishes Exposed wood frame
 - d) Furnishings/machinery Plant life


CULTURAL RESOURCE SURVEY MAP FORM

CRS#	S-898	

1.	ADDRESS/LOCATION:	19961	Bee Jay La	ane/Unpaved driveway E of Beaver <u>Dam Road, N of Jimtown</u>
	-			- · · · · · · · · · · · · · · · · · · ·
2.	NOT FOR PUBLICATION		reason:	
		_		
3.	LOCATION MAP:			

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)



. Shed Kennel

DELAWARE STATE HISTORIC PRESERVATION OFFICE

PHOTOGRAPHIC INVENTORY

RS# S-898 Photo Roll # C-4629 Surveyor Bradley S. Reese 12/2005 Date

Description: C-4629:12 House, N and W (front) elevations, facing SE; C-4629:13 House, W (front) and S elevations, facing NE; C-4629;14 House, S and E (rear) elevations, facing NW; C-4629:15 Chicken coop (.01), N and W (front) elevations, acing SE; C-4629:16 Storage shed (.02), W and S (rear) elevations, facing NE; C-4629:17 Barn (.03), S and E rear) elevations, facing NW

Negative location (if other than SHPO)

Skelly and Loy, Inc.

Attach contact print(s):













doc # 20-06-01-05-12

DELAWARE STATE HISTORIC PRESERVATION OFFICE

PHOTOGRAPHIC INVENTORY

Bradley S. Reese S-898 Date 12/2005 Photo Roll # C-4629 Surveyor

Description:

:-4629:18 House, E (rear) and N elevations, facing SW; C-4629:19 Carriage barn (.04), S (front) and E elevations, facing NW; C-4629;20 Milkhouse (.05, left) and workshop/storage shed (.06, right), S (front) and E elevations, picing NW; C-4629:21 Barn (.07), W and S (front) elevations, facing NE; C-4629:22 Greenhouse (.08), W and S front) elevations, facing NE; C-4629:23 Workshop/storage shed (.06) and milkhouse (.05), N (rear) and W elevations, facing SE; C-4629:24 Carriage barn (.04) and barn (.03), N and W elevations, facing SE Skelly and Loy, Inc. Negative location (if other than SHPO)

Attach contact print(s):














CULTURAL RESOURCE SURVEY LOCUS IDENTIFICATION FORM

DELAWARE BUREAU OF ARCHALOLOGY AND HISTORIC PRESERVATION HALL OF RECORDS DOVER: DELAWARE 19901 (302) 678-5314



FORM CRS-2


FOR OFFICE USE GALY


CRS # 5-898 Quad Formation + SPO map # 18 PC 10 Hundred July 1112 DOCUMENT 20-05/.8/04/7

1. HAME OF LOCUS: BACK 175- TOKOOP 3-24-5
2. STREET LOCATION: down dut lane from Rs. 285 - Northogonaction 14 Pt 2851
3. OWNER'S NAME: Continuo on O Binateasting One
ADDRESS: PO POR 647 ATPAINTA LA 3030
4. TYPE OF LOCUS: a) structure V b) district c) archaeological site
d) other
s SURROUNDINGS OF LOCUS: (check more than one if newssary)
a) fallow field b) cultivated field V c) woodland
d) scattered buildings _/ e) densely built upf) other
6. THREATS TO LOCUS: (check move than one if necessary)
a) none known / b) zoningc) roadsd) developers
e) deterioration f) other
7. REPRESENTATION ON OTHER SURVEYS:
11716
TIME:
B. YOUR NAME: Que Hasters TE: "
YOUR ADDRESS: Sualer County Co
ORGANIZATION (If any) Assi Programices Placeacos DATE: "CLIBIA!"

USE-BLACK, THE ONLY

i de la companya de la la companya de la companya





	ner i de apolitique de la composition de la composition de la composition de la composition de la composition La composition de la	ai rug
	S CONDITION: good 4	
	A INTEGRITY: (a) original site (b) moved	
	c)» iramoved, tiwhon and from whore the state of the stat	
		ia unmer
	6. ARCHLITECT/BUILDER:	
	RELATED COUTBUILDINGS:	
	b) carriage house c) garage d) privy	
	e) shedf) greenhouseg) shop:h) igairdens i)) icehousej) springhousek) other	
	describe @ style mod speeds greater by me and trock to rest should be a second to the second	
	BETTERLY DISCUSS THE ORIGINAL AND SUBSEQUENT USES OF THE STRUCTURE HOTE AND	
	BRIEFLY DISCUSS THE ORIGINAL AND SUBSEQUENT USES OF THE ORIGINAL AND SUBSEQUENT USES OF THE ORIGINAL AND SUBSEQUENT USES OF THE ORIGINAL AND SUBSEQUENT OF THE ORIGINAL AND SUBSECUENT OF	
	Serves most to the many many many many many many many many	
	1	
	Primary Belgerons and the second seco	
	Company of the contract of the ball place of the ball place of the contract of	
	The state of the s	ellija".i
popr de parties de la companya de la	Total Surveyorie Callicate Stores Care Care Care Care Care Care Care Care	Appliatore and
	The state of the s	
	The state of the second and the seco	iales H

Bildailts.	PROPERTY IDENT					Le R∈ Fa	-19-11 wes and choboth dirmount arlous
HISTO	ORIC NAME/FUNCTION:	Jimtown Potential Historic D	istrict/A	rican Ar	nericar	Cor	nmunity
ADDF	RESS/LOCATION:Jimtov	vn and Beaver Dam Roads/	South of	the Five	Points	inte	rsection
TOW	N/NEAREST TOWN: Lewe	es					vicinity?
MAIN	TYPE OF RESOURCE:	• —	ucture listrict		site		object
MAIN	FUNCTION OF PROPERT	r: Residential					
	IECT TITLE/ REASON FOR tern Parkway Project (Sect	, , ,		•			
	ONAL FORMS USED:						
#:	Form:	List property	types:				
#:	Form: CRS 2 Main Building For	m	types:	··· · · · · · · · · · · · · · · · · ·			
#: 0 0	Form: CRS 2 Main Building For CRS 3 Secondary Buildin	m ig Form	types:		-		
#: 0 0	Form: CRS 2 Main Building For CRS 3 Secondary Buildir CRS 4 Archaeological Sit	m ng Form re Form	types:				
#: 0 0 0	Form: CRS 2 Main Building For CRS 3 Secondary Buildin CRS 4 Archaeological Sit CRS 5 Structure (Buildin	m ng Form e Form g-Like) Form	types:				
#: 0 0 0 0	Form: CRS 2 Main Building For CRS 3 Secondary Buildin CRS 4 Archaeological Sit CRS 5 Structure (Buildin CRS 6 Structure (Land Fo	m ng Form e Form g-Like) Form	types:				101
#: 0 0 0 0 0	Form: CRS 2 Main Building For CRS 3 Secondary Buildin CRS 4 Archaeological Sit CRS 5 Structure (Buildin CRS 6 Structure (Land Fo	m ng Form se Form g-Like) Form sature) Form	types:				
#: 0 0 0 0	Form: CRS 2 Main Building For CRS 3 Secondary Buildin CRS 4 Archaeological Sit CRS 5 Structure (Buildin CRS 6 Structure (Land Fo	m ng Form se Form g-Like) Form sature) Form	lypes:				
#: 0 0 0 0 0 0	Form: CRS 2 Main Building For CRS 3 Secondary Buildin CRS 4 Archaeological Sid CRS 5 Structure (Buildin CRS 6 Structure (Land Form CRS 7 Object Form CRS 8 Landscape Eleme CRS 9 Map Form	m ng Form se Form g-Like) Form eature) Form nts Form N/A	types:				
#: 0 0 0 0 0 0 1	Form: CRS 2 Main Building For CRS 3 Secondary Buildin CRS 4 Archaeological Sid CRS 5 Structure (Buildin CRS 6 Structure (Land Form CRS 7 Object Form CRS 8 Landscape Eleme CRS 9 Map Form CRS 14 Potential District	m ng Form se Form g-Like) Form eature) Form nts Form N/A	types:				
#: 0 0 0 0 0 0 1	Form: CRS 2 Main Building For CRS 3 Secondary Buildin CRS 4 Archaeological Sid CRS 5 Structure (Buildin CRS 6 Structure (Land Form CRS 7 Object Form CRS 8 Landscape Eleme CRS 9 Map Form	m ng Form se Form g-Like) Form eature) Form nts Form N/A	types:				
#: 0 0 0 0 0 0 1 1	Form: CRS 2 Main Building For CRS 3 Secondary Buildin CRS 4 Archaeological Sid CRS 5 Structure (Buildin CRS 6 Structure (Land Form CRS 7 Object Form CRS 8 Landscape Eleme CRS 9 Map Form CRS 14 Potential District	m ng Form se Form g-Like) Form eature) Form nts Form N/A	types:				
#: 0 0 0 0 0 1 1 SURVE	Form: CRS 2 Main Building For CRS 3 Secondary Buildin CRS 4 Archaeological Sit CRS 5 Structure (Buildin CRS 6 Structure (Land Form CRS 7 Object Form CRS 8 Landscape Eleme CRS 9 Map Form CRS 14 Potential District YOR INFORMATION:	m ng Form e Form g-Like) Form eature) Form nts Form N/A Form Dwellings	types:				
#: 0 0 0 0 0 1 1 1 SURVE	Form: CRS 2 Main Building For CRS 3 Secondary Buildin CRS 4 Archaeological Sit CRS 5 Structure (Buildin CRS 6 Structure (Land Form CRS 7 Object Form CRS 8 Landscape Eleme CRS 9 Map Form CRS 14 Potential District YOR INFORMATION: or name:	m ng Form se Form g-Like) Form eature) Form N/A Form Dwellings Gerald M. Kuncio	types:				

9.	OTHER NOTES OR OBSERVATIONS:	CRS#	S-11730
9.	The African American community known as Jimtown began forming in the 1870s and 1880s by no later than 1900. It was named after James Daniel Hargis, a farmer who owned and so the buildings in Jimtown date from the late 20 th century; earlier buildings have for the maltered. The Jimtown Potential Historic District is evaluated as not eligible for NRHP listing	, and was lid land in ost part i	s a definable place the area. Most of
). STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to sta an(s)):	ate mana	gement
	a) Time period(s) Pre-European Contact Paleo-Indian Archaic Woodland I Woodland II		,
	 □ 1600-1750± Contact Period (Native American) □ 1630-1730± Exploration and Frontier Settlement □ 1730-1770± Intensified and Durable Occupation □ 1770-1830± Early Industrialization □ 1830-1880± Industrialization and Early Urbanization ☑ 1880-1940± Urbanization and Early Suburbanization ☑ 1940-1960± Suburbanization and Early Ex-urbanization 		
	b) Geographical zone Upper Peninsula Lower Peninsula/Cypress Swamp Coastal Urban (Clty of Wilmington)		
	c) Historic period theme(s)		
	Agriculture Transportation and Community Forestry Settlement Patterns and Description of the Community Organizations Architecture, Engineering and Community Organizations Architecture, Engineering and Covernment architecture, Engineering architectu	mograp ind Deco	hic Changes trative Arts

doc # 20-06-01-05-13

DELAWARE STATE HISTORIC PRESERVATION OFFICE 15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY POTENTIAL DISTRICT FORM

CRS#	S-11730
------	---------

1. 2.	BOUNDARY: Portion Hundred.		Potential Historic District Road and Beaver Dam Ro	oad (State Route 23) in	Lewes and Rehoboth
3.	FUNCTION:	residential: recreational: other:	commercial: industrial: describe:	reilgious: ⊠ governmental: □	archaeological: educational:
4.	REASON FOR SUR	VEY: Western	Parkway Project (Section	106)	
5.	DOCUMENTATION				
	a) Report title:	Western Park	vay Project, Phase II Histor	ric Architectural Resour	ce Survey
	b) Map showing bo	oundary:	attached 🗵		
	c) Cross-reference	list of individu	ial CRS#s (use ranges only	for sequential numbers)):
	S-895 S-11538 S-11539 S-940 S-941 S-942 S-11540 S-9028				
_					
6.	SURVEYOR INFOR	MATION:			
	Surveyor name:		Gerald M. Kuncio		
	Principal Investiga	tor name:	Gerald M. Kuncio	<i>(((((((((((((</i>	
	Principal Investiga	tor signature:	Eqnale/	bonus	
	Organization:		Skelly and Loy, Inc.	r	Pate: 7/2006
doc	# 20-06-01-05-13		USE BLACK INK ONLY		crs-14


CULTURAL RESOURCE SURVEY MAP FORM

1.	ADDRESS/LOCATION: Po	rtions of Jimtow	n and Beaver Dam Roads
2.	NOT FOR PUBLICATION [reason:	
3	LOCATION MAP:		

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN



DELAWARE STATE HISTORIC PRESERVATION OFFICE PHOTOGRAPHIC INVENTORY

Photo Roll # C-4652 S-11730 7/2006 Surveyor Gerald M. Kuncio Date

Description: 1 Late twentieth century house on Beaver Dam Road N of Jimtown Road, facing SE; 2 Late twentieth century house on Beaver Dam Road N of Jimtown Road, facing SE; 3 S-895, late nineteenth century farmhouse on Beaver Dam Road S of Jimtown Road, facing SE; 4 House on Beaver Dam Road S of Jimtown Road, facing SE; 5 Altered house on Beaver Dam Road S of Jimtown Road, facing SE; 6 House on Beaver Dam Road S of Jimtown Road, facing S.

Negative location (if other than SHPO)

Skelly and Loy, Inc.

Attach contact print(s):











loc # 20-06-01-05-12

crs-13

DELAWARE STATE HISTORIC PRESERVATION OFFICE PHOTOGRAPHIC INVENTORY

CRS # S-11730 Date 7/2006 Photo Roll # C-4653 Surveyor Gerald M. Kuncio

Description: 18 Late twentieth century house on the N side of Jimtown Road, facing N; 19 late twentieth century louse on the N side of Jimtown Road, facing NE; 20 Altered mid-twentieth century house on the N side of Jimtown Road, facing N; 21 Late twentieth century house on the N side of Jimtown Road, facing N; 22 House from the early 1950s on the S side of Jimtown Road, facing S; 23 Twentieth century trailer located on the north side of Jimtown Road, facing NE.

Negative location (if other than SHPO) Skelly and Loy, Inc. Attach contact print(s):



loc # 20-06-01-05-12

DELAWARE STATE HISTORIC PRESERVATION OFFICE PHOTOGRAPHIC INVENTORY


C-4654 Gerald M. Kuncio S-11730 7/2006 Photo Roll # Surveyor Date

Description: 1 S-940, late nineteenth/early twentieth century house located on the S side of Jimtown Road, facing SE; 2 S-11540, moved to Jimtown in 1992, facing SW; 3 House from the 1960s located on the N side of Jimtown Road, facing NE; 4 House built on the N side of Jimtown Road in the 1960s and later expanded, facing N; 5 House built on the N side of Jimtown Road in the 1960s and later expanded, facing N; 6 House expanded by building around a house dating from the early twentieth century, facing SW; 7 S-941, located on the S side of Jimtown Road, facing south; the one-story section dates from the late twentieth century; 8 Late twentieth century trailer located on the north side of Jimtown Road, facing E.

Negative location (if other than SHPO)

Skelly and Loy, Inc.

Attach contact print(s):



doc # 20-06-01-05-12

DELAWARE STATE HISTORIC PRESERVATION OFFICE PHOTOGRAPHIC INVENTORY

Photo Roll # C-4654 Gerald M. Kuncio Surveyor S-11730 Date 7/2006

Description: 9 House moved to the S side of Jimtown Road in the late twentieth century, facing SE; 10 House built on he N side of Jimtown Road and then expanded, facing NE; 11 S-9028, located on the S side of Jimtown Road, facing south, the house replaced an older house in the early 1960s; 12 Modified trailer located on the N side of Jimtown road, facing N; 13 Late twentieth century trailer located on the N side of Jimtown Road, facing N; 14 Mid-twentieth entury house located on the S side of Jimtown Road, facing S; 15 Building located on the S side of Jimtown Road, acing SW; it was subsequently expanded.

Negative location (if other than SHPO)

Skelly and Loy, Inc.

Attach contact print(s):









20-06-01-05-12

doc # 20-01-00-05-02

DELAWARE STATE HISTORIC PRESERVATION OFFICE 15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY SURVEY UPDATE FORM

CRS#	S-947

	out in		
۱.	HISTORIC NAME/FUNCTION:	Valls Farm/Agricultural Complex	
2.	ADDRESS/LOCATION: 18886 F	Robinsonville Road/West side at Cedar Grove F	Road intersection
3.	CURRENT CONDITION: excelle	ent ⊠ good [] fair ∏ poor	demolished
4.	part of the original house was tor intact. This front (east) portion da	s been altered several times. According to the orn down in the 1950s leaving the former kitchen lates from ca. 1878, and the rear addition dates on was added to the older portion of the house,	area (to the north) from <i>ca.</i> 1936.
5.		e is still surrounded by farmland and wooded ared on the other side of Robinsonville Road (to th	
6. I	FORMS ADDED (give number of for		
6. (#: Form:	List property types:	
6. (#: Form: 1 CRS 2 Main Building Form	List property types: Dwelling	
6. (#: Form: 1 CRS 2 Main Building Form 3 CRS 3 Secondary Building	List property types: Dwelling Form Barn, shed, shed	
6 . I	#: Form: 1 CRS 2 Main Building Form 3 CRS 3 Secondary Building 0 CRS 4 Archaeological Site	List property types: Dwelling Form Barn, shed, shed Form	
6. (#: Form: 1 CRS 2 Main Building Form 3 CRS 3 Secondary Building 0 CRS 4 Archaeological Site 0 CRS 5 Structure (Building-	List property types: Dwelling Form Barn, shed, shed Form Like) Form	
6 . I	#: Form: 1 CRS 2 Main Building Form 3 CRS 3 Secondary Building 0 CRS 4 Archaeological Site 0 CRS 5 Structure (Building- 0 CRS 6 Structure (Land Feat	List property types: Dwelling Form Barn, shed, shed Form Like) Form	
6 . I	#: Form: 1 CRS 2 Main Building Form 3 CRS 3 Secondary Building 0 CRS 4 Archaeological Site 0 CRS 5 Structure (Building-land) 0 CRS 6 Structure (Land Feat 0 CRS 7 Object Form	List property types: Dwelling Form Barn, shed, shed Form Like) Form sture) Form	
6. (#: Form: 1 CRS 2 Main Building Form 3 CRS 3 Secondary Building 0 CRS 4 Archaeological Site 0 CRS 5 Structure (Building- 0 CRS 6 Structure (Land Feat 0 CRS 7 Object Form 0 CRS 8 Landscape Element	List property types: Dwelling Form Barn, shed, shed Form Like) Form sture) Form	
6. (#: Form: 1 CRS 2 Main Building Form 3 CRS 3 Secondary Building 0 CRS 4 Archaeological Site 0 CRS 5 Structure (Building- 0 CRS 6 Structure (Land Feat 0 CRS 7 Object Form 0 CRS 8 Landscape Elements 1 CRS 9 Map Form	List property types: Dwelling Form Barn, shed, shed Form Like) Form Sture) Form SFORM N/A	
6. I	#: Form: 1 CRS 2 Main Building Form 3 CRS 3 Secondary Building 0 CRS 4 Archaeological Site 0 CRS 5 Structure (Building- 0 CRS 6 Structure (Land Feat 0 CRS 7 Object Form 0 CRS 8 Landscape Element	List property types: Dwelling Form Barn, shed, shed Form Like) Form Sture) Form SFORM N/A	
7 .	#: Form: 1 CRS 2 Main Building Form 3 CRS 3 Secondary Building 0 CRS 4 Archaeological Site 0 CRS 5 Structure (Building- 0 CRS 6 Structure (Land Feat 0 CRS 7 Object Form 0 CRS 8 Landscape Elements 1 CRS 9 Map Form	List property types: Dwelling Form Barn, shed, shed Form Like) Form Sture) Form SFORM N/A	
7 .	#: Form: 1 CRS 2 Main Building Form 3 CRS 3 Secondary Building 0 CRS 4 Archaeological Site 0 CRS 5 Structure (Building- 0 CRS 6 Structure (Land Feat 0 CRS 7 Object Form 0 CRS 8 Landscape Element: 1 CRS 9 Map Form 0 CRS 14 Potential District Fe	List property types: Dwelling Form Barn, shed, shed Form Like) Form Sture) Form SFORM N/A	
7 .	#: Form: 1	List property types: Dwelling Form Barn, shed, shed Form Like) Form sture) Form N/A Form	
7 .	#: Form: 1	List property types: Dwelling Form Barn, shed, shed Form Like) Form Sture) Form N/A Form Laura C. Ricketts and Gerald M. Kuncio	
7 .	#: Form: 1	List property types: Dwelling Form Barn, shed, shed Form Like) Form Sture) Form N/A Form Laura C. Ricketts and Gerald M. Kuncio	Date: 12/2006

USE BLACK INK ONLY CRS-10

8.	OTHER NOTES OR OBSERVATIONS:	CRS#	S-947
	According to the owner, the farm has been in his family since <i>ca</i> . 1878. Most of the torn down in the 1950s, leaving just a small wing in place which was added on to. was placed where the torn down section was formerly located. The addition comprote barn, too, lacks historical integrity due to a large addition.	In 2006,	a large addition
	STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to sta an(s)):	ate mana	gement
	a) Time period(s) Pre-European Contact Paleo-Indian Archalc Woodland I Woodland II		
	 □ 1600-1750± Contact Period (Native American) □ 1630-1730± Exploration and Frontier Settlement □ 1730-1770± Intensified and Durable Occupation □ 1770-1830± Early Industrialization □ 1830-1880± Industrialization and Early Urbanization □ 1880-1940± Urbanization and Early Suburbanization □ 1940-1960± Suburbanization and Early Ex-urbanization 		
	b) Geographical zone Upper Peninsula Lower Peninsula/Cypress Swamp Coastal Urban (City of Wilmington)		
	c) Historic period theme(s)		
	Agriculture	emograpi and Deco	hic Changes crative Arts

CULTURAL RESOURCE SURVEY MAIN BUILDING FORM

CRS#	S-947	

١.	ADDRESS/LOCATION: 18886 Robinsonville Road/West side at Cedar Grove Road interse	ection
2.	FUNCTION(S): historic Farmhouse current Farmhouse	
3.	YEAR BUILT: 1905 CIRCA?: MA ARCHITECT/BUILDER: N/A	
S .	STYLE OR FLOOR PLAN: Three-gable with rectangular plan	
5.	INTEGRITY: original site 🗵 moved 🗌	
	If moved, from where other location's CRS#	<u>year</u>
	list major alterations and additions with years (if known) a. 2-story rear addition	<u>year</u> ca. 1936
	b. Main portion torn down	ca. 1955
6. 7.	CURRENT CONDITION: excellent good fair poor DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable blanks.) a. Overall shape: Rectangular with addition Stories: 2	; leave no
	Additions: 1-story lean-to side addition (north) b Structural system (if known): Frame	
	c. Foundation: materials: Concrete skim coat basement: full ☐ partial ☐ not visible ☑ no basement ☐	
	d. Exterior walls (original if visible & any subsequent coverings): Blue vinyl siding	
	e. Roof: shape: 3 gable; shed roof over side addition; front gable over side door (south) materials: Asphalt shingle cornice: Simple boxed cornice dormers: 0 chimney: location(s): 1-exterior brick chimney on S elevation	
8.	DESCRIPTION OF ELEVATIONS:	
	a Francis Rispetion E	

- - Bays 3 1)
 - 2) Windows 5

fenestration Regular type 6/6 sash trim Simple trim shutters 0

Door(s) 1

location Center

type 6-panel wood door

trim Colonial Revival fluted Doric pilasters and broken pediment with acorn finial

- Porch(es) 0 4)
- b. Side: Direction: S
 - Bays 5 1)
 - Windows 5 2)

fenestration Irregular

type 6/6 sash trim Simple trim shutters 0

Door(s) 1 3)

location Center of rear addition

type Paneled wood door with glass and metal replacement storm door trim Simple trim

- Porch(es) Front gable canopy and steps at door 4)
- Side: Direction: N
 - 1) Bays 5
 - 2) Windows 6

fenestration irregular

type 6/6 sash including large window of 3 grouped 6/6 sash windows at left trim Simple trim

shutters 0

Door(s) 1 3)

location Left of side addition

type Wood paneled door with glass and metal storm door trim Simple trim

- Porch(es) 0 4)
- Rear: Direction: W
 - Bays 3 1)
 - 2) Windows 4

fenestration irregular

type 3 - 6/6 sash window; paired 6/1 sash window at center

trim Simple trim

shutters 0

Door(s) 0 3)

location N/A

type N/A

trim N/A

- Porch(es) 0
- INTERIOR: Not accessible 9.
- 10. LANDSCAPING: The house is still surrounded by farmland and wooded areas. A new housing development is being constructed on the other side of Robinsonville Road (to the east).
- OTHER COMMENTS: The J. Burton farm appears at this location in the 1868 Beers Atlas. 11.



CULTURAL RESOURCE SURVEY SECONDARY BUILDING FORM

CRS#	S-947.01	

1.	ADDRESS/LOCATION: 18886 Robinsonville Road/West side at Cedar Grove Road intersection	on
2.	FUNCTION(S): historic Barn current Barn	
3.	YEAR BUILT: 1925 CIRCA?: ARCHITECT/BUILDER: N/A	
4.	STYLE/FLOOR PLAN: Front gambrel hall barn with side gable addition/T-shaped plan	
5.	INTEGRITY: original site 🗵 moved 🗌	
	if moved, from where original location's CRS#	year
	list major alterations and additions with years (if known) a. Side gable addition at north side b.	<u>year</u> ca. 1977
6.	CURRENT CONDITION: excellent good fair	poor 🗆
7.	DESCRIPTION:	
	a. Structural system Frame	
	b. Number of stories 3	
	 c. Wall coverings Blue aluminum siding on E and N; Vinyl shake siding (incomplete) on S; W (originally vertical board and batten wood siding) 	not visible
	d. Foundation Concrete slab	
	 Roof structural system Steep gambrel roof with flared eaves; shallow side gable roof coverings Asphalt shingle openings 0 	
8.	DESCRIPTION OF ELEVATIONS:	

- a. Facade: direction: E
 - 1) bays: 5
 - 2) windows: 3-hinged rectangular casement windows on addition
 - 3) door(s): 1 Large sliding wood door at right of original barn; 1 Hinged second story door with aluminum siding at center of original barn
 - 4) other: N/A

CRS#	S-947.01
------	----------

- b. Side: direction: N
 - 1) bays: 5
 - 2) windows: 0
 - 3) door(s): 2 Large sliding wood barn doors centered under gable
 - 4) other: N/A
- c. Side: direction: S
 - 1) bays: 5
 - 2) windows: 5 6/6 replacement sash windows on first floor
 - 3) door(s): 1 Large sliding wood barn door on second floor left of center
 - 4) other: N/A
- d. Rear: direction; W
 - 1) bays: 5
 - 2) windows: Not visible
 - 3) door(s): Not visible
 - 4) other: N/A
- 9. INTERIOR (if accessible):
 - a) Floor plan Not accessible
 - b) Partition/waits Not accessible
 - c) Finishes Not accessible
 - d) Furnishings/machinery Not accessible



CULTURAL RESOURCE SURVEY SECONDARY BUILDING FORM

CRS#	S-947.02	
	· · · · · · · · · · · · · · · · · · ·	

1.	ADDRESS/LOCATION: 18886 Robinsonville Road/West side at Cedar Grove Road intersection	<u>n</u>
2.	FUNCTION(S): historic Shed current Shed	···
3.	YEAR BUILT: 1977 CIRCA?: M ARCHITECT/BUILDER: N/A	
4.	STYLE/FLOOR PLAN: Imegular side gable shed/Irregular plan	
5.	INTEGRITY: original site moved original location's CRS# Unknown	<u>year</u> ca. 1977
	list major alterations and additions with years (if known) a. N/A b.	<u>year</u>
6.	CURRENT CONDITION: excellent ☐ good ⊠ fair ☐	poor 🗆
7.	DESCRIPTION:	
	a. Structural system Frame	
	b. Number of stories 1	
	c. Wall coverings Vertical board and batten wood siding with green stain; exterior plywood par	nels
	d. Foundation Not visible	
	 Roof structural system Side gable roof with stepped edge on S side coverings Standing seam metal roofing openings 0 	
8.	DESCRIPTION OF ELEVATIONS:	
	a. Facade: direction: S1) bays: 32) windows: Not visible	
	3) door(s): Not visible	

CRS#	S-947.02	
------	----------	--

			_
b.	Side:	direction	n: E

- 1) bays: 2
- 2) windows: 0
- 3) door(s): 1 Hinged wood plank door recessed at left
- 4) other: N/A
- c. Side: direction: W
 - 1) bays: 2
 - 2) windows: Not visible
 - 3) door(s): Not visible
 - 4) other: N/A
- d. Rear; direction: N
 - 1) bays: 3
 - 2) windows: 3 Square openings with single hinged wood plank shutters
 - 3) door(s): 0
 - 4) other: N/A
- 9. INTERIOR (if accessible):
 - a) Floor plan Not accessible
 - b) Partition/walls Not accessible
 - c) Finishes Not accessible
 - d) Furnishings/machinery Not accessible



CULTURAL RESOURCE SURVEY SECONDARY BUILDING FORM

CRS# S-947.03	
---------------	--

1.	ADI	DRESS/LOC	ATION: _	18886 R	obinsonville	Road/Wes	st side a	at Cedar (Grove Road intersection	on
2 .	FUN	ICTION(S):	histori	c Shed				current	Shed	
3.	YEA	R BUILT:	_1977_ C	IRCA7:	ARCH	ITECT/BUI	LDER:	N/A		
4.	STY	LE/FLOOR	PLAN: _S	Side gable	e shed/Rect	angular pla	an			
5.	INT	EGRITY:	origin	al site	×I	moved				
	If m	oved, from	where					<u>oriç</u>	inal location's CRS #	
		major altera N/A	itions and	additions	with years	(if known)				уеаг
6.	CUF	RENT CON	DITION:		excellent []	good	×	fair 🗌	poor 🗌
7.	DES	SCRIPTION:								
	а. :	Structural sy	stem Frar	ne						
	b.	Number of s	tories 1					•		
	c . '	Wall coverin	gs Vertica	l board a	nd batten w	ood siding	; vertica	al board v	vood siding	
	d.	Foundation	Not visible	3						
		Roof structural sy coverings A openings 0			oof with boxe	ed aluminu	m comi	ice		
8.	DE	SCRIPTION	OF ELEVA	TIONS:						
	a.	Facade: di 1) bays: 2) windo	1							
		3) door(s): 1 - Slidi	ng board	and batten	wood barr	door			

CRS# S	5-947.03
--------	----------

- b. Side: direction: E
 - 1) bays: 1
 - 2) windows: 1 Square opening with single hinged wood shutter at right
 - 3) door(s): 0
 - 4) other: N/A
- c. Side: direction: W
 - 1) bays: 1
 - 2) windows: Not visible
 - 3) door(s): Not visible
 - 4) other: N/A
- d. Rear: direction: N
 - 1) bays: 1
 - 2) windows: 0
 - 3) door(s): 0
 - 4) other: N/A
- 9. INTERIOR (if accessible):
 - a) Floor plan Not accessible
 - b) Partition/walls Not accessible
 - c) Finishes Not accessible
 - d) Furnishings/machinery Not accessible

CULTURAL RESOURCE SURVEY MAP FORM


CRS#	S-947	
CRS#	S-947	

1,	ADDRESS/LOCATION:	18886	<u>Robinsonvi</u>	ille Road/ West side at Cedar Grove Road intersection
2.	NOT FOR PUBLICATION		reason:	
3.	LOCATION MAP:			·


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN



DELAWARE STATE HISTORIC PRESERVATION OFFICE

PHOTOGRAPHIC INVENTORY

RS# S-947 Date 12/2005 Photo Roll# C-4620 Surveyor Laura C. Ricketts

Pescription:

:-4620:6 Farmhouse, E (front) and N elevations, facing SW; C-4620:7 Farmhouse, S and E (front) elevations, facing NW; C-4620:8 Farmhouse, W (rear) and S elevations, facing NE; C-4620:9 Shed (.02), E (front) elevation,

facing W; C-4620:10 Shed (.03), S and E elevations, facing NW

Negative location (if other than SHPO) Skelly and Loy, Inc.

Attach contact print(s):











doc # 20-06-01-05-12

CRS-13

DELAWARE STATE HISTORIC PRESERVATION OFFICE

PHOTOGRAPHIC INVENTORY

RS# S-947 Date 12/2005 Photo Roll# C-4620 Surveyor Laura C. Ricketts

escription:

E-4620:11 Barn (.01), S and E (front) elevations, facing NW; C-4620:12 Barn (.01) and shed (.03 foreground), N elevation, facing S; C-4620:13 Shed (.02), E and N elevations, facing SW; C-4620:14 Shed (.03) E and N elevations, facing SW; C-4620:15 Barn (.01), E (front) and N elevations, facing SW

Negative location (if other than SHPO) Skelly and Loy, Inc.

ttach contact print(s):











doc # 20-06-01-05-12

CRS-13

DELAWARE STATE HISTORIC PRESERVATION OFFICE

PHOTOGRAPHIC INVENTORY

CRS # S-947 Date 10/2006 Photo Roll # C-4655 Surveyor Gerald M. Kuncio

Description:
C-4655:28 Farmhouse, E (front) and N elevations and the large addition being built, facing W; C-4655:29 addition, rear (W) and N sides, facing S; C-4655:30 Original portion of the farmhouse and the addition under construction, S and rear (W) elevations, facing E

Negative location (if other than SHPO)

Skelly and Loy, Inc.

Attach contact print(s):







doc # 20-06-01-05-12

CRS-13

C	1	j	ĽΤ	U	۲A	Ľ	R	E	S	0	UR	C	E,	5	ÜF	٧	E١	ĺ.	
													T 1						

DELAWARE BUREAU OF ARCHAEOLOGY AND HISTORIC PRESERVATION HALL OF RECORDS DOVER, DELAWARE 19901 (302) 678-5314




FORM CRS-2

FOR OFFICE USE ONLY

CRS # SQUT
Quad Favorable |
SPO map # 18 17 11
Hundred | SPO map |
DOCUMENT 20-06/18/04/1

1.	NAME OF LOCUS: Parcel 7-Tax map 3-34-11
	STREET LOCATION: NOT . AS OF RE STEE OF COS MOR MENTION IN RE 283
	OWNER'S NAME: Clasers Howey Walls + Margaret TEL.
1 M.	ADDRI 35: 13,0 2CH, Laure D. 19958
4.	TYPE OF LOC. >) structure / b) district c) archaeological site
	d) other
5.	SURROUNDINGS OF LOCUS: (check more than one if necessary)
	a) fallow field b) cultivated field c) woodland
	d) scattered buildings e) densely built up f) other
6.	THREATS TO LOCUS: (check more than one of necessary)
	a) none knownb) zoningc) roadsd) wevelopers
	e) deterioration f) other two beca highly moderance
7.	REPRES . FATION ON OTHER SURVEYS:
	TELT LEGISLATION OF THE PROPERTY OF THE PROPER
	Tite,
	TIPLE
8.	YOUR NAME! PROJICE HISTORY
	YOUR ADDRESS: Sunsey County Courthons.
	ORGANIZATION (*1. any) Asat Predefination Phones DATE: 9/12/72

USE BLACK INK ONLY



CI S1	JLTU TRUC	RAL RESOURCE SURVEY TURAL DATA FORM		Form CRS-1 FOR OFFICE USE ONLY
	ARCH PRES HALL DOVE	WARE BUREAU OF AEOLOGY AND HISTORIC : ERVATION OF RECORDS R. DELAWARE 19901) 678-5314		CRS 5-947 Quad Fairmant SPO map 18-19-11 Hundred 18-19-11 DOCUMENT 20-06/78/09/14
١.	ADDR	ESS OF STRUCTURE : במום	side of Pt 277 Outeco	he and from from them wy 24 203
2.	DESC	RIBE THE STRUCTURE AS C	• :	in a supplemental superior sup
	a)	Overall shape main ho stories two stored bays 3 bay forced wings 2 story good	nces .e. Es wing out necus, sways	
	ь)	Structural system	sule in center bull	
	c)	Foundation materials back with		, SKETCH PLAN
	d)	Exterior walls materials wood Sn color(s)	ingle + chaptairle A aluminum Sidin	on covered us/ musclern
	e)	shape: waterials cornice suraple.	alosali comice - a	Luj composition shrugher literature. The your extensor gates.
	f)	windows spacing summed type modern a trim machine shutters none	tud Luninum, double Laire + small aluninum bum	hung saahes of 6/6 sastres white
	g)	spacing Jacache type trim spakes of	teor in central ba necessarily panels deor in south side yell door shoot	J- retural colored wood
	h)	Porches: location(s) materdals supports trim	untuus ka 1876	
		(interior details (if a	CC###1610) USE BLACK INK ONLY	
2 (1996) 1812 (1996)	5 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3			

3.	CONDITION: good deteriorated
	remarks: has been so higher mortenings that the original
4.	INTEGRITY: a) original site b) moved
	c) if moved, when and from where
	d) list major alterations and dates (if known)
5.	DATE OF INITIAL CONSTRUCTION:
5.	ARCHITECT/BUILDER:
7.	RELATED OUTBUILDINGS:
	a) barn 📈 🏚) carriage house c) garage d) privy
	e) shedf) greenhouse g) shop h) gardens
	i) icehouse j) springhouse k) other
	describe: Burn : wood shingled gamened noof; frink walls of
	vertical butters, the gable ringed extension on
	side - vert plant the walls we went bottom,
8.	BRIEFLY DISCUSS THE ORIGINAL AND SUBSEQUENT USES OF THE STRUCTURE. NOTE ANY ASSOCIATIONS WITH HISTORIC EVENTS OR PERSONS:
	Original main house " 21/2 stones w/ grobs roof tour down; present main house was originally the witches wing
9). Primary References: (include location of reference).
. 17	o serveyors Paulin Hours and Date of Pores 9/12/79
ा है। के	USP BLACK INK OFFLY
<u> </u>	

PHOTOGRAPHIC INVENTORY

BUREAU OF ARCHAEOLOGY AND HISTORIC PRESERVATION Document 20-06/79/01/11

Boe Miche 20 00/15/	01/21
CRS Number <u>5-947</u> Date <u>9</u>	Contact Sheet # <u>C - 783 (15)</u>
Description facade of the Claurice	Walls face
Location (if other than Bureau collection)	
Attach contact print	
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	

Wals



1920s or 30 < barrier by a proper boards aspect to the gambrelved with flore shifted to the gringle to the gringle to the gringle to the grind to th

DELAWARE STATE HISTORIC PRESERVATION OFFICE 15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY SURVEY UPDATE FORM

CRS#	\$-951	

											
-	нізто	ORIC NAME/FUNCTION: _Jo	seph Farm	n/Agricu	ultural	Comp	ex	•••			
! -	ADDR	ESS/LOCATION: 18345 R	obinsonvill	e Road	l/East	side o	f Robii	nsonville	Road		_
i.	CURR	ENT CONDITION: excelle	nt 🗀	good	\boxtimes	fair		poor		demolished	
	INTEG while	GRITY: The farmstead lacks the farmhouse has integrity.	s integrity; i , the barn is	nine of s in a s	13 bu tate of	ildings collap	date f se and	rom the	late 20 ^t ot.	h century. Also	,
i.		ING INTEGRITY: Nine of 13 Itivated and uncultivated farm IE.									
i. F	ORMS	ADDED (give number of form	ns complet	ed for e	each):						
	#:	Form:				y type:	31				
	1	CRS 2 Main Bullding Form			house						
	44		_	vehic stora	le she ge she	lter, ch ed, hou	icken	coop, ou	itbuildin	mobile home, ig, Quonset hut garage, mobile	•
	14	CRS 3 Secondary Building		nome	, barr	<u> </u>					
	0	CRS 4 Archaeological Site I CRS 5 Structure (Building-I							· · · · · · · · · · · · · · · · · · ·		
	0	CRS 6 Structure (Land Feat		-		_ ".					
	0	CRS 7 Object Form									
	0	CRS 8 Landscape Elements	Form								
	1	CRS 9 Map Form		N/A							
	0	CRS 14 Potential District Fo	orm								
7.	SURV	YEYOR INFORMATION:									
	Surve	eyor name:	Laura C.	Ricket	ts and	Geral	<u>d М. К</u>	Cuncio			
		ipal Investigator name:	Gerald M	t. Kunc	io	V	\rightarrow				
	Princ	ipal Investigator signature:		coult	1014			7			
	Orga	nization:	Skelly an	nd Loy,	Inc.				Dat	e: <u>12/2006</u>	
doc #	¥ 20-01-0	00-05-02	USE BLA	CK INK	ÖNL	,				crs-1()

	since ca. 1890. The far of 14) date to the late two of the resource. The Jo	owned the property since at least 1852, and it has been at the current acreage imhouse dates to ca. 1904. However, the majority of the farmstead's buildings (9 ventieth century. They visually dominate the farmstead, compromising the integrity oseph Farm is, consequently, not eligible for NRHP listing. EXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s):	
y .		Pre-European Contact	
	a) Time period(s)	Paleo-Indian	
		Archaic Woodland I	
		Woodland II	
	<u></u>	1600-1750± Contact Period (Native American) 1630-1730± Exploration and Frontier Settlement	
	H	1730-1770± Intensified and Durable Occupation 1770-1830± Early Industrialization	
		1830-1880± Industrialization and Early Urbanization	
		1880-1940± Urbanization and Early Suburbanization 1940-1960± Suburbanization and Early Ex-urbanization	
	b) Geographical zone	 □ Piedmont □ Upper Peninsula □ Lower Peninsula/Cypress Swamp ☑ Coastal □ Urban (City of Wilmington) 	
	c) Historic period theme	ə(s)	
	×	Agriculture	
	Ĭ	Trapping/Hunting Architecture, Engineering and Decorative Arts	
		Mining/Quarrying Government Fishing/Oystering Religion	
		Manufacturing	
		Finance Occupational Organizations	
		Professional Services	

8. OTHER NOTES OR OBSERVATIONS:

CRS# S-951

CULTURAL RESOURCE SURVEY MAIN BUILDING FORM

 CRS#	S-951	
CRS#	3-90 I	

1.	ADD	DRESS/LOCATION: 18345 Robinsonville Road/East side of Robinsonville Road	
2.		ICTION(S): historic Farmhouse current Farmhouse	
3.		R BUILT: 1904 CIRCA?: ARCHITECT/BUILDER: N/A	
4.	-	'LE OR FLOOR PLAN: Gable front and wing with one-story enclosed front porch with sheet	d roof
5 .	INTE	EGRITY: original site 🖾 moved 🗌 oved, from where other location's CRS#	year
	N/A		
		major alterations and additions with years (if known) Front porch enclosed	<u>vear</u> N/A
		Rear addition; rear door filled in	N/A
6.	CUR	RENT CONDITION: excellent good fair poor	
7 .		SCRIPTION; (Describe the resource as completely as possible. Use N/A for not applicable; leavents.)	e no
	a.	Overall shape: T-shape with additions Stories: 2½ Additions: 1-story enclosed front porch (west); 1-story lean-to rear addition (east)	
	b	Structural system (if known): Frame	
	C.	Foundation: materials: Stucco basement: full partial not visible no basement	
	d.	Exterior walls (original if visible & any subsequent coverings): Machine-hewn wood shingles decorative pattern under west and north gables; vinyl siding on rear addition	with
	€.	Roof: shape: 3 gable materials: Slate shingles cornice: Exposed scroil-sawn rafter tails dormers: 0 chimney: location(s): 2 interior corbelled brick chimneys through ridge at center of gable let	ngths
۰	DES	CODIDTION OF ELEVATIONS	

DESCRIPTION OF ELEVATIONS:

- a. Facade: Direction W
 - 1) Bays 4
 - 2) Windows 13

fenestration Regular

type 1/1 sash; hopper; 2/2 sash

trim Architrave trim

shutters Operable wood shutters with 2 panels (first floor) and louvers (second floor)

Facade (cont'd)

3) Door(s) 1

location Left of center type Not visible; aluminum screen door trim Simple

- Porch(es) 1-story enclosed porch with shed roof at left
- b. Side: Direction: S
 - 1) Bays 3
 - 2) Windows 5

fenestration Regular

type 1/1 sash trim Architrave trim

shutters Operable wood shutters with 2 panels (first floor) and louvers (second floor)

3) Door(s) 0

location N/A type N/A trim N/A

- 4) Porch(es) 0
- c. Side: Direction: N
 - 1) Bays 4
 - 2) Windows 7

fenestration Regular type 1/1 sash; 2/2 sash trim Architrave trim; simple trim on additions shutters Operable two panel shutters first floor only

3) Door(s) 0

location N/A type N/A trim N/A

- 4) Porch(es) 0
- d. Rear: Direction: E
 - 1) Bays 3
 - 2) Windows 5

fenestration Regular

type 1/1 sash trim Architrave trim

shutters Operable two panel shutters first floor only

Door(s) 1

location Center of rear addition; original door filled in to right type Not visible

trim Not visible

- 4) Porch(es) 0
- INTERIOR: Not accessible
- LANDSCAPING: The farmhouse, barn, and outbuildings are still surrounded by farmland, but new housing developments are encroaching on the SW, NW, and NE.
- 11. OTHER COMMENTS: The S. W. Joseph farm appears in the 1868 Beers Atlas.



CULTURAL RESOURCE SURVEY SECONDARY BUILDING FORM

CRS# S-951.01	

1.	ADDRESS/LOCATION: 18345 Robinsonville Road/East side of Robinsonville Road									
 2.	FUNCTION(S): historic Summer kitchen current Storage									
3.	YEAR BUILT: 1910 CIRCA?: ARCHITECT/BUILDER: N/A									
4.	STYLE/FLOOR PLAN: Front gable, 1-story building/Rectangular plan									
5.	INTEGRITY: original site ⊠ moved ☐ If moved, from where original location's CRS # N/A	<u>year</u>								
	list major alterations and additions with years (if known) a. N/A b.	year								
6.	CURRENT CONDITION: excellent ☐ good ☑ fair ☐	роог 🗀								
7.	DESCRIPTION:									
	a. Structural system Wood frame									
	b. Number of stories 1									
	c. Wall coverings Wood clapboard siding with cornerboards on front (west) and sides; vertical beaded wood panel on rear									
	d. Foundation Raised on concrete blocks									
	e. Roof structural system Front gable coverings Asphalt shingle openings Chimney at rear									
_										

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: W
 - 1) bays: 1
 - 2) windows: 1 3/3 transom window under gable
 - 3) door(s): 1 Replacement steel door with 1/1 light
 - 4) other: N/A

- b. Side: direction: N
 - 1) bays: 1
 - 2) windows: 1 2/2 sash
 - 3) door(s): 0
 - 4) other: N/A
- c. Side: direction: S
 - 1) bays: 1
 - 2) windows: 1 2/2 sash
 - 3) door(s): 0
 - 4) other: N/A
- d. Rear: direction: E
 - 1) bays: 1
 - 2) windows: 0
 - 3) door(s): 0
 - 4) other: Exterior concrete block chimney
- 9. INTERIOR (if accessible):
 - a) Floor plan Not accessible
 - b) Partition/walls Not accessible
 - c) Finishes Not accessible
 - d) Furnishings/machinery Not accessible



CULTURAL RESOURCE SURVEY SECONDARY BUILDING FORM

CRS#	S-951.02	

1,	ADDRESS/LOCATION: 18345 Robinsonville Road/East side of Robinsonville Road	
2.	FUNCTION(S): historic Cold cellar current Unknown	
3.	YEAR BUILT: 1930 CIRCA?: MA ARCHITECT/BUILDER: N/A	
4.	STYLE/FLOOR PLAN: Pyramidal roof 1-story building/Square plan	
5.	INTEGRITY: original site 🗵 moved 🗌	
	If moved, from where N/A original location's CRS #	<u>year</u>
	list major alterations and additions with years (if known) a. N/A b.	year
6 .	CURRENT CONDITION: excellent good fair	poor 🗌
7 .	DESCRIPTION:	
	a. Structural system Frame	
	b. Number of stories 1 (half-height story)	
	c. Wall coverings Lattice openwork panels of wood lath with cornerboards on front (west) and significant metal panels on rear elevation	des;
	d. Foundation Not visible	
	e. Roof structural system Pyramidal hipped roof coverings Standing seam metal roof panels openings 0	
8.	DESCRIPTION OF ELEVATIONS:	
	a. Facade: direction: W 1) bays: 1 2) windows: 0	
	3) door(s): 1 - Wood door with strap hinges	
	4) other: N/A	

CRS#	S-951.02
------	----------

- b. Side: direction: N
 - 1) bays: 1
 - 2) windows: 0
 - 3) door(s): 0
 - 4) other: N/A
- c. Side: direction: S
 - 1) bays: 1
 - 2) windows: 0
 - 3) door(s): 0
 - 4) other: N/A
- d. Rear: direction: E
 - 1) bays: 1
 - 2) windows: 0
 - 3) door(s): 0
 - 4) other: N/A
- 9. INTERIOR (if accessible):
 - a) Floor plan Not accessible
 - b) Partition/walls Not accessible
 - c) Finishes Not accessible
 - d) Furnishings/machinery Not accessible



CULTURAL RESOURCE SURVEY SECONDARY BUILDING FORM

ί	51.03
---	-------

1.	ADDRESS/LOCATION: 18345 Robinsonville Road/East side of Robinsonville Road	
2.	FUNCTION(S): historic Outhouse current Unknown	
3.	YEAR BUILT: 1920 CIRCA?: M ARCHITECT/BUILDER: N/A	
4.	STYLE/FLOOR PLAN: Front gable 1-story building/Rectangular plan	
5.	INTEGRITY: original site	<u>year</u>
	list major alterations and additions with years (if known) a. N/A b.	year
6.	CURRENT CONDITION: excellent good fair	poor 🗌
7.	DESCRIPTION:	
	a. Structural system Frame	
	b. Number of stories 1	•
	c. Wall coverings Wood panels with vertical grooves	
	d. Foundation Concrete slab with concrete block	
	e. Roof structural system Front gable coverings Asphalt shingle openings 0	
8.	DESCRIPTION OF ELEVATIONS:	
	a. Facade: direction: N 1) bays: 1 2) windows: 0	
	3) door(s): 1- Wood panel door with strap hinges to left	
	4) other: N/A	

CRS#	\$-951.03	
------	-----------	--

- b. Side: direction: W
 - 1) bays: 1
 - 2) windows: 0
 - 3) door(s): 0
 - 4) other: N/A
- c. Side: direction: E
 - 1) bays: 1
 - 2) windows: 1 6-light hopper window
 - 3) door(s): 0
 - 4) other: N/A
- d. Rear: direction: S
 - 1) bays: 1
 - 2) windows: 0
 - 3) door(s): 0
 - 4) other: N/A
- 9. INTERIOR (if accessible):
 - a) Floor plan Not accessible
 - b) Partition/walls Not accessible
 - c) Finishes Not accessible
 - d) Furnishings/machinery Not accessible



CULTURAL RESOURCE SURVEY SECONDARY BUILDING FORM

CRS#	S-951.04	

1.	ADDRESS/LOCATION: 18345 Robinsonville Road/East side of Robinsonville Road	
 2.	FUNCTION(S): historic Mobile home current Mobile home	
∡.	Policinosito): Instanto <u>Infobile (folito</u>	
3.	YEAR BUILT: 2000 CIRCA?: ARCHITECT/BUILDER: N/A	
4.	STYLE/FLOOR PLAN: Side gable 1-story building/Rectangular plan	
5.	INTEGRITY: original site ⊠ moved □	
	if moved, from where original location's CRS #	year
	list major alterations and additions with years (if known) a. N/A	year
	b	
6.	CURRENT CONDITION: excellent ⊠ good ☐ fair ☐	poor 🗌
7.	DESCRIPTION:	
	a. Structural system Frame	
	b. Number of stories 1	
	c. Wall coverings Vinyl siding	
	d. Foundation Not visible	
	e. Roof structural system Side gable coverings Standing seam metal openings Exhaust vent at ridge near north end	

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: W
 - bays: 4
 - 2) windows: 3 1/1 sash; 1 2-pane sliding window irregularly arranged
 - 3) door(s): 1 with semi-circular fan light and vinyl storm door located to right of center

USE BLACK INK ONLY

4) other: Concrete stoop with 3 stairs leading to door

CRS#	S-951.04	
------	----------	--

h	Side	direction:	Ν
υ.	JIUG.	anocion.	, ,

- 1) bays: 1
- 2) windows: 1 1/1 sash
- 3) door(s): 0
- 4) other: N/A

c. Side: direction: S

- 1) bays: 1
- 2) windows: 1 Projecting bay window with 3 1/1 sash windows
- 3) door(s): 0
- 4) other: N/A

d. Rear: direction: E

- 1) bays: 4
- 2) windows: 4 1/1 sash windows irregularly arranged
- 3) door(s): 1 Door with vinyl storm door to right of center
- 4) other: Pressure-treated wood porch with trellis and attached stair to right of center

9. INTERIOR (if accessible):

- a) Floor plan Not accessible
- b) Partition/walls Not accessible
- c) Finishes Not accessible
- d) Furnishings/machinery Not accessible



CULTURAL RESOURCE SURVEY SECONDARY BUILDING FORM

CRS# S-951.05

1.	ADI	DRESS/LOCATION: 18345 Robinsonville Road/East side of Robinsonville Road	
2.	FUN	NCTION(S): historic Vehicle shelter current Vehicle shelter	
3.	YEA	AR BUILT: _2000_ CIRCA?: ARCHITECT/BUILDER: N/A	
4.	STY	/LE/FLOOR PLAN: Open pole building/Rectangular plan	
5.		EGRITY: original site	year
	list	major alterations and additions with years (if known) N/A	year
6.		RRENT CONDITION: excellent 🗵 good 🗌 fair 🗌	poor 🛚
7.	DE	SCRIPTION:	
	b.	Structural system Frame of 31 wood posts supporting steel I-beams and roof trusses Number of stories 1 Wall coverings Open sides; ridged metal sheeting under rear (east) gable	
	d.	Foundation Earth	
	:	Roof structural system Front gable with shallow hipped roof on three sides (not west) coverings Standing seam steel roofing openings 0	
8.	DE	SCRIPTION OF ELEVATIONS:	
	a.	Facade: direction: W 1) bays: 4 2) windows: 0	
		3) door(s): 0	
		4) other: N/A	

CRS# S	-951.05
--------	---------

- b. Side: direction: N
 - 1) bays: 6
 - 2) windows: 0
 - 3) door(s): 0
 - 4) other: N/A
- c. Side: direction: S
 - 1) bays: 6
 - 2) windows: 0
 - 3) door(s): 0
 - 4) other: N/A
- d. Rear; direction: E
 - 1) bays: 6
 - 2) windows: 0
 - 3) door(s): 0
 - 4) other: N/A
- 9. INTERIOR (if accessible):
 - a) Floor plan Central aisle with flanking aisles
 - b) Partition/walls 31 posts support the roof and separate the aisles
 - c) Finishes N/A
 - d) Furnishings/machinery N/A



CULTURAL RESOURCE SURVEY SECONDARY BUILDING FORM

1.	ADDRESS/LOCATION: 18345 Robinsonville Road/East side of Robinsonville Road	
2.	FUNCTION(S): historic Chicken coop current Storage	
3.	YEAR BUILT: 1929 CIRCA?: ARCHITECT/BUILDER: N/A	
4.	STYLE/FLOOR PLAN: Front gable 1-story building/Rectangular plan	
5.	INTEGRITY: original site	<u>year</u>
	list major alterations and additions with years (if known) a. N/A b.	year
6.	CURRENT CONDITION: excellent ☐ good ☐ fair ☑	роог 🗀
7.	DESCRIPTION:	
	a. Structural system Frame	
	b. Number of stories 1	
	c. Wall coverings Wood vertical boards; white vinyl siding on south elevation	
	d. Foundation Concrete slab	
	e. Roof structural system Side gable coverings Wood shingle openings 0	
8.	DESCRIPTION OF ELEVATIONS:	
	a. Facade: direction: S 1) bays: 4 2) windows: 0	
	3) door(s): 4 hinged iron grille doors inside 4 hinged wood doors	

4) other: Construction date of 1929 drawn in concrete foundation slab

CRS#	S-951.06	
------	----------	--

- b. Side: direction: E
 - 1) bays: 1
 - 2) windows: 0
 - 3) door(s): 0
 - 4) other: N/A
- c. Side: direction: W
 - 1) bays: 1
 - 2) windows: 0
 - 3) door(s): 0
 - 4) other: N/A
- d. Rear: direction: N
 - 1) bays: 4
 - 2) windows: Not visible
 - 3) door(s): Not Visible
 - 4) other: Mostly obscured by connection to S-951.07
- 9. INTERIOR (If accessible):
 - a) Floor plan Not accessible
 - b) Partition/walls Not accessible
 - c) Finishes Not accessible
 - d) Furnishings/machinery Not accessible



CULTURAL RESOURCE SURVEY SECONDARY BUILDING FORM

CRS#	S-951.07	
		_

١.	ADDRESS/LOCATION: 18345 Robinsonville Road/East side of Robinsonville Road				
2.	FUNCTION(S): historic Unknown current Storage				
3.	YEAR BUILT: 1980 CIRCA?: ARCHITECT/BUILDER: N/A				
1 .	STYLE/FLOOR PLAN: Front gable 1-story building/Rectangular plan				
5.	INTEGRITY: original site 🗵 moved 🗌				
	If moved, from where original location's CRS # year N/A				
	list major alterations and additions with years (if known) a. N/A b.				
B .	CURRENT CONDITION: excellent good fair poor				
7.	DESCRIPTION:				
	a. Structural system Frame and concrete block				
	b. Number of stories 1				
	 c. Wall coverings Concrete block on west façade; vertical wood boards and vinyl siding on south elevation; concrete block and vinyl siding on north elevation 				
	d. Foundation Concrete slab				
	e. Roof structural system Front gable coverings Standing seam steel roofing				

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: W
 - 1) bays: 1
 - 2) windows: 0
 - 3) door(s): 1 Steel door
 - 4) other: Shed roof porch with 2 wood posts

openings Exhaust vent at ridge near east end

CRS#	S-951.07	

- b. Side: direction: N
 - 1) bays: 4
 - 2) windows: 1 2-pane sliding window at left
 - 3) door(s): 1 steel door at right
 - 4) other: N/A
- c. Side: direction: S
 - 1) bays: 4
 - 2) windows: 0
 - 3) door(s): 1 Steel pedestrian door at left; 2 Large sliding wood barn doors at center; 1 New 8-panel door at right
 - 4) other: N/A
- d. Rear: direction: E
 - 1) bays: 1
 - 2) windows: 0
 - 3) door(s): 0
 - 4) other: Mostly obscured by connection to S-951.06
- 9. INTERIOR (If accessible):
 - a) Floor plan Not accessible
 - b) Partition/walls Not accessible
 - c) Finishes Not accessible
 - d) Furnishings/machinery Not accessible



CULTURAL RESOURCE SURVEY SECONDARY BUILDING FORM

CRS#	S-951.08	

	· addafine.	
1.	ADDRESS/LOCATION: 18345 Robinsonville Road/East side of Robinsonville Road	
2.	FUNCTION(S): historic Unknown current Unknown	_
3.	YEAR BUILT: 2000 CIRCA?: ARCHITECT/BUILDER: N/A	
4.	STYLE/FLOOR PLAN: Prefabricated metal Quonset hut/Rectangular plan	
5.	INTEGRITY: original site 🗵 moved 🗔	
	if moved, from where N/A original location's CRS#	<u>year</u>
	list major alterations and additions with years (if known)	year
	a. N/A	
	<u>b.</u>	
6.	CURRENT CONDITION: excellent ⊠ good ☐ fair ☐	poor 🗌
7.	DESCRIPTION:	
	a. Structural system Prefabricated metal components with barrel vault	
	b. Number of stories 1	
	c. Wall coverings Ridged steel flat panels and deeply corrugated steel sheeting	
	d. Foundation Concrete slab	
	e. Roof structural system Barrel vault coverings Corrugated metal openings 0	

B. DESCRIPTION OF ELEVATIONS:

- a. Façade: direction: W
 - 1) bays: 1
 - 2) windows: 0
 - 3) door(s): 2 Large sliding metal doors with overhead track
 - 4) other: N/A

CR\$ #	S-951.08
--------	----------

- b. Side: direction: N
 - 1) bays: 2
 - 2) windows: 0
 - 3) door(s): 0
 - 4) other: N/A
- c. Side: direction: S
 - 1) bays: 2
 - 2) windows: 0
 - 3) door(s): 0
 - 4) other: N/A
- d. Rear: direction: E
 - 1) bays: 1
 - 2) windows: 0
 - 3) door(s): 1 Steel pedestrian door at left
 - 4) other: N/A
- 9. INTERIOR (if accessible):
 - a) Floor plan Not accessible
 - b) Partition/walls Not accessible
 - c) Finishes Not accessible
 - d) Furnishings/machinery Not accessible



CULTURAL RESOURCE SURVEY SECONDARY BUILDING FORM

CRS#	S-951.09	

1.	ADDRESS/LOCATION: 18345 Robinsonville Road/East side of Robinsonville Road			
2.	FUNCTION(S): historic Storage shed current Storage shed			
3.	YEAR BUILT: 2000 CIRCA?: X ARCHITECT/BUILDER: N/A			
4.	STYLE/FLOOR PLAN: Prefabricated storage building/Rectangular plan			
5.	INTEGRITY: original site 🗵 moved 🔲			
	if moved, from where original location's CRS #	<u>year</u>		
	list major alterations and additions with years (if known) a. N/A b.	Year		
6.	CURRENT CONDITION: excellent ☑ good ☐ fair ☐	poor [
7.	DESCRIPTION:			
	a. Structural system Frame			
	b. Number of stories 1			
	c. Wall coverings Wood panels with vertical grooves			
	d. Foundation Raised on concrete blocks			
	e. Roof structural system Steep gambrel roof coverings Asphalt shingles openings 0			
8.	DESCRIPTION OF ELEVATIONS:			
	a. Facade: direction: Е 1) bays: 1 2) windows: 0			

3) door(s): 2 - Hinged wood panel doors

4) other: Projecting roof peak over entrance

CRS# S	-951.09
--------	---------

- b. Side: direction: N
 - 1) bays: 2
 - 2) windows: 0
 - 3) door(s): 0
 - 4) other: N/A
- c. Side: direction: S
 - 1) bays: 2
 - 2) windows: 0
 - 3) door(s): 0
 - 4) other: N/A
- d. Rear: direction: W
 - 1) bays: 1
 - 2) windows: Not visible
 - 3) door(s): Not visible
 - 4) other: N/A
- 9. INTERIOR (if accessible):
 - a) Floor plan Not accessible
 - b) Partition/walls Not accessible
 - c) Finishes Not accessible
 - d) Furnishings/machinery Not accessible



CULTURAL RESOURCE SURVEY SECONDARY BUILDING FORM

CRS#	S-951	.10	
			

					
1.	ADDRESS/LOCATION: 18345 Robinsonville Road/East side of Robinsonville Road				
2.	FUNCTION(S): historic House (unfinished) current Vacant				
3.	YEAR BUILT: 2000 CIRCA?: ARCHITECT/BUILDER: N/A				
4 .	STYLE/FLOOR PLAN: Side gable 1-story house/Rectangular plan				
5.	INTEGRITY: original site 🔲 moved 🗵				
	<u>If moved, from where</u> <u>original location's CRS #</u> <u>Unknown</u>	<u>year</u> ca. 2002			
	list major alterations and additions with years (if known) a. N/A	<u>year</u>			
6.	b. CURRENT CONDITION: excellent good fair	poor 🏻			
7 .	DESCRIPTION:				
	a. Structural system Frame				
	b. Number of stories 1				
	c. Wall coverings Wood panels with vertical grooves				
	d. Foundation Raised on concrete blocks				
	e. Roof structural system Side gable coverings Asphalt shingles openings 0				
8.	DESCRIPTION OF ELEVATIONS:				
	 a. Facade: direction: E 1) bays: 3 2) windows: 2 - 1/1 sash windows flanking central door 				
	3) door(s): Central door cutout only				

4) other: N/A

- b. Side: direction: N
 - 1) bays: 1
 - 2) windows: 1 1/1 sash at center of elevation
 - 3) door(s): 0
 - 4) other: N/A
- c. Side: direction: S
 - 1) bays: 1
 - 2) windows: Not visible
 - 3) door(s): 0
 - 4) other: N/A
- d. Rear: direction: W
 - 1) bays: 3
 - 2) windows: 1 1/1 sash at right
 - 3) door(s): Far left door cutout only
 - 4) other: N/A
- 9. INTERIOR (if accessible):
 - a) Floor plan Not accessible
 - b) Partition/walls Not accessible
 - c) Finishes Not accessible
 - d) Furnishings/machinery Not accessible



CULTURAL RESOURCE SURVEY SECONDARY BUILDING FORM

CRS#	S-951.11	

1.	ADDRESS/LOCATION: 18345 Robinsonville Road/East side of Robinsonville Road				
2.	FUNCTION(S): historic Storage current Storage				
3.	YEAR BUILT: 1995 CIRCA?: X ARCHITECT/BUILDER: N/A				
4.	STYLE/FLOOR PLAN: Side gable 1-story building/Rectangular plan				
5.	INTEGRITY: original site	<u>year</u>			
	list major alterations and additions with years (if known) a. N/A b.	year			
6.	CURRENT CONDITION: excellent good fair	poor 🖾			
7.	DESCRIPTION:				
	a. Structural system Frame				
	b. Number of stories 1				
	c. Wall coverings Corrugated metal sheets; vertical wood boards on south elevation				
	d. Foundation Concrete slab				
	e. Roof structural system Side gable coverings Corrugated metal roofing sheets openings Exhaust pipe at center of roof ridge				
8.	DESCRIPTION OF ELEVATIONS:				
	 a. Facade: direction: E 1) bays: 2 2) windows: Paired 2-pane sliding windows at left 				
	3) door(s): 2 - Large hinged wood doors at far right				

4) other: N/A

CRS# S	-951.11	ł
--------	---------	---

b.	1)	e: direction: N bays: 2 windows: 0		
	2)	door(s): 0		
	3)	other: N/A		
	4)	other: IV/A		
c.		e: direction: S		
	1) 2)	bays: 2 windows: 1 - 2-pane sliding window at center of elevation		
	3)	door(s): 1 - Former pedestrian door at far right filled in with vertical boards		
	4)	other: N/A		
d.	Dan	r: direction: W		
Q.	1)	bays: 3		
	2)	windows: 2 - Paired 2-pane sliding windows		
	3)	door(s): 0		
	4)	other: N/A		
INTE	RIOR	(if accessible):		
a) Fl	оог р	Ian Not accessible		
b) P	artitio	n/walls Not accessible		
c) Fi	nishe	s Not accessible		
#\ E-	املیس	nings/machinery Not accessible		
u) ri	إهرازين	III Returner Liver accession		

9.



CULTURAL RESOURCE SURVEY SECONDARY BUILDING FORM

CRS#	S-951.1	2
	•	

1.	ADDRESS/LOCATION: 18345 Robinsonville Road/East side of Robinsonville Road	
 2.	FUNCTION(S): historic Garage current Unknown	
3.	YEAR BUILT: 1995 CIRCA?: ARCHITECT/BUILDER: N/A	
4.	STYLE/FLOOR PLAN: Front gable 1-story building/Rectangular plan	
5.	INTEGRITY: original site ⊠ moved □ If moved, from where N/A Original location's CRS #	year
	list major alterations and additions with years (if known) a. N/A b.	Aest
6.	CURRENT CONDITION: excellent good fair	poor 🛚
7.	DESCRIPTION:	
	a. Structural system Frame	
	b. Number of stories 1	
	c. Wall coverings Wood clapboard siding and wood panels with vertical grooves	
	d. Foundation Raised on concrete blocks over concrete slab	
	e. Roof structural system Front gable with exposed rafter tails coverings Corrugated metal roofing sheets openings Chimney to rear of building	
8.	DESCRIPTION OF ELEVATIONS:	

- a. Facade: direction: W
 - 1) bays: 2
 - 2) windows: 0
 - 3) door(s): 1 Large metal overhead garage door at center; 1 pedestrian door with aluminum storm door at far right
 - 4) other: N/A

Y''Y # 3-851.12	CRS	#	S-951.1	2
-----------------	-----	---	---------	---

	1) 2)	bays: 4 windows: 1 - Boarded square window; 2 - 4/4 sash windows					
	3) door(s): 2 - Wood doors at far left and center						
	4)	other: N/A					
c.		e: direction: S					
	1)	bays: 4					
	2)	windows: 2 - Boarded square windows; 2 - 1/1 sash windows					
	3)	door(s): 0					
	4)	other: N/A					
d.	Re	ar: direction: E					
	1)	bays: 1					
	2)	windows: 2 - Boarded square windows; 1 - square window cutout only					
	3)	door(s): 0					
	4)	other: N/A					
INTEDIOD /if accessible):							
INTERIOR (if accessible):							
a) Floor plan Not accessible							
b) Partition/walls Not accessible							
c) Finishes Not accessible							
d) Fu	d) Furnishings/machinery Not accessible						

b. Side: direction: N

9.



CULTURAL RESOURCE SURVEY SECONDARY BUILDING FORM

CRS#	S-951.13

1.	ADDRESS/LOCATION: 18345 Robinsonville Road/East side of Robinsonville Road	
2.	FUNCTION(\$): historic Mobile home current Mobile hom	ne
3.	YEAR BUILT: 1995 CIRCA?: ARCHITECT/BUILDER: N/A	
4.	STYLE/FLOOR PLAN: Side gable 1-story building/Rectangular plan	
5.	INTEGRITY: original site moved original location's C	
	Unknown list major alterations and additions with years (if known) a. N/A b.	ca. 2000 year
6.	CURRENT CONDITION: excellent good fair	□ poor ⊠
7.	DESCRIPTION:	
	a. Structural system Frame	
	b. Number of stories 1	
	c. Wall coverings Aluminum siding, vinyl siding, and panels of pressed board	
	d. Foundation Raised on concrete blocks	
	e. Roof structural system Side gable with cross gable over entry coverings Asphalt shingle openings Exhaust pipe near ridge at north end	
8.	DESCRIPTION OF ELEVATIONS:	
	 a. Facade; direction: W 1) bays: 3 2) windows: 5 - 1/1 sash windows irregularly arranged 	
	3) door(s): 1 - Door under cross gable with metal grille storm door	
	4) other: N/A	

CRS# S-951.13

- b. Side: direction: N
 - 1) bays: 2
 - 2) windows: 2 1/1 sash windows
 - 3) door(s): 0
 - 4) other: N/A
- c. Side: direction: S
 - 1) bays: 2
 - 2) windows: 2 1/1 sash windows
 - 3) door(s): 0
 - 4) other: N/A
- d. Rear: direction: E
 - 1) bays: 3
 - 2) windows: 3 1/1 sash windows
 - 3) door(s): 1 Door with 1/1 light at right
 - 4) other: N/A
- 9. INTERIOR (if accessible):
 - a) Floor plan Not accessible
 - b) Partition/walls Not accessible
 - c) Finishes Not accessible
 - d) Furnishings/machinery Not accessible



CULTURAL RESOURCE SURVEY SECONDARY BUILDING FORM

CRS#	S-951.14	

1.	ADDRESS/LOCATION: 18345 Robinsonville Road/East side of Robinsonville Road	
2 .	FUNCTION(S): historic Barn current Vacant (collapsed)	
3.	YEAR BUILT: 1900 CIRCA?: ARCHITECT/BUILDER: N/A	
4.	STYLE/FLOOR PLAN: _Front gable 1½-story barn/Rectangular plan	
5.	INTEGRITY: original site 🗵 moved 🗌	
	If moved, from where original location's CRS #	<u>year</u>
	ilst major alterations and additions with years (if known) a. N/A b.	year
6.	CURRENT CONDITION: excellent good fair	poor 🛚
7.	DESCRIPTION:	
	a. Structural system Frame	
	b. Number of stories 1½	
	c. Wall coverings Vertical board siding	
	d. Foundation Not visible	
	e. Roof structural system Front gable (partially collapsed) coverings Wood shingle openings 0	
8.	DESCRIPTION OF ELEVATIONS:	
	a. Facade: direction: W 1) bays: 1 2) windows: 0	
	3) door(s): 0	
	4) other: N/A	

CRS #	S-951.14	ļ
-------	----------	---

- b. Side: direction: N
 - 1) bays: 2
 - 2) windows: 0
 - 3) door(s): 0
 - 4) other: N/A
- c. Side: direction: S
 - 1) bays: N/A (the east and south elevations of the barn have collapsed)
 - 2) windows: N/A
 - 3) door(s): N/A
 - 4) other: N/A
- d. Rear: direction: E
 - 1) bays: N/A (the east and south elevations of the barn have collapsed)
 - 2) windows: N/A
 - 3) door(s): N/A
 - 4) other: N/A
- INTERIOR (if accessible):
 - a) Floor plan Not accessible
 - b) Partition/walls Not accessible
 - c) Finishes Not accessible
 - d) Furnishings/machinery Not accessible

SEE SEE

DELAWARE STATE HISTORIC PRESERVATION OFFICE 15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY MAP FORM

CRS#	S-951	


1.	ADDRESS/LOCATION:	18345	Robinsony	/ille Road/East side of Robinsonville Road
2.	NOT FOR PUBLICATION		reason:	
•	LOCATION MAR-			

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN

PHOTOGRAPHIC INVENTORY

RS# S-951 Date 12/2005 Photo Roll# C-4621 Surveyor Laura C. Ricketts

escription:

2-4621:1 Garage (.12), E (rear) and N elevations, facing SW; C-4621:2 Garage (.12), W (front) and S elevations, facing NE; C-4621:3 Storage building (.11), N and W elevations, facing SE; C-4621:4 Storage building (.11), S and E elevations, facing NW; C-4621:5 House (.10), E (front) and N elevations, facing SW; C-621:6 Vehicle shelter (.05), E (rear) and N elevations, facing SW

legative location (if other than SHPO)

Skelly and Loy, Inc.

Attach contact print(s):

20-06-01-05-12



crs-13

PHOTOGRAPHIC INVENTORY

RS# S-951 Date 12/2005 Photo Roll# C-4621 Surveyor Laura C. Ricketts

Pescription:

:-4621:7 House (.10), W (rear) elevation, facing E; C-4621:8 Storage shed (.09), S and E (front) elevations, facing NW; C-4621:9 Storage shed (.09), E (front) and N elevations, facing SW; C-4621:10 Quonset hut (.08), E (rear) and N elevations, facing SW; C-4621:11 Quonset hut (.08), W (front) and S elevations, facing NE; C-621:12 Outbuilding (.07) and chicken coop (.06), N and W elevations, facing SE

Negative location (if other than SHPO)

Skelly and Loy, Inc.

Attach contact print(s):



oc # 20-06-01-05-12

CRS-13

PHOTOGRAPHIC INVENTORY

RS# S-951 Date 12/2005 Photo Roll# C-4621 Surveyor Laura C. Ricketts

Pescription:

:-4621:13 Outbuilding (.07), S elevation, facing NE; C-4621:14 Chicken coop (.06), S (front) elevation, facing W; C-4621:15 Vehicle shelter (.05), N elevation, facing SW; C-4621:16 Vehicle shelter (.05), W (front) and S elevations, facing NE; C-4621:17 Mobile home (.04), S and E (rear) elevations, facing NW; C-4621:18 Mobile ome (.04), W (front) and S elevations, facing NE

legative location (if other than SHPO)

Skelly and Loy, Inc.

Attach contact print(s):



oc # 20-06-01-05-12

CRS-13

PHOTOGRAPHIC INVENTORY

CRS # S-951 Date 12/2005 Photo Roll # C-4621 Surveyor Laura C. Ricketts

Description:

C-4621:19 Outbuildings (.03 at center), N and W elevations, facing SE; C-4621:20 Cold cellar and outhouse (.02 left and .03 right), S and E elevations, facing NW; C-4621:21 Cold cellar (.02 center), S and E (rear) elevations, facing NW; C-4621:22 Outhouse and cold cellar (.03 left and .02 right), N and W elevations, facing SE; C-4621:23 Farmhouse and summer kitchen (.01 foreground), S and E (rear) elevations, facing NW; C-4621:24 Summer kitchen (.01), N and W (front) elevations, facing SE

Negative location (if other than SHPO)

Skelly and Loy, Inc.

Attach contact print(s):



CRS-13

doc # 20-06-01-05-12

PHOTOGRAPHIC INVENTORY

C-4621/

CRS# S-951 Date 12/2005 Photo Roll# C-4622 Surveyor Laura C. Ricketts

Pescription:

C-4621:25 Farmhouse, E (rear) and N elevations, facing SW; C-4621:26 Farmhouse, W (front) and S elevations, facing NE; C04622:33 Barn (.14), N and W (front) elevations, facing SE; C-4622:34 Barn (.14), S and E (rear) elevations, facing NW; C-4622:35 Mobile home (.13), E (rear) and N elevations, facing SW; C-622:36 Mobile home (.13), W (front) and S elevations, facing NE

Negative location (if other than SHPO)

Skelly and Loy, Inc.

Attach contact print(s):



CRS-13

loc # 20-06-01-05-12

CULTURAL RESOURCE SURVEY LOCUS IDENTIFICATION FORM

DELAWARE BUREAU OF ARCHAEOLOGY AND HISTORIC PRESERVATION HALL OF RECORDS DOVER, DELAWARE 19901 (302) 678-5314




FORM CRS-2

FOR OFFICE USE ONLY

CRS # 5,751
Quad Equipment
SPO map # 18 19 11
Hundred
OCCUMENT 20-06/78/04/7

1.	NAME OF LOCUS: Parcel 46 of Tax map 3-34-11
2.	STREET LOCATION: FREE COLOR OF RE 277 - OCTO OF WACTER WIRE 280
3.	OWNER'S NAME: Boarche M Joseph TEL. #
	AUDRESS: R. D. 2 BOX 53, Heure De 19958
4.	TYPE OF LOCUS: a) structure b) district c) archaeological site
	d) other
5.	SURROUNDINGS OF LOCUS: (check more than one if necessary)
	a) fallow field b) cultivated field c) woodland
	d) scattered buildings e) densely built up f) other
6.	THREATS TO LOCUS: (check more than one if necessary)
	a) none known / b) zoning c) roads d) developers
	e) deteriorationf) other
7.	REPRESENTATION ON OTHER SURVEYS:
	ilte:
	TITLE:
	TITLE:
₿.	YOUR NAME: Day LL Hostings TEL. #
	YOUR ADDRESS: Sugar County County County County
	ORGANIZATION (IF any) Asst Frenenchico Planes DATE: 9/19/79
	· · · · · · · · · · · · · · · · · · ·

USE BLACK INK ONLY



Form CR5-1 CULTURAL RESOURCE SURVEY FOR OFFICE USE ONLY STRUCTURAL DATA FORM DELAWARE BUREAU OF CRS # <u> 5-951</u> ARCHAEOLOGY AND HISTORIC Ouad: Farmount PRESERVATION SPO map # __15 : 19:11 HALL OF RECORDS Hundred 20-56/78/09/14 DOVER, DELAWARE 19901 DOCUMERT (302) 678-5314 ADDRESS OF STRUCTURE : DESCRIBE THE STRUCTURE AS COMPLETELY AS POSSIBLE: a) Overall shape T-stape& Two stences (21/2) stories wings takele start form-to addition, .

b) Structural system bays c) Foundation materials Stucks SKETCH PLAN basement d) Exterior walls materials machine heurs word stringles and descriptive staggered color(s) white butt shinglan in gave endo shaper materials gables team to search metal outs more standing cornice decentaire exposed seems nafter ender more surrelessed e) Roof none " dormers chimney location(s) contelled brick channeys at central roof f) Windows spacing regular; summetrical type modern in datable hung scittes 42 sastes in gathe ends, trim architecte trem shutters green insocian shutters - 2 panel shutters on 14 ft., g) Door spacing Facade door in most bay of front set back pant of Ttype tweeter seems to have window there now - white word
trim franch door w/ 15 lite on least such of real least to white
proches h) Porches naterials been a forch at one time - has been as Il souther, trim 1) Interior details (1) accessible) USE BLACK INK ONLY

	1 1 2 1 2 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2		San Strait Strait Strait Strait Strait Strait	<u> 1868 - Nobel Maria de la Carte de la Car</u>		The second second
		명시 상황에 있다				
3. CONDITION	good		deter	orated		
remarks:		dist Wi				
4. INTEGRITY: a)	original site		b) moved			
c)	if moved, who	en and from	where			
	list major a	lterations a	nd dates (if	∡noún`i		
• · · · · · · · · · · · · · · · · · · ·	.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	D. 7. 100		
5. DATE OF INITIAL	CONSTRUCTION					
6, ARCHITECT/BUILDE	R:					
7. RELATED OUTBUILD	INGS:	100 mm 100 m 100 mm 100 mm			raperen apartika. National Aleksana	
a) barn	b) carriag	je house	c) garage	d) priv		
was from the second of the second				h) gardens 👱		*
	j) sp:			i, water to a com-		1
					guy fores b	. d
Comaça	where we will have	THE LAND	والادر والمسائد والمساورة	وسرا معامد الثار	cancilio - process us	بتاصيصهمه
Le chia 5 th	eridi on one will bein,	mer a para	la litte ca La - hou ce	nciete bec	<u> </u>	* 4
الهاج في المريدة ف	norchita a	مسل کی اس	Ohming to the	وبديد بع حامري	board - La	94 G. F. (1)
8 BRIEFLY DISCUSS ASSOCIATIONS WIT	THE ORIGINAL	AND SUBSEQUI	ENT USES OF T	HE STRUCTURE.	NOTE ANY	
Mulkhon,	n nisionic Et	Chingle Day	alvee Licos	my forces	boans counce	
	The state of	مرحاطیات اور عمر میرود	ment, pe	mon of the		
Person	composition	در خاند سناده در خاند سناده	معہ مدرون محا کامالیہ	By Chine		
S. O. #	and add the	ب المصمود مرة . بو المصمود المراث	wall - comme	s IEU mala	may anterior	nate
8 0 0 10 6 0 0	ماسدده در	the motal	gates non	Dy lear to	m ench sid	
- 八田 かいかいかい 出行学をおす 手続き 第二十十二十二十二十二十二十二十二十二十二十二十二十二十二十二十二十二十二十二			" ~ ~ ~ 6 € \		wheat beade	
9. Primary Refere		a location o	f reference)			
⑤ 2√− δ. ,						
10. Surveyor: 🔐	عحدا دبال	2.17.4		ite of Parmi	ๆ(๗ฅ	
	g . T. sp. 25 g 23 kg (25 a 25 a 25 g 26 kg (25 g 27 a 26 a	USE BLACK I	New York M			
1864 - 384 - 1861 - 47 O'THREET IN 1974 -	<u> </u>	COR. PLACE I				696 B. B

PHOTOGRAPHIC INVENTORY

BUREAU OF ARCHAEOLOGY AND HISTORIC PRESERVATION Document 20-06/79/01/11

			,				
CRS Number	<u>5-951</u>	Date _	9179	Contact	Sheet #	† C-808 (.04	<u>A+.</u> 04B
Description		U	_		•	showe;	<u> </u>
	T- sha	OPD IN AL	Mole Stro	a lean.	<u>+6</u>		
Location (if							
Attach conta							
						f r r	
	Z BAT BE			6			

doc # 20-01-00-05-02

DELAWARE STATE HISTORIC PRESERVATION OFFICE 15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY SURVEY UPDATE FORM

CRS#	S-7911	
------	--------	--

1.	HISTORIC NAME/FUNCTION: Holland Cemetery/Cemetery						
•							
2.	ADDRESS/LOCATION: W of Cedar Grove Road/South of Plantations Road						
3.	CURRENT CONDITION: excelle	nt 🗌 good	☐ fair	☐ poor		temolished	
4.	INTEGRITY: Poor; headstones are in the cemetery, and some have for		ed/broken, or	fallen on the g	round. Tr	rees have gr	own
5.	SETTING INTEGRITY: The cemete field.	ery is located in a	wooded setti	ng on the edge	of a cultiv	/ated farm	
6. I	FORMS ADDED (give number of form	ns completed for	each):				
	#: Form:	List	property type:	q :			
	0 CRS 2 Main Building Form	<u> </u>	proporty type	<u>. </u>			
	0 CRS 3 Secondary Building	Form					
	0 CRS 4 Archaeological Site						
	0 CRS 5 Structure (Building-						
	0 CRS 6 Structure (Land Feat						
	0 CRS 7 Object Form		_				
	1 CRS 8 Landscape Elements	s Form	Cemetery				
	1 CBS 9 Man Form N/A						
	0 CRS 14 Potential District Form						
7.	SURVEYOR INFORMATION:						
	Surveyor name:	Gerald M. Kund	cio				
	Principal Investigator name:	Gerald M. Kund	c <u>îo</u>	(
	Principal Investigator signature:	Leruli	Man	ed			
	Organization: Skelly and Loy, Inc. Date: 7/2006						

USE BLACK INK ONLY CRS-10

8.	OTHER NOTES OR OBSERVATIONS:	CRS#	\$-7911
	The Holland Cemetery appears to be a family burying ground. Legible headstone: through the 1850s. Attempts to find historical information on the cemetery has procernetery is recommended as not eligible for National Register of Historic Places I not meet the requirements of NRHP Criteria Consideration D.	s date fro oven diffic	om the 1820s cult. The
9.	STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to sta	ite manag	gement plan(s):
	a) Time period(s) Pre-European Contact Paleo-Indian Archaic Woodland I Woodland II		
	 ☐ 1600-1750± Contact Period (Native American) ☐ 1630-1730± Exploration and Frontier Settlement ☐ 1730-1770± Intensified and Durable Occupation ☐ 1770-1830± Early Industrialization ☐ 1830-1880± Industrialization and Early Urbanization ☐ 1880-1940± Urbanization and Early Suburbanization ☐ 1940-1960± Suburbanization and Early Ex-urbanization 		
	b) Geographical zone		
	c) Historic period theme(s)		
	Agriculture Forestry Settlement Patterns and De Trapping/Hunting Mining/Quarrying Fishing/Oystering Manufacturing Retailing/Wholesaling Finance Professional Services Transportation and Commu Settlement Patterns and De Architecture, Engineering a Retailing/Quarrying Government Religion Education Community Organizations Occupational Organizations	mograph ind Decor	ative Arts

CULTURAL RESOURCE SURVEY LANDSCAPE ELEMENTS FORM

CRS#	S-7911	
------	--------	--

۱.	ADDRESS/LOCATION: W of Cedar Grove Road/South of Plantations Road	
2.	TYPE/FUNCTION/NAME: Holland Cemetery	
3.	YEAR BUILT: 1820 CIRCA?: ⊠	
lis	t major alterations and additions with years (If known)	
a.	Headstones damaged/destroyed, fallen down; trees have grown in cemetery Unknow	۸n
<u>b.</u>		
4.	DESIGNER: original Unknown	
	alteration(s) N/A	
5.	STYLE: No style	
6.	CURRENT CONDITION: excellent good fair poor	
7.	RELATIONSHIP TO OTHER PROPERTIES: None known	
В.	DESCRIPTION:	
	a) Scenic views/vistas: The cemetery is situated in a wooded lot on the edge of a cultivated farm field. There are no scenic views or vistas.	
	b) Circulation system: There is no circulation system.	
	c) Spatial subdivisions: There are no spatial subdivisions.	
	d) Paving material(s): There are no paved areas within the cemetery.	
	e) Utilities: N/A	
	f) Water elements: N/A	
	g) Vegetation: The abandoned cemetery has trees and brush growing within it.	
	h) Other: The cemetery features 11 marked graves and may include as many as 36 burials. The	
	boundary was delineated through archaeological probing.	

STREET HINGSHOP

DELAWARE STATE HISTORIC PRESERVATION OFFICE 15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY MAP FORM


CRS#	S-7911	

1.	ADDRESS/LOCATION:	W Of C	edar Grove	Road/South Of Plantations Road
^	NOT COD DUDI ICATION			
2.	NOT FOR PUBLICATION	Ш	reason:	
3.	LOCATION MAP:			

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



doc#20-06-01-05-09 USE BLACK INK ONLY CRS-9

INDICATE NORTH ON PLAN -BARB WIRE ROLL N125 COMFORT HOLLAND N120 CLUSTER OF UNINSCRIBED LEAH HOLLAND-BENJAMIN TO THE PROPERTY OF N115 DAVID HOLLAND-NATURAL DEPRESSION UNKNOWN DISTORBED ISAAC HOLLAND DOUBLE ROW OF UNINSCRIBED MARKERS THOMAS KELLUN N110 JOHN HOLLAND UNKNOWN DISTURBED PATIENCE HOLLAND Ë SARAH S. WAPLES ELIJAH HOLLAND N105 0 LEGEND: GRAVE LOCATION TREES EXTREMELY DENSE BRUSH COVER TREE FALL N100 E18 E105 E120

PHOTOGRAPHIC INVENTORY

CRS # S-7911 Date 9/2006 Photo Roll # C-4655 Surveyor Gerald M. Kuncio

Description:

C-4376:22 Gravestones of Sarah Waples and John Holland (upright), and those of Betsey and Isaac Holland on the ground, facing NW; C-4376:23 Gravestones of Betsey and Isaac Holland (foreground), John Holland, Sarah Waples, and Thomas Kellum, facing SE; C-4376:24 Head and footstones for David Holland, gravestone of Jean Holland, facing NW; C-4376:25 General cemetery conditions, facing SW; C-4376:26 Detail of Comfort and James Holland headstone; C-4376:27 General cemetery conditions, facing NE.

Negative location (if other than SHPO)

Skelly and Loy, Inc.

Attach contact print(s):



doc # 20-06-01-05-12

CRS-13

CULTURAL RESOURCE SURVEY LOCUS IDENTIFICATION FORM

DELAWARE BUREAU OF ARCHAEOLOGY AND HISTORIC PRESERVATION HALL OF RECORDS DOVER, DELAWARE 19901 (302) 736 - 5695




FORM CRS-3

FOR OFFICE USE ONLY

CRS #	57911
Quad	FOURMOUNT
SPO map #	18-19-11
Hundred	Lewes and Reh
DOCUMENT	20-06/78/04/7

1.	NAME OF LOCUS: Historic Cometery
2.	STREET LOCATION: Approximately two miles southwest of Five Points
3.	STREET LOCATION: Approximately two miles southwest of Five Points between Susseph County Road 285 and 277, east of Goslee creek OWNER'S NAME: TEL. #
	ADDRESS:
4.	TYPE OF LOCUS: a) structure b) district c) archaeological site
	d) other <u>cemetery</u>
5.	SURROUNDINGS OF LOCUS: (check more than one if necessary)
	a) fallow fieldb) cultivated fieldc) woodland
	d) scattered buildingse) densely built upf) other
6.	THREATS TO LOCUS: (check more than one if necessary)
	a) none known X b) zoning c) roads d) developers
	e) deterioration f) other
7.	REPRESENTATION ON OTHER SURVEYS:
	TITLE:##
	TITLE:##
	TITLE: #
8.	751 # 451-6 590
	YOUR NAME: (5 lea Mellin YOUR ADDRESS: (0) Ewing Hall Arthropology Dept., University of Demark, D. 19716 ODCANIZATION (if any) Replaced Research DATE: 11-28-89
	ORGANIZATION (if any) center for Archaeological Research DATE: 11-28-89

USE BLACK INK ONLY



	CULTURAL RESOURCE SURVEY PROPERTY IDENTIFICATION FORM						CRS # SPO Map Hundred Quad Other	Le Re Fa	S-11548 20-21-11 Lewes and Rehoboth Fairmount 3-34-12-52		
1.	HISTOR	IC NAME/FUNCTI	ON: E	enezer Me	thodist E	piscopal Chu	irch C	emetery/C	eme	etery	
2.	ADDRES	SS/LOCATION:	East side	of Cedar (Grove Ro	ad just south	of P	lantations F	Road	i	
3.	TOWN/N	IEAREST TOWN:	Lewes							vicinity?	\boxtimes
4.	MAIN TY	PE OF RESOUR	CE:	building landscape		structure district		site		objec	ot 🗌
5.	MAIN F	UNCTION OF PRO	OPERTY:	Cemete	ry						
6. 7.	Wester	T TITLE/ REASO n Parkway Project	t (Section	JRVEY (if ap n 106)	oplicable):	:				•	
	#: F	Form:			List prop	perty types:					
		CRS 2 Main Bulldi									
		CRS 3 Secondary									
		CRS 4 Archaeolog									
		CRS 5 Structure (I									
		CRS 6 Structure (I		ure) Form							
		CRS 7 Object Forn									
		CRS 8 Landscape	Elements	Form	Cemete	ry					
		CRS 9 Map Form			N/A						
	SURVEYO	CRS 14 Potential I	!		···						
	Surveyor	name:	_	Gerald M. k	vuncio						

Gerald M. Kuncio

Skelly and Loy, Inc.

Principal Investigator name:

Organization:

doc# 20-06-01-05-01

Principal Investigator signature:

CRS-1 **USE BLACK INK ONLY**

Date: 12/2006

affine.

Δ	ATHER	NOTES	ΛP	OBSERVATIONS:
9.	CHER	NUIES	UK	OBSERVATIONS:

CRS# S-11548

According to a plaque located on the site, the property once contained the Ebenezer Methodist Episcopal Church, built in 1822. A new church replaced the original in 1876. That church was demolished in 1955. There are approximately 150 headstones and footstones in the cemetery, with the earliest dating to the mid19th century and the most recent, the 1940s. The majority of the stones date to the 19th and early 20th centuries, and are inscribed with the names of residents from the area. The cemetery is recommended as not eligible for listing in the National Register of Historic Places because it does not meet Criteria Consideration D.

10. STATE HISTORIC CONT plan(s)):	EXT FRAMEWORK (check	all appropriate boxes; refer to state management
a) Time period(s)	Pre-European Co Paleo-Indian Archaic Woodland I Woodland II	ontact
		nd Frontier Settlement d Durable Occupation alization
b) Geographical zonec) Historic period theme	⊠ Coastal □ Urban (Cit	ninsula ninsula/Cypress Swamp ty of Wilmington)
	Agriculture Forestry Trapping/Hunting Mining/Quarrying Fishing/Oystering Manufacturing Retailing/Wholesaling Finance Professional Services	 □ Transportation and Communication ☑ Settlement Patterns and Demographic Changes □ Architecture, Engineering and Decorative Arts □ Government ☑ Religion □ Education □ Community Organizations □ Occupational Organizations □ Major Families, Individuals and Events

CULTURAL RESOURCE SURVEY LANDSCAPE ELEMENTS FORM

CRS# S-11548


1.	ADDRESS/LOCATION: East side of Cedar Grove Road just south of Plantations Road		
2.	TYPE/FUNCTION/NAME: Ebenezer Methodist Episcopal Church Cemetery		
3.	YEAR BUILT: 1822 CIRCA?: list major alterations and additions with years (if known) year		
	a, N/A		
	b.		
4.	DESIGNER: original <u>Unknown</u> alteration(s) <u>N/A</u>		
5.	STYLE: No style		
6.	CURRENT CONDITION: excellent 🗌 good 🗌 fair 🛛 poor 🔲		
7.	RELATIONSHIP TO OTHER PROPERTIES: Ebenezer M.E. Church		
8.	DESCRIPTION:		
	a) Scenic views/vistas: The cemetery is situated at the west end of a previously cultivated field, which surrounds it to the north, east, and south. It is bounded immediately to the west by the two-lane Cedar Grove Road and three single-family dwellings. Multi-family residential development is encroaching from the northeast.		
	b) Circulation system: There is no circulation system in the cemetery. Originally, the church building sat in its center.		
	c) Spatial subdivisions: N/A		
	-, -, -, -, -, -, -, -, -, -, -, -, -, -		
	d) Paving material(s): There are no paved areas within the cemetery.		
	e) Utilities: N/A		
	f) Water elements: N/A		
	g) Vegetation: The property is covered with grass, and two pine trees stand to the northeast.		
	h) Other: The headstones are scattered around the property, with some grouped and encircled by an iron rail with concrete supports.		


_
-
_
_
-
•
_
- 1
_
_
1
1
_
_
-
115
1
_
_
2
Year
-
4
_
-
_
-
_
,

CULTURAL RESOURCE SURVEY MAP FORM

11548	S-	#	CRS
-------	----	---	-----

1.	ADDRESS/LOCATION:	East si	ide of Ceda	r Grove Road just south of Plantations Road
2.	NOT FOR PUBLICATION		reason:	
3.	LOCATION MAP:			
	Indicate position of resor	urce in r	elation to g	eographical landmarks such as streams and crossroads.





PHOTOGRAPHIC INVENTORY

RS # S-11548 Date 12/2005 Photo Roll # C-4614 Surveyor Gerald M. Kuncio escription:
6414:15- View from the SW corner, facing NE; C-6414:16 - View from the NW corner, facing SE egative location (if other than SHPO) Skelly and Loy, Inc.

Attach contact print(s):





c# 20-06-01-05-12

crs-13

Ħ
_
1
_
•
I
_
-
_
=
-

CULTURAL RESOURCE SURVEY SURVEY UPDATE FORM

CRS#	\$-966	

	Justifier,					
1.	HISTORIC NAME/FUNCTION: H	art Farm/Sing	e Family C	Owelling		
2.	ADDRESS/LOCATION: 34139 C	edar Grove R	oad/Betwe	en Plantation	ns Road and Ne	everland Lane
3.	CURRENT CONDITION: excelle	nnt 🗌 go	od 🏻	fair 🗌	poor 🗌	demolished [
4.	INTEGRITY: There have been no the outbuildings are deteriorating,					dings. Although
5.	SETTING INTEGRITY: Originally, the two barns, and a shed. It is no lo			e agricultural	complex with o	cultivated fields,
6. i	ORMS ADDED (give number of form	•	•			
	#: Form:	L	ist propert	y types:		
	0 CRS 2 Main Building Form 3 CRS 3 Secondary Building	Farms ('arriago Br	rn Born on	d Chad	
	0 CRS 4 Archaeological Site		arriage be	arn, Barn, and	J Siled	
	0 CRS 5 Structure (Building-Like) Form					
	0 CRS 6 Structure (Land Feature) Form					
	0 CRS 7 Object Form					
	0 CRS 8 Landscape Elements	s Form				
	1 CRS 9 Map Form	١	I/A			
	0 CRS 14 Potential District Form					
7.	SURVEYOR INFORMATION:					
	Surveyor name:	Gerald M. K	(uncio			
	Principal Investigator name:	Gerald M. K	iuncio			
	Principal Investigator signature:	_ Tem		m.	2	
	Organization:	Skelly and L	.oy, Inc.		Dat	e: <u>12/2006</u>

₿.	OTHER NOTES OR OBSERVATIONS:	CRS#	S-966	
	The farmhouse of the Hart Farm dates to <i>ca.</i> 1865. The barn and carriage barn applicability in the 20 th century. The Hart Farm is recommended as eligible for National Replaces listing under Criteria A and C as a 19 th and 20 th century Sussex County Agriproperty, however, is slated for development.	gister o	f Historic	
	STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to sta an(s)):	te mana	gement	
	a) Time period(s) Pre-European Contact Paleo-Indian Archaic Woodland I Woodland II			
	 □ 1600-1750± Contact Period (Native American) □ 1630-1730± Exploration and Frontier Settlement □ 1730-1770± Intensified and Durable Occupation □ 1770-1830± Early Industrialization □ 1830-1880± Industrialization and Early Urbanization □ 1880-1940± Urbanization and Early Suburbanization □ 1940-1960± Suburbanization and Early Ex-urbanization 			
	b) Geographical zone Upper Peninsula Lower Peninsula/Cypress Swamp Coastal Urban (City of Wilmington)			
	c) Historic period theme(s)			
	Agriculture Forestry Transportation and Commu Settlement Patterns and Del Architecture, Engineering at Government Fishing/Oystering Manufacturing Patailing/Mhologaling Community Organizations	mograpi	nic Change	

Finance

Professional Services

Occupational Organizations Major Families, Individuals and Events



CULTURAL RESOURCE SURVEY SECONDARY BUILDING FORM

CRS#	S-966	
------	-------	--

1.	ADDRESS/LOCATION: 34139 Cedar Grove Road/Between Plantations Road and Neverland La	<u>iue</u>
2.	FUNCTION(S): historic Barn current Barn	
3.	YEAR BUILT: 1920 CIRCA?: ARCHITECT/BUILDER: N/A	
4.	STYLE/FLOOR PLAN: No style/Open	
5.	INTEGRITY: original site moved	
	If moved, from where N/A original location's CRS #	<u>year</u>
	list major alterations and additions with years (if known) a. N/A b.	year
6.	CURRENT CONDITION: excellent good fair	poor 🗆
7.	DESCRIPTION:	
	a. Structural system Wood frame	
	b. Number of stories 1	
	c. Wall coverings Plywood	
	d. Foundation Stone	
	e. Roof Saltbox structural system Frame coverings Corrugated metal sheeting openings 0	
8.	DESCRIPTION OF ELEVATIONS:	
	 a. Façade: direction: S 1) bays: 3 2) windows: 1 - 6-light wood casement 	
	3) door(s): 1 - Open bay; 1-small square wood access door	
	4) other:	

b.	Side:	direction: W
	1) i	oays: 3
	2) v	vindows: 4 - 1

2) windows: 4 - 1/1 metal sash and casement

3) door(s): 2

4) other: A dog kennel with chain-linked fence and concrete block extends from the south elevation

c. Side: direction: N
1) bays: 3
2) windows: 0

3) door(s): 0

4) other; N/A

d. Rear: direction: W

1) bays: 3

2) windows: Not visible

3) door(s): Not visible

4) other: Not visible

- 9. INTERIOR (if accessible):
 - a) Floor plan Open
 - b) Partition/walls Wood
 - c) Finishes N/A
 - d) Furnishings/machinery N/A



CULTURAL RESOURCE SURVEY SECONDARY BUILDING FORM

CRS#	S-966		
------	-------	--	--

1.	ADDRESS/LOCATION: 34139 Cedar Grove Road/Between Plantations Road and Neverland La	ne
2.	FUNCTION(S): historic Carriage Barn current Carriage Barn/Storage	<u> </u>
3.	YEAR BUILT: 1920 CIRCA?: ARCHITECT/BUILDER: N/A	
4.	STYLE/FLOOR PLAN: 3-bay	
5.	INTEGRITY: original site 🗵 moved 🗌	
	If moved, from where original location's CRS #	year
	Ilst major alterations and additions with years (if known) a. N/A b.	уеаг
6.	CURRENT CONDITION: excellent ☐ good ☐ fair ☒	poor 🗀
7.	DESCRIPTION:	
	a. Structural system Wood frame	
	b. Number of stories 1½	
	c. Wall coverings Plywood	
	d. Foundation Concrete piers	
	e. Roof Front gable with shed on side bays structural system Frame coverings Corrugated metal sheeting openings 0	
8.	DESCRIPTION OF ELEVATIONS:	
	a. Facade: direction: W 1) bays: 3 2) windows: 0	
	3) door(s): 1 - Open bay; 2 - Barn doors	
	4) other: N/A	

CRS# <u>S</u> -966	
--------------------	--

b.	Side: direction: S 1) bays: 2 2) windows: 0			
	3) door(s): 0			
	4) other: N/A			
G.	Side: direction: N 1) bays: 2 2) windows: 0			
	3) door(s): 0			
	4) other: N/A			
d.	Rear: direction: E 1) bays: 1 2) windows: 1 - Fixed light replacement casement 3) door(s): 0			
	4) other: N/A			
INTE	RIOR (if accessible):			
a) Fk	oor plan Open			
b) Pa	ertition/walis Wood			
c) Fi	nishes N/A			
d) Fi	d) Furnishings/machinery N/A			

9.



CULTURAL RESOURCE SURVEY SECONDARY BUILDING FORM

S-966	
	S-966

1,	ADDRESS/LOCATION: 34139 Cedar Grove Road/Between Plantations Road and Neverland La	ine
2.	FUNCTION(S): historic Shed current Shed	
3.	YEAR BUILT: 1985 CIRCA?: ARCHITECT/BUILDER: N/A	
4.	STYLE/FLOOR PLAN: No style/Open	
5.	INTEGRITY: original site 🖾 moved 🗆	
	If moved, from where N/A original location's CRS #	year
	list major alterations and additions with years (if known) a. N/A b.	year
6.	CURRENT CONDITION: excellent ☐ good ☐ fair ☒	poor 🗌
7.	DESCRIPTION:	
	a. Structural system Wood frame	
	b. Number of stories 1	
	c. Wall coverings Plywood	
	d. Foundation Not visible	
	e. Roof Saltbox structural system Frame coverings Corrugated metal sheeting openings 0	
8.	DESCRIPTION OF ELEVATIONS:	
	a. Facade: direction: E 1) bays: 2 2) windows: 0	
	3) door(s): 2 - Barn doors	

4) other: N/A


CRS#	S-966	

- b. Side: direction: S
 - 1) bays: 1
 - 2) windows: 0
 - 3) door(s): 0
 - 4) other: N/A
- c. Side; direction: N
 - 1) bays: 1
 - 2) windows: 0
 - 3) door(s): 0
 - 4) other: N/A
- d. Rear: direction: W
 - 1) bays: 2
 - 2) windows: 0
 - 3) door(s): 0
 - 4) other: N/A
- 9. INTERIOR (if accessible):
 - a) Floor plan Not accessible
 - b) Partition/walls Not accessible
 - c) Finishes Not accessible
 - d) Furnishings/machinery Not accessible


CULTURAL RESOURCE SURVEY MAP FORM

1.	ADDRESS/LOCATION:	34139	Cedar Gro	ove Road/Between Plantations Road and Neverland Lane
2.	NOT FOR PUBLICATION		reason:	
3.	LOCATION MAP:			
	Indicate position of resor	arce in r	relation to g	geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)



INDICATE NORTH ON PLAN



DELAWARE STATE HISTORIC PRESERVATION OFFICE

PHOTOGRAPHIC INVENTORY

RS # S-966 Date 12/2005 Photo Roll # C-4614 Surveyor Gerald M. Kuncio

Description:

C-4614:17 House, S and E (front) elevations, facing NW; C-4614:18 House, E (front) elevation, facing SW; C-4614:19 Barn and Carriage Barn, facing W; C-4614:20 Barn, S and W (front) elevations, facing NW; C-4614:21

Shed, facing NW

Negative location (if other than SHPO)

Skelly and Loy, Inc.

Attach contact print(s):








doc # 20-06-01-05-12

CRS-13

DELAWARE BUREAU OF ARCHISTORIC PRESERVATION HALL OF RECORDS DOVER, DELAWARE 19901 1. NAME OF LOCUS: 12		ULTURAL RESOURCE SURVEY DOUS IDENTIFICATION FORM FOR OFFICE USE ONLY
1. NAME OF LOCUS: 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1.		DELAWARE BUREAU OF ARCHAEOLOGY AND HISTORIC PRESERVATION HALL OF RECORDS DOVER, DELAWARE 19901 (302) 678-5314 CRS # CHOCK Guad Fainawat SPO Map # 2C 21-11 Hundred Log Rehobota DOCUMENT 20-06/78/04/7
STREET LOCATION: an usest inde ag Rt 253 und smith of municipal at R 3. OWNER'S NAME:	٦.	NAME OF LOCUS: 14 - 42 70 - 10 - 10 - 3-34-12
ADDRESS:		
ADDRESS:		OWNER'S NAME: 1 TEL. =
4. TYPE OF LOCUS: a) structure h) district c) archaeological site d) other 5. SUPPOUNDINGS OF LOCUS: (check more than one if necessary) a) fallow field b) cultivated field c) woodland d) scattered buildings e) densely built up f) other profunc 6. THREATS TO LOCUS: (check more than one if necessary) a) none known b) zoning c) roads d) developers e) deterioration f) other 7. REPRESENTATION ON OTHER SURVEYS: TITLE: * TITLE: * TITLE: * TITLE: * YOUR NAME: Payll: Heatings TEL. * YOUR ADDRESS: LLOGGE Create County C		
b) other 5. SUFFROUNDINGS OF LOCUS: (check more than one if necessary) a) fallow field b) cultivated field c) woodland d) scattered buildings e) densely built up f) other protects 6. THREATS TO LOCUS: (check more than one if necessary) a) none known b) zoning c) roads d) developers e) deterioration f) other 7. REPRESENTATION ON OTHER SURVEYS: TITLE:	4.	
5. SUPPOUNDINGS OF LOCUS: (check more than one if necessary) a) fallow field b) cultivated field c) woodland d) scattered buildings e) densely built up f) other		
d) scattered buildings e) densely built up f) other protuct. 6. THREATS TO LOCUS: (check more than one if necessary) a) none known b) zoning c) roads d) developers e) deterioration f) other 7. REPRESENTATION ON OTHER SURVEYS: TITLE:	5,	
d) scattered buildings e) densely built up f) other protuct. 6. THREATS TO LOCUS: (check more than one if necessary) a) none known b) zoning c) roads d) developers e) deterioration f) other 7. REPRESENTATION ON OTHER SURVEYS: TITLE:		a) fallow field b) cultivated field c) woodland
6. THREATS TO LOCUS: (check more than one if necessary) a) none known		
e) deterioration f) other 7. REPRESENTATION ON OTHER SURVEYS: TITLE: TITLE: TITLE: VOUR NAME: Payth Heatings Tel. YOUR ADDRESS: Suggest County	6.	·
e) deterioration f) other 7. REPRESENTATION ON OTHER SURVEYS: TITLE: TITLE: TITLE: VOUR NAME: Payth Heatings Tel. YOUR ADDRESS: Suggest County		a) none known 📈 b) zoning c) roads d) developers
7. REPRESENTATION ON OTHER SURVEYS: TITLE: TITLE: ** ** ** ** ** ** ** ** **		
TITLE: TITLE: 8. YOUR NAME: PALLIC Hastings TEL. + YOUR ADDRESS: Sugges County County County County	7.	
TITLE: TITLE: 8. YOUR NAME: Print Hastings TEL. * YOUR ADDRESS: Bussey County Count		TITLE:
** YOUR NAME: Prythis Hastings TEL. * YOUR ADDRESS: Bussey County County County		
8. YOUR NAME: Profit Hostings TEL. +		
YOUR ADDRESS: Sugar County County County	8.	
ORGANIZATION (if any) Asst Presonatur Planer) DATE: 1015/19		
		ORGANIZATION (if any) Asst Presonation Planer) DATE: 1015/20
Na minor de la comunicación de la c	;	
	0.74	rander et de la companya de la comp Estado de la companya de la company



CULTURAL RESOURCE SURVEY STRUCTURAL DATA FORM

DELAWARE BUREAU OF ARCHAEOLOGY AND HISTORIC PRESERVATION HALL OF RECORDS DOVER, DELAWARE 19901 (302) 678-5314



Form CRS-3

FOR OFFICE USE ONLY

CRS M عاماكيت Formaret ()uad 5P0 mac # <u>ac ar ir ...</u> Hundred DOCUMENT


1. ADDRESS OF STRUCTURE: _____ + code of the Z82 + moneth of

2. DESCRIBE THE STRUCTURE AS COMPLETELY AS POSSIBLE:

- a) Overall shape makes through his thingship stories ...lub Manage bays - Charactaple. wings There single struct learn to addition.

 at rules, single struct form to addition.

 b) Structural system in facade
- LEIGHAR c) Foundation materials buck basement



- d) [xterior walls materials much have heavy word abungles and common beautile color(s) natural calcuss
- shapes materials grades come a feet of the e) Roof none in bornel commerce cornice chimney location(s) server dele have as a constant of the public of advertigon
- f) Windows As a complete comes recent, established therma territorial Vinletter, mainte in province comprehension recently market in comprehension rule in the territorial transfer and market comprehension medical comprehension there please Therma spacing consequence type trim shutters
- g) Door spacing spacetic electric control bary mechaning princh is type place through substant electric electric protection of the rich stant electrics.
- h) Porches location(s) Simple there I been to reduction on formation many Lear for ignituding them or porch that the state materials supports t/im
- i) Interior details (if accessible)

USE BLACK INK ONLY

3.	CONDITION:	90/J <u>V</u>	deteriorated
	remarks:	the second secon	· · · · · · · · · · · · · · · · · · ·
4.	INTEGRITY: a	a) origin <mark>al site</mark>	b) moved
	(;) if moved, when and fi	rom where
	(i) list major alteration	ns and dates (if known)
5,	DATE OF INIT		
6.			
7,	RELATED OUTBO		F 7 3 1 3 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
	a) barn	💪 b) canniage house	, (c) garaged) privy
	e) shed	f) greenhouse	g) shop h) garden.
	i) iceho	ousej) springhouse	k) other
	در عرف ليمون . الأرام الأمام الأرام	Bellett (1965) - 1984 - Estable Hill March (1965) 1984 - M. J. (1965) - 1985 - 1985 - 1985	Lance day in the land the state of presenting a specific to the state of the state
н,	BRIEFLY DISCH		EQUENT USES OF THE STRUCTURE. NOTE ANY
9.	. Primary Ref	erences: (include locati	on of reference).
			4
			1
10	Surveyor	Work toward Whatterween	Date of Forme (Arabus
	en i en en en e	use etac	K INK ONLY

BUREAU OF ARCHAEOLOGY AND HISTORIC PRESERVATION Document 20-06/79/01/11


		Document 20-00	770701744	
CRS Number _	5-966	Date <u>9179</u>	Contact Sheet # C	<u>806 (01)</u>
Description	LOOP -	ga code + month sid	e of the Hedling house	
Location (if	other than	Bureau collecti	on)	
Attach conta	ct print	· · · · · · · · · · · · · · · · · · ·		
ale Marie Carlos and Assessment				



BUREAU OF ARCHAEOLOGY AND HISTORIC PRESERVATION

Document 20-06/79/01/11
CRS Number S-966 Date 10/79 Contact Sheet # C-807 (19
Descriptioneast pacade of the Hedling bouse - heavily
obscured -ly-trees
Location (if other than Bureau collection)
Attach contact print
PHOTOGRAPHIC INVENTORY
BUREAU OF ARCHAEOLOGY AND HISTORIC PRESERVATION Document 20-06/79/01/11
CRS Number 5-966 Date 10/19 Contact Sheet # C-807 (.2
Description east facuote of the Hedling house; single story
lean-to addition
Location (if other than Bureau collection)

Attach contact print



BUREAU OF ARCHAEOLOGY AND HISTORIC PRESERVATION Document 20-06/79/01/11

CRS Number <u>5-966</u>		-10 Contact Sheet # <u>c - 806 (.02)</u>
Description	behind to	re Herteing house
Location (if other than	Bureau colle	ection)
Attach contact print		
:	PHOTOGRAPHIC	INVENTORY
BURÉAU OF AR		ND HISTORIC PRESERVATION D-06/79/01/11
CRS Number 5-966	Date9/-	Contact Sheet # C-806 (.08)
Description Small	sneD (gable	- Horfo Davi lean-to on one side)
	-	ause
	-	ection)
Attach contact print		



BUREAU OF ARCHAEOLOGY AND HISTORIC PRESERVATION Document 20-06/79/01/11

CRS Number 5-966 Date 1019 Contact Sheet # C-807 (.22)
Description addition at rear of main section of the Gedling
bouse
Location (if other than Bureau collection)
Attach contact print
PHOTOGRAPHIC INVENTORY
BUREAU OF ARCHAEOLOGY AND HISTORIC PRESERVATION Document 20-06/79/01/11
CRS Number 5-966 Date 1019 Contact Sheet # (2-807 (2))
Description east facade + north side of the Hedling house;
lear-to addition at rear
Location (if other than Bureau collection)

Attach contact print



CRS# \$-8591

CULTURAL RESOURCE SURVEY SURVEY UPDATE FORM

۱.	HISTORIC NAME/FUNCTION: Isr	el United Metho	odist Church	and Cemetery			
2.	ADDRESS/LOCATION: 20230	Plantations Roa	d/Between SI	nady Road and	Mackenzie	e Way	
3.	CURRENT CONDITION: exceller	nt 🗌 good	⊠ fair	Door	_ d	emolished	
4.	INTEGRITY: The church has unde addition.	rgone alteration	s, including re	eplacement wir	ndows and	a front and	rear
5.	SETTING INTEGRITY: The original development.	al sense of set	ting is no lo	nger conveyed	d because	of encroad	hing
6. F	ORMS ADDED (give number of form			۰.			
	#: Form: 1 CRS 2 Main Building Form	Chu	property type rch	<u> </u>			
	0 CRS 3 Secondary Building F		<u> </u>				
	0 CRS 4 Archaeological Site F						
	0 CRS 5 Structure (Building-L						
	0 CRS 6 Structure (Land Feature) Form						
	0 CR\$ 7 Object Form						
	1 CRS 8 Landscape Elements		netery				
	1 CRS 9 Map Form 0 CRS 14 Potential District Fo	N/A					
7.	SURVEYOR INFORMATION:	····					
	Surveyor name:	Gerald M. Kur	cio				
	Principal Investigator name:	Gerald M. Kur	icio	,	<u> </u>		
	Principal Investigator signature:		wo sv(fx	<u>~~~</u>			
	Organization:	Skelly and Loy	, Inc.		Date:	12/2005	

crs-10

8. OTHER NOTES OR OBSERVATIONS:	CRS#	S-8591	
---------------------------------	------	--------	--

The cemetery purportedly dates to the late 1700s and may be of Native American (Nanticoke) origin. According to the current minister, the congregation was established in 1840. The current building dates to 1916, replacing an earlier building that may have burned down. The Atlas of the State of Delaware (Beers 1868) shows a church at this location, and labels it a "Mulatto Ch.," a designation that often indicates an African American-Native American connection. The oldest graves are in the front of the cemetery, while the more recent ones are at the rear (2004). The estimated number of grave stones is 250, with most of them dating to the 20th century.

A development company is constructing condominiums near the rear of the cemetery and church, but stipulations are in place to protect the gravesites.

9. STATE HISTORIC CONT plan(s)):	EXT FRAMEWORK (chec	ck all appropriate boxes; refer to state management
a) Time period(s)	Pre-European Paleo-Indian Archaic Woodland I Woodland II	Contact
	1730-1770± Intensified a 1770-1830± Early Indust 1830-1880± Industrializa 1880-1940± Urbanizatio	and Frontier Settlement and Durable Occupation
b) Geographical zone	Lower I	Peninsula Peninsula/Cypress Swamp
c) Historic period them	e(s)	
	Agriculture Forestry Trapping/Hunting Mining/Quarrying Fishing/Oystering Manufacturing Retalling/Wholesaling Finance Professional Services	Transportation and Communication Settlement Patterns and Demographic Changes Architecture, Engineering and Decorative Arts Government Religion Education Community Organizations Occupational Organizations Major Families, Individuals and Events

CULTURAL RESOURCE SURVEY MAIN BUILDING FORM

CRS#	S-8591	

۱.	ADDRESS/LOCATION: 20230 Plantations Road/Between Shady Road and Mackenzie Way	
2.	FUNCTION(S): historic Church current Church	
3.	YEAR BUILT: 1916 CIRCA?: ARCHITECT/BUILDER: N/A	
4.	STYLE OR FLOOR PLAN: Open	
5.	INTEGRITY: original site 🗵 moved 🔲	
	If moved, from where N/A other location's CRS #	<u>year</u>
	list major alterations and additions with years (if known) a. Front and rear additions b. Replacement roof and windows	<u>year</u> 1974
6.	CURRENT CONDITION: excellent good fair poor	
7.	DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leav blanks.)	e no
	a. Overall shape: Rectangle Stories: 1 Additions: 2 - front gable additions at front and rear	
	b Structural system (if known): Wood frame	
	c. Foundation: materials: Concrete and concrete block basement: full partial not visible no basement	
	d. Exterior walls (original if visible& any subsequent coverings): Vinyl siding	
	e. Roof: shape: Front gable with front and rear engaged gables materials: Asphalt shingles cornice: Exposed eaves dormers: 0 chimney: location(s): Exterior square plan brick with arched top on the west elevation	
8.	DESCRIPTION OF ELEVATIONS: a. Facade: Direction: W 1) Bays 3 2) Windows 2 fenestration Regular type 1 - Gothic with border tracery; 1 - stained glass with 1/1 metal sash trim Simple metal surrounds shutters 0	

Facade (cont'd)

Door(s) 1

location Central

type Modern steel and glass

trim Simple metal surrounds; recessed entryway

- Porch(es) Concrete entry ramp and brick steps
- b. Side: Direction: N
 - 1) Bays 5
 - Windows 4

fenestration irregular

Type Gothic with border tracery and stained glass with 1/1 metal sash

Trim Simple metal surrounds

shutters 0

3) Door(s) 0

location N/A

Type N/A

Trim N/A

- 4) Porch(es) N/A
- c. Side: Direction: S
 - 1) Bays 5
 - 2) Windows 4

fenestration irregular

type Gothic with border tracery and stained glass with 1/1 metal sash

trim Simple metal surrounds

shutters 0

Door(s) 0

location N/A

type N/A

trim N/A

- 4) Porch(es) N/A
- d. Rear: Direction: E
 - 1) Bays 3
 - 2) Windows 2

fenestration Regular type 1/1 vinyl sash trim Simple surrounds

shutters 0

3) Door(s) 1

location Left corner

type Wood with no windows

trim Simple wood board

- 4) Porch(es) Concrete steps
- INTERIOR: Not accessible
- LANDSCAPING: The church is bounded to the south by Plantations Road and on all other sides by the cemetery.
- 11. OTHER COMMENTS: A steeple with a single square base straddles the roof peak near the front of the church.

CULTURAL RESOURCE SURVEY LANDSCAPE ELEMENTS FORM

CRS#	S-8591	

۱.	ADDRESS/LOCATION: 20230 Plantations Road/Between Shady Road and Mackenzie Way
2.	TYPE/FUNCTION/NAME: Israel United Methodist Church Cemetery
3.	YEAR BUILT: 1790-2004 CIRCA?: ⊠ list major alterations and additions with years (if known) a. N/A year
4 .	DESIGNER: original Native American (Nanticoke) alteration(s) N/A
5.	STYLE: None
6.	CURRENT CONDITION: excellent good fair poor
7.	RELATIONSHIP TO OTHER PROPERTIES: Israel United Methodist Church
8.	DESCRIPTION:
	a) Scenic views/vistas: The cemetery is situated around the church. It is bounded to the west by the dual- lane Plantations Road. Residential development surrounds the other sides of the cemetery. Multi-family residential development is encroaching from the rear.
	b) Circulation system: There is a marked parking lot adjacent to the cemetery, with access to and from Plantations Road.
	c) Spatial subdivisions: N/A
	d) Paving material(s): A concrete sidewalk leads to the front entry of the church from the parking lot, through the cemetery.
	e) Utilities: N/A
	f) Water elements: N/A
	g) Vegetation: The property is covered with grass and one pine tree stands to the north.
	h) Other: The headstones are grouped mostly in rows from front (south) to back (north), with some scattered about.

THE STATE OF THE S

DELAWARE STATE HISTORIC PRESERVATION OFFICE 15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY MAP FORM

1.	ADDRESS/LOCATION: 20230 Plantations Road/Between Shady Road and Mackenzie Way
2.	NOT FOR PUBLICATION reason:
3.	LOCATION MAP:
	Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH lltown U.S.G.S. QUAD. SHEETS: LEWES AND FAIRMOUNT, DEL.

NDICATE NORTH ON PLAN
GRAVES GRAVES
PLANTATIONS ROAD

DELAWARE STATE HISTORIC PRESERVATION OFFICE

PHOTOGRAPHIC INVENTORY


CRS # S-8591 Date 12/2005 Photo Roll # C-4613 Surveyor Gerald M. Kuncio

Description:

Negative location (if other than SHPO)

Skelly and Loy, Inc.

Attach contact print(s):



doc # 20-06-01-05-12

CRS-13

DELAWARE STATE HISTORIC PRESERVATION OFFICE

PHOTOGRAPHIC INVENTORY


CRS # S-8591 Date 12/2006 Photo Roll # C-4652 Surveyor Gerald M. Kuncio

Description:

C-4652:7 Interior from the rear of the interior toward the altar and choir, facing N; 4652:8 Interior from the altar toward the rear of the church, facing S; C-4652:9 Interior detail of the window and surround, facing W; 4652:10 Interior detail of rear doors, facing S; C-4652:11 Detail of communion rail, altar, and choir, facing N; 4652:12 Interior letail from the corner of the altar, facing SE; 4652:13 Interior detail from the corner of the altar, facing SW; 4652:14 Detail of the transcription above the altar, facing N.

Negative location (if other than SHPO) Skelly and Loy, Inc.

Attach contact print(s):





doc # 20-06-01-05-12 CRS-13